
LAGOS STATE BUILDING CONTROL AGENCY

► COMPENDIUM OF CHURCHES AND MOSQUES WITHIN OJODU DISTRICT





► COMPILED BY: OJODU DISTRICT



BOUNDARY LAYOUT OF OJODU

NAMES OF OFFICERS IN THE DISTRICT

S/N	NAMES	CADRES	GRADE LEVEL
1	ENGR. ODEWOLE BABAJIDE O.	ASST CHIEF ELECTRICAL ENGR	13
2	ENGR LESANMI AYOKUNLE O.	SENIOR CIVIL EINGINEER	10
3	AWOTAYO QUDUS O.	SENIOR CIVIL ENGINEER	10
4	ENGR. AJAYI FUNMILOLA O.	CIVIL ENGINEER 1	10
5	BAKINSON ADETUNJI O.	CIVIL ENGINEER 1	10
6	GIDADO ABDULRAZAQ O.	MECHANNICAL ENGR 1	10
7	RUFAI OLAWALE	BUILDING OFFICER 1	10
8	Sanni Babatunde	CIVIL ENGINEER 1	10

INTRODUCTION

Ojodu District shares boundary with Ifako – Ijaiye district, Ikeja district, and Ogun State.

For this exercise:

Total number of churches captured is 53

Total number of mosques captured is 7

Total number of approved worship center is 3

Total number of converted worship center is 7

Total number of mixed-use worship center 7

Total number of unapproved worship center is 57

HOLY FIRE OVERFLOW MINISTRIES INTL,

ABIODUN JAGUN STREET, OJODU

- ▶No. of floors: 2
- ▶Status: In –Use ; No sign of distress
- Approval status: Not approved
- ▶ Converted







GOSPEL BAPTIST CHURCH

PLOT 19, OLOLADE KADIRI CLOSE, OGBA, OJODU

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





THE STONE CHURCH

OGUNNUSI ROAD, OGBA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ► Mixed use





THE REDEEMED CHRISTIAN CHURCH OF GOD (LORD'S HOUSE)

OGUNNUSI ROAD, OGBA`

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ► Mixed Use





THE REDEEMED CHRISTIAN CHURCH OF GOD

OLADOYINBO STREET, OGBA

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: DCB/DO/035/OJD
- ► Mixed Use





CHERUBIM & SERAPHIM CHURCH INT'L OKE- IGBALA

18, OLADOYINBO STREET, OGBA, LAGOS

- ►No. of floors: 1 (Bungalow)
- Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





JOINT HEIRS OF SALVATION CHURCH

23, OLADOYINBO STREET, AGUDA, OGBA, LAGOS

- ▶No. of floors: 1
- ▶Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





THE REDEEMED CHRISTIAN CHURCH OF GOD

15 MOBOLAJI STREET, OGBA, LAGOS

- ▶No. of floors: 1
- ▶Status: In Use; No sign of distress
- ▶Approval status: Not approved
- ▶Purpose built





CHRIST APOSTOLIC CHURCH

2, KOKUMO STREET, AGUDA, OGBA, LAGOS

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶ Converted





THE REDEEMED CHRISTIAN
CHURCH OF GOD
(TRANSFIGURATION
CHAPEL)

OKUNOWO LANE, JAFA'S COMPOUND, OGBA

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶ Converted






ONAOPEPO CENTRAL MOSQUE

ADU STREET, OGBA, LAGOS

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





RADIANT ARMY DELIVERANCE MINISTRY,

CALVARY CLOSE, OGBA, LAGOS

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶ Converted





CELESTIAL CHURCH OF CHRIST

CALVARY CLOSE, OGBA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distresss
- ► Approval status: Not approved
- ▶Purpose built





CHRISTHOUSE

IYE STREET, OFF KUPOLATI STREET, OGBA, LAGOS

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





CHRIST FAITH TERBANACLE INT'L CHURCH

ADEDOYIN STREET, OGBA, LAGOS

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





MOVEMENT OF HOLY SPIRIT

MINISTRY, MUYIBI STREET, OGBA, LAGOS

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





GOFAMINT

AYO ALABI STREET, OGBA, LAGOS

- ▶No. of floors: 2
- ▶Status: In Use; Sign of distress
- ► Approval status: Not approved
- ► Mixed






THE REDEEMED CHRISTIAN CHURCH OF GOD

32 AYO ALABI STRT, OKE IRA, OGBA

- ▶No. of floors: 2
- ►Status: In Use; Signs of distress
- Approval status: Not approved
- ▶ Converted





THE REDEEMED CHRISTIAN
CHURCH OF GOD
(BETHEL SANCTUARY)

OLANIPEKUN STREET, OKE IRA, OGBA

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶ Converted





GOD OF WONDERS INTL. MINISTRY

2B OLANIPEKUN, OKE IRA, OGBA, LAGOS

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶converted





CHRIST EMBASSY

OLANIPEKUN STREET, OKE IRA, OGBA

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶ Converted





FAVOUR CITY CHURCH

OLANIPEKUN, OKE IRA, OGBA, LAGOS

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶ Converted





CHERUBIM & SERAPHIM CHURCH

AYO ALABI STREET, OKE IRA OGBA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





THE REDEEMED CHRISTIAN CHURCH OF GOD

AYO ALABI, OKE-IRA, OGBA LAGOS.

- ►No. of floors: 1 (bungalow)
- ►Status: In- Use ; not distress
- ► Approval status: Not approved
- ▶Purpose built





ROYAL LIFE BAPTIST CHURCH

AYO ALABI STREET, OKE-IRA, OGBA, LAGOS

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built






CHRIST EMBASSY

ALONG OMOFADE CRESC. OMOLE PHASE 1, OJODU

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built






FOURSQUARE CHURCH

ALONG TITILAYO ADEDOYIN, OMOLE PHASE 1

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





ST JUDES ANGLICAN

ADEMOLA AJASA, OMOLE PHASE 1

- ▶No. of floors: 3
- ▶Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





OMOLE ESTATE MOSQUE

ADEYEMO AKAPO, OMOLE PHASE 1

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





CATHOLIC CHURCH OF THE HOLY SPIRIT

CORNERPIECE, AGORO AND ADEYEMO AKAPO, OMOLE PHASE1

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: DCB/DO/079/OJD
- ▶Purpose built





CHRIST APOSTOLIC CHURCH

ALONG AGORO STR. OMOLE PHASE 1

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





ANSARUDEEN MOSQUE,

ALONG OGUNNUSI, BY AHLAJI BAKARE, OJODU

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





APOSTOLIC CHURCH OF NIGERIA

ALONG OREMETA STREET, OFF OBA OGUNNUSI ROAD OJODU

- ▶No. of floors: 3
- Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶ Mixed use





REDEMMED CHRISTIAN CHURCH OF GOD

OREMETA STR. OFF OGUNNUSI RD.

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





THE TRUTH CHURCH

ALONG OREMETA STR. OJODU

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





THY KINGDOM COME

ALONG AINA STR. OJODU

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





MOSQUE, BAYTU NUUR,

ALONG AINA, OJODU

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





MOALANA SHEIK IBRAHIM AL-KAOLA CENTRAL MOSQUE

ALONG MORGAN STREET OJODU

- ▶No. of floors: 1`
- Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built






CHAPEL OF UNCOMMON GRACE

ALONG LJ DOSUNMU STREET CBD IKEJA

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶ Mixed use





CHERUBIM & SERAPHIM

ALONG BAALE STR. OFF ADEBOWALE, OJODU

- No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





FOURSQUARE CHURCH

CORNERPIECE ADEBOWALE & DIPO ABE, OJODU

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





MOUNTAIN OF FIRE

BAALE STR. OFF ADEBOWALE, OJODU

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built






REDEEMED CHRISTIAN CHURCH OF GOD

ALONG DIPO ABE, OJODU

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





CHRIST APOSTOLIC CHURCH GBADAMOSI STR. OJODU

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





CHURCH OF JESUS CHRIST OF THE LATTER DAY SAINTS,

ALONG ODOZIE, OJODU

- ▶No. of floors: 2
- ▶Status: In Use; No sign of distress
- ► Approval status: DCB/DO/PROV/074/OJD
- ▶Purpose built





AGIDINGBI CENTRAL MOSQUE

ALONG ACME CRESCENT, IKEJA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built






REDEEMED CHRISTIAN CHURCH OF GOD CITY OF GOD

AROMIRE ROAD, OJODU

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





CELESTIAL CHURCH OF CHRIST

OBAFEMI AWOLOWO ROAD, IKEJA

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





GRACEVILLE CHAPEL

OBAFEMI AWOLOWO ROAD, IKEJA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ► Approval status: Not approved
- ▶Purpose built





GRACE FAMILY INT'L CHURCH

JOBIFELE WAY, CBD, ALAUSA

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





REDEEMED CHRISTIAN CHURCH OF GOD LAGOS STATE HQ DAVID ASSEMBLY

JOBIFELE STREET, CBD

- No. of floors: 4
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





REDEEMED CHRISTIAN CHURCH OF GOD

CIPM ROAD. ALAUSA

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





LAGOS STATE SECRETARIAT MOSQUE

CIPM ROAD, ALAUSA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





CHAPEL OF CHRIST THE LIGHT

CIPM ROAD, ALAUSA

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





THE VICTORIOUS ARMY MINISTRY INTERNATIONAL

ACME CRESCENT OF ACME ROAD

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- ▶Approval status: Not approved
- ▶Purpose built





REDEEMED CHRISTIAN CHURCH OF GOD DOMINION SANCTUARY

ACME ROAD

- ▶No. of floors: 3
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





HOUSEHOLD OF DAVID

ALONG SURULERE INDUSTRIAL AVENUE

- ▶No. of floors: 1
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





THE SCENT OF CHRIST CHURCH

CORNER PIECE MOLADE OKOYA, THOMAS JUNCTION ADENIYI JONES

- ▶No. of floors: 2
- ►Status: In Use; No sign of distress
- Approval status: Not approved
- ▶Purpose built





OLUWOLE CENTRAL MOSQUE

OLUWOLE HOUSIING ESTATE, WEMPCO, OGBA.

- No. of floors: 2
- Status: In use; No sign of distress
- Approval status: Not approved
- ▶ Purpose built



