




# **COMPENDIUM OF PLACES OF WORSHIP WITHIN ONIGBONGBO DISTRICT**

**SEPTEMBER 2022**



# COMPILED BY:


- Odofin S.A. (SD Onigbongbo)
  - Olusegun O. O.
  - Osilama O. E.
  - Bukoye O. R.
  - Sadullah M. M.
  - Afolabi M. O.
- Building Inspectors
- 

# Overview

- This is a list of Places of worship (Churches and Mosques) within Onigbongbo district.
- The district consists of 4 zones namely: Onigbongbo-Maryland, Government Residential Area (GRA), Opebi and Oregun.
- Having visited all four (4) zones to capture the video recordings for proper and full coverage of these places of worship with the aid of a drone, the Onigbongbo LCDA is termed a "Restricted No Flight Zone" on the radar due to its proximity to Military bases and both local and International airports.

## Overview cont'd

- However, out of the four zones in the district, Oregon was the only area being a non-restricted flight zone where some coverage of the churches was taken with the aid of the drone.



# Dominion City Parish

## Location:

75, Kudirat Abiola Way,  
Opposite Conoil, Oregun, Ikeja.

## Description:


A ±6m height hall (1 floor), in use  
as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site

# Celestial Church of Christ Olusosun Parish

## Location:

1A, Kudirat Abiola Way, Oregon, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site

# The Citadel Global Community Church (The Latter Rain Assembly)

## Location:

98, Kudirat Abiola Way, Oregun,  
Ikeja.

## Description:


A 6 floor structure and multi-level  
car park, in use as a place of  
worship and multi-purpose hall.

## Observation:

- ❑ No defects detected on the  
structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site

# Christ Embassy Head Quarters Church

## Location:

8, Billings Way, Oregon, Ikeja.

## Description:

A multi-floor ( $\pm 9\text{m}$  height hall), in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site



# Highland Church (Headquarters)

## Location:

94, Kudirat Abiola Way, Oregun,  
Ikeja.

## Description:

A multi-floor structure, in use as  
a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site

# Daystar Christian Centre

## Location:

71, Kudirat Abiola Way,  
Oregon, Ikeja.

## Description:

A multi-structure property in  
use as a place of worship.

## Observation:

- No defects detected on the  
structure by visual  
observation.



Video coverage of the subject site with the aid of a drone



Photograph showing the Subject Site

# GloryPlus International

## Location:

18, Kudirat Abiola Way, Opebi, Ikeja.

## Description:

A  $\pm 6\text{m}$  height warehouse (1 floor), in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photograph showing the Subject Site

# Christ Embassy Church

## Location:

Adjacent No 8, Billings Way,  
Oregun, Ikeja.

## Description:

A  $\pm 6\text{m}$  height warehouse (1 floor),  
in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Video coverage of the subject site with the aid of a drone



Photographs showing the Subject Site

# Archbishop Vining Memorial Church Cathedral

## Location:


9, Oba Akinjobi Way, GRA, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Redeemed Christian Church of God (Rose of Sharon)

## Location:

48B, Adekunle Fajuyi Way, GRA,  
Ikeja.

## Description:

A three floor structure, in use as  
a place of worship and  
multipurpose hall.

## Observation:

- No defects detected on the  
structure by visual  
observation.



Photographs showing the Subject Site

# Universal Church of the Kingdom of God

## Location:


13B Opebi Road, Opebi, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# The Church of Jesus Christ of Latter Day Saints

## Location:


5, Gbemi Oluwa Close, Opebi, Ikeja.

## Description:

A Bungalow, in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site



# Bola Memorial Anglican Church

## Location:

Along Mobolaji Bank Anthony Way, Ikeja.

## Description:

A two floor structure, in use as a place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# The Apostolic Church (Oregon District Centre)

## Location:


Plot 217, Kudirat Abiola Way,  
Oregon, Ikeja.

## Description:

A 2 floor structure, in use as a  
place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Household of God (Pentecostal Church)

## Location:

Household of God Street, Off Billings Way, Oregon, Ikeja.

## Description:

A multi-structure property in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Grace Assembly

## Location:

Along Kudirat Abiola Way,  
Oregon, Ikeja.

## Description:

A two floor structure in use as a  
place of worship.

## Observation:

- No defects detected on the  
structure by visual  
observation.



Photographs showing the Subject Site

# St. Francis Catholic Church

## Location:

1, Oremeji Street, Off Kudirat  
Abiola Way, Oregon, Ikeja.

## Description:

A three floor structure in use as a  
place of worship.

## Observation:

- No defects detected on the structure by visual observation.



# Anglican Church of the Ascension

## Location:

Along Omodara Street, Off Opebi Road, Opebi, Ikeja.

## Description:

A four floor structure in use as a place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# The Methodist Church

## Location:

2, Methodist Church Street, Off Ajanaku Street, Opebi, Ikeja.

## Description:

A three floors structure in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Christ Apostolic Church

## Location:

2, Methodist Church Street, Off Ajanaku Street, Opebi, Ikeja.

## Description:

A Bungalow, in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site



# Catholic Church of the Presentation

## Location:



21, Oba Akinjobi Way, GRA, Ikeja.

## Description:

A Bungalow structure, in use as a place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Redeemed Christian Church of God (Salvation Centre)

## Location:

10, Oba Akinjobi Way, GRA,  
Ikeja.

## Description:

A Bungalow structure, in use as  
a place of worship.

## Observation:

- No defects detected on the  
structure by visual  
observation.



Photographs showing the Subject Site

# New Nations Baptist Church

## Location:



1A, Aderibigbe Shitta Street,  
Ikeja.

## Description:

A bungalow, in use as a place  
of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Redeemed Christian Church of God (Sunrise Assembly)

## Location:


9, Salvation Road, Opebi, Ikeja.

## Description:

A Three floor structure with the first floor left wing in use as a place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Ebenezer African Church Parish

## Location:



22, Irewole Avenue, Onigbagbo, Opebi, Ikeja.

## Description:

A Bungalow, in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Omega Fire Ministry

## Location:



2/3, Kudirat Abiola Way, Opebi, Ikeja.

## Description:

A two floor structure in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Redeemed Christian Church of God (Resurrection Centre)

## Location:

58, Adekunle Fajuyi Way, GRA,  
Ikeja.

## Description:

A two floor structure in use as a  
place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# The Leadership Church

## Location:

49, Kudirat Abiola Way, Oregon, Ikeja.

## Description:

A three floor structure, in use as a place of worship.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site



# Redeemed Christian Church of God (Praise Arena)

## Location:

Along Sadatu Street, Off Kudirat Abiola Way, Oregun, Ikeja.

## Description:

A Bungalow, in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Grace and Glory Chapel

## Location:

1, Tunde Osilaja Street, Off Opebi Road, Opebi, Ikeja.

## Description:

A Bungalow, in use as a place of worship and multipurpose hall.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Salvation Ministries

## Location:


12, Kudirat Abiola Way, Oregon, Ikeja.

## Description:

A three floor structure in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Redeemed Christian Church of God (Rivers of Joy Parish)

## Location:

23, Wasimi Street, Maryland,  
Ikeja.

## Description:

A bungalow, in use as a place  
of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photograph showing the Subject Site

# The Redeemed Christian Church of God (The Lifespring Parish)

## Location:

Plot 9 Block 1, Oregon Mixed Development Scheme, Etal Avenue (Etal Hotel/NNPC Filling Station) Off Kudirat Abiola Way, Oregon, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photograph showing the Subject Site

# Shamsi Adisa Thomas (SAT) Mosque

## Location:

Corner piece of Muiz Banire Street/Oba Akinjobi Way, old Secretariat, GRA, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship and multi purpose hall.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Onigbongbo Central Mosque

## Location:

Along Palace Road, Maryland, Ikeja.

## Description:

A 2 floor structure, in use as a place of worship and multipurpose hall.

## Observation:

- ❑ No defects detected on the structure by visual observation.



Photographs showing the Subject Site

# Opebi Central Mosque

## Location:

Along Irewole Street, Off Kudirat Abiola Way, Oregun, Ikeja.

## Description:

A three floor structure in use as a place of worship.

## Observation:

- No defects detected on the structure by visual observation.



Photographs showing the Subject Site



# Conclusion

- There are 36 Nos. places of worship listed above with 33 Churches and 3 Mosques.
- This is by no means the number of churches and mosques in Onigbongbo district as there are less obvious places of worship that could not be captured due to time constraint and logistical issues. However, we would continue to make it an ongoing exercise to update our records.
- Partially submitted with due respect.



# THANK YOU

