

# List of all Churches and Mosques within Eti-Osa West 2 District

Presented by: Bldr Ibrahim A.A Supervising Director, Eti-Osa West 2 District


## INTRODUCTION

• The purpose of this exercise is to compile a list of all religious centers (churches and mosques) within the district

Actions taken:

- Street by street monitoring and Identification of the religious centers by taking photographs and videos
- Physical assessment of the structures identified to check for structural defects

## AREA OF COVERAGE



#### AREA OF COVERAGE CONT'D

- Eti-Osa West 2 District spans across the right-hand side of Lekki-Epe Expressway starting from Akiogun road and ending at the canal after the Eti-Osa district office at Ikota after the second toll gate
- Notable development areas covered by the district are: Lekki Phase 1, Ikate, Elegushi, Ilasan, Jakande, Ologolo, Igbo-Efon, Alpha Beach road and Olugborogan town


# List of Officers in Eti-Osa West 2 District

- 1. Bldr Ibrahim A.A
- 2. Arc Owoiya Taofik
- 3. Engr Olojo-Kosoko Damilola
- 4. Engr Fadahunsi Adedapo
- 5. Engr Akande Dorcas
- 6. Bldr Owolowo Adetutu
- 7. Engr Salako Aderemi


(Supervising Director) (Building Inspector) (Building Inspector) (Building Inspector) (Building Inspector) (Building Inspector) (Building Inspector)

#### ANALYSIS OF DATA OBTAINED FROM THE EXERCISE


A total of 37 churches and 3 mosques were captured during the exercise



#### NUMBER OF CHURCHES ACCORDING TO DENOMINATION



#### NUMBER OF WORSHIP CENTERS ACCORDING TO NUMBER OF FLOORS



Series 1





1. SAVIOURS FAMILY ANGLICAN CHURCH AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 15





2. TESTIMONY PLACE AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 30





3. DOMINION CITY AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 10





4. THE REDEEM CHRISTIAN CHURCH OF GOD, CORNER STONE EMBASSY AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 10





5. MOUNTAIN OF FIRE MINISTRIES,AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 13





6. ANSARUDEEN SOCIETY OF NIGERIA CENTRAL MOSQUE OPPOSITE SILVER FOX, AKIOGUN ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





7. RCCG, SOLOMON'SPARISH, ALONGT.F.KUBOYE, LEKKI PHASE1.

- Type of structure: temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 15





8. CHURCH OF GOD MISSION INTERNATIONAL BY RAFIAT AYINKE, TINUBU CLOSE OFF T.F.KUBOYE, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





9. WINNERS CHAPEL ALONG T.F KUBOYE, LEKKI PHASE 1.

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 30





10. LIFE POINT CHURCH OPPOSITE PINNACLE FILLING STATION ALONG REMI OLOWUDE, LEKKI PHASE 1.

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 20





11. NEW CREATION CATHEDRAL CHURCH ALONG REMI OLOWUDE ROAD, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





12. PENTECOSTAL FELLOWSHIP OF NIGERIA (LAGOS ISLAND PROVINCE) ALONG REMI OLOWUDE ROAD,LEKKI.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





13. MOUNTAIN OF FIRE MINISTRIES ALONG AKINYEMI AVENUE, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 30





14. KINGDOM HALL JEHOVAH WITNESS ALONG AKINYEMI AVENUE BY OLABANJI OLAJIDE STREET, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





15. THE REDEEM CHRISTIAN CHURCH OF GOD, SALVATION PARISH, GLORY TERBANACLE, ZONE ALONG AKINYEMI AVENUE ELF, LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 15





- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 20





17. THE REDEEM CHRISTIAN CHURCH OF GOD CANAAN LAND PARISH, WHITESAND AVENUE LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 30





18. CCIC CHRIST CHAPEL INTERNATIONAL CHURCH, CHRIST CHAPEL STREET OFF WHITESANDS AVENUE LEKKI PHASE 1.

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 30





19. VICTORIA FELLOWSHIP CHURCH, VFC CLOSE OFF STILL WATERS ROAD, LEKKI

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 40





20. THE COVENANT TEMPLE, COVENANT WAY,LEKKI

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 40



21. CHRIST EMBASSY LOVE WORLD CHISCO BY ELEGUSHI BEACH GATE LEKKI

- Type of structure : temporary
- No of floors: 2
- Structural defects: none
- No of parking spaces: 40





22. RCCG TESTIMONY CHAPEL NEW ILASAN ROAD LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 15



#### 23. ASSEMBLIES OF GOD'S CHURCH, NEW ILASAN ROAD, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 10





24. CAC NEW ILASAN ROAD, ILASAN, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 10





25, RCCG DIVINE FAVOUR PARISH, NEW ILASAN LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 10





26. NEW ERA ANGLICAN CHURCH, ALONG HON AJAYI ALABA STREET, ILASAN, LEKKI

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 20





27. ELEVATION CHURCH ALONG RESURRECTION DRIVE, ILASAN, LEKKI

- Type of structure : permanent
- No of floors: 8
- Structural defects: none
- No of parking spaces: 50





28. RCCG RESURRECTION PARISH, JAKANDE 1<sup>ST</sup> GATE, LEKKI

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 50





29. THE ETERNAL SACRED ORDER OF THE CHERUBUIM AND SERAPHIM JAKANDE 1<sup>ST</sup> GATE MARKET ROAD

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 10



30. DEEPER LIFE BIBLE CHURCH LEKKI DISTRICT JAKANDE MARKET ROAD LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 10



31. CELESTIAL CHURCH OF CHRIST JAKANDE MARKET ROAD, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 5



32. RCCG FOUNTAIN OF POWER PARISH, AREA 12 ZONE 5 WITHIN EMMADEB PFS, OLOGOLO, LEKKI

- Type of structure : permanent
- No of floors: 3
- Structural defects: none
- No of parking spaces: 10



33. DIOCESE OF LAGOS (ANGLICAN COMMUNION) CHURCH OF REDEMPTION ALONG OLOGOLO ROAD, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 10





34. CATHOLIC CHURCH OF THE EPIPHANY, OLOGOLO ROAD, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 30



35. SAHEED BANKOLE MOSQUE AT THE CORNERPIECE OF SAHEED BANKOLE AND OLOGOLO ROAD, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: none
- No of parking spaces: 1





36. MAYEGUN CENTRAL MOSQUE, OLOGOLO, LEKKI

- Type of structure : permanent
- No of floors: 1
- Structural defects: differential settlement, dampness in walls
- No of parking spaces: 5





37. DAVID CHRISTIAN CENTER, STILL WATERS GARDENS ROAD, LEKKI PHASE 1.

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 20




38. THE REDEEM CHRISTIAN CHURCH OF GOD TRINITY CHAPEL LP92 ALONG ORCHID ROAD.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 10



39. THE DOXA CHURCH ALONG OLUGBORAGAN TOWN ROAD BY ORCHID ROAD.

- Type of structure : temporary
- No of floors: 1
- Structural defects: none
- No of parking spaces: 20



40. WESLEY CHAPEL METHODIST CHURCH ALONG OJOMU DRIVE OPPOSITE ELEGANZA.

- Type of structure : permanent
- No of floors: 2
- Structural defects: none
- No of parking spaces: 30

## CHALLENGES ENCOUNTERED

- Access was denied into some religious centers by the security personnel
- Indigenes of some volatile areas prevented LASBCA officials from properly carrying out their duties

## **RECOMMENDATIONS AND CONCLUSION**

- The owner/developers of the above detected structures should be compelled to forward their development permits to the district office for further conformity checks
- Information regarding the development permits and land use information for each area within the districts should be provided by LASPPPA to assist LASBCA in enforcing the Urban and Development laws appropriately

## THANK YOU