



# COMPEDIUM OF CHURCHES & MOSQUES (PLACES OF WORSHIP)

**WITHIN IBEJU LEKKI EAST DISTRICT, LAGOS STATE.**

**LAGOS STATE BUILDING CONTROL AGENCY**

**IBEJU LEKKI EAST DISTRICT**

September 21, 2022

# COMPEDIUM OF CHURCHES & MOSQUES (PLACES OF WORSHIP)

WITHIN IBEJU LEKKI EAST DISTRICT, LAGOS STATE.

## List of Officers

S/N	NAME	DESIGNATION
1	Ajibola Oyindamola .I	Principal Civil Engr
2	Fagbemi Adeshina Ayowale	Senior Civil Engr
3	Olowu Adegbayi .G	P.T.O II (Civil)
4.	Bamisola Ademola. M	S.T.O Arch.

## TABLE OF CONTENT

1.0	Executive Summary	Pg 2
2.0	Introduction	Pg 3
2.1	Aims of the study	Pg 4
3.0	Methodology	Pg 5
3.1	The study Area	Pg 6
3.2	Map of the Study Area	Pg 7
4.0	Results	Pg 8
5.0	conclusion	Pg 76

## 1.0 EXECUTIVE SUMMARY

This inventory of churches and mosques within Ibeju Lekki East District was undertaken by officers of Lagos State building control Agency, Ibeju Lekki East District in September 2022.

A total number of sixty seven (67) places of worship were captured, which comprises sixty two (62) churches and five (5) mosques. One (1) number of structure was observed to be defective and unfit for usage, as shown in table below.

S/N	DESCRIPTION	NUMBER
1	NO OF ALL STRUCTURES CAPTURED	67
2	NO OF CHURCHES	62
3	NO OF MOSQUES	05
4	NO OF COMPLETED AND IN-USE	56
5	NO OF UNCOMPLETED AND IN-USE	11
6	NO OF DISTRESSED STRUCTURES	1
7	NO OF PURPOSE BUILT STRUCTURES	65
8	NO OF ONE (1) FLOOR STRUCTURES	45
9	NO OF TWO (2) FLOOR STRUCTURES	19
10	NO OF THREE (3) FLOOR STRUCTURES	03

## 2.0 INTRODUCTION

---

Churches and mosques are places of worship and spiritual up-liftment, synonymous with the two prevalent religions in Nigeria today, i.e Christianity and Islam respectively. These places of worship are also places of social gatherings where people of all kinds congregate in large and small numbers as the case may be.


Hence the need for its careful design, construction, maintenance and post-construction auditing so as to avert minor and major mishaps with resultant loss of lives and property.



## 2.1 AIMS OF THE STUDY

---

- To identify and enumerate the various churches and mosques within the coverage area of Ibeju Lekki East District.
- To provide pictorial and video evidences of the identified churches and mosques.
- To provide basic details as regards each place of worship captured, thereby producing a reliable data base for enlightenment and planning purposes.
- To highlight structural defects in the identified structures.





### 3.0 METHODOLOGY

---

The methods employed for the purpose of this study are;

#### **1. Data Collection**

This entails field work i.e moving all through the study area to where the places of worship are located.

Data was collected by means of:

- A. Pictures and videos captured with hand held camera devices.
- B. Imagery and videos captured with Drone Device.
- C. Google earth maps.

#### **2. Data Processing and Presentation.**

Collected data was sorted and arranged in presentation formats, and deductions from collected data were also done.

### 3.1 THE STUDY AREA.

---

The Study area here is Ibeju Lekki East District of Ibeju Lekki Local Government Area, Lagos State. The area of study is about 5303.72hectres with a perimeter of 45.358km.


The study area starts at Majek Bus stop after Fara Park along the Lekki Epe Express way and extends up to Igando area, the study area is bound on the left by the Atlantic Ocean, on the right by Lekki Epe Express way.

*Cardinal divisions within the district*

- \*Abijo
- \*Awoyaya
- \*Ogunfayo
- \*Lakowe
- \*Bogije



## 3.2 MAP OF THE STUDY AREA



## 4.0

## RESULTS

---

### CAPTURED PLACES OF WORSHIP



# ABIJO G.R.A CENTRAL MOSQUE

OFF LEKKI –EPE EXPRESS WAY, ABIJO G.R.A, IBEJU LEKKI



## DETAILS OF STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



## LIFTING LIFE CHURCH

*WITHIN ABIJO G.R.A, OFF LEKKI –EPE EXPRESSWAY, IBEJU LEKKI*



### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Three (3)
- Type of Structure Permanent structure
- Type of Use Mixed Use (Non -Purpose Built)

**MOSQUE ALONG ADEBA STREET,  
OFF LEKKI-EPE EXPRESSWAY, ADEBA, IBEJU LEKKI**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built
- Other Observation Grossly Inadequate Airspace (Left Side)

# OUR LADY QUEEN OF APOSTLES CATHOLIC CHURCH

ALONG ADEBA ROAD, OFF LEKKI-EPE, EXPRESSWAY, LAKOWE,  
IBEJU LEKKI.



## DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built.



**REDEEMED CHRISTIAN CHURCH OF GOD, POWERFUL HERITAGE  
ASSEMBLY AREA HEADQUATERS,**

*ADE OLOWOPOPO AVENUE, OFF OGUNYOMI CRESCENT, SCHOOL GATE,  
BUS-STOP, LAKOWE PHASE 2, IBEJU LEKKI*



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | Three (3)           |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |

## LIBERTY FAMILY CHURCH,

*ALONG ADEBA STREET, OFF LEKKI-EPE EXPRESSWAY, LAKOWE,  
IBEJULEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### DETAILS OF THE STRUCTURE

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |

## REAPERS ASSEMBLY (THE CITY OF JOY),

3 JOY OGUNBANWO STREET, OFF ADEBA STREET, LAKOWE, IBEJU LEKKI



### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



# NEW HERITAGE BAPTIST CHURCH

*LAKOWE, IBEJU LEKKI*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

## DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

## ***ASSEMBLIES OF GOD CHURCH***

***IGBOLOKO ADEBA, LAKOWE, IBEJU LEKKI***



### **DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully

***FOUR SQUARE GOSPEL CHURCH  
NO 3 LAYI ODERINDE LANE OFF SIKIRUJAGUNNA  
STREET, IGBOLOKO, ADEBA AREA, LAKOWE IBEJU LEKKI***



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected **N\A**
- Use **Place of Worship**
- Number of Floors **One (1)**
- Type of Structure **Permanent structure**
- Type of Use **Purposefully built**



## **MOUNTAIN OF FIRE AND MIRACLE MINISTRIES**

**7 OGUNYOMI CRESCENT, OFF SEYI OMOGUNWA ROUNDABOUT LAKOWE  
PHSE 2, IBEJU LEKKI**



### **DETAILS OF STRUCTURE**

- **Defects detected** N\A
- **Use** Place of Worship
- **Number of Floors** One (1)
- **Type of Structure** Permanent structure
- **Type of Use** Purposefully built

**THE RESTORATION PROPHETIC CHURCH OF ALL NATION (INC)**  
**N0.8 OGUNYOMI CRESCENT, OFF SEYI OMOGUNWA ROUNDABOUT LAKOWE**  
**PHASE 2 , IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**EVIDENCE CHRISTIAN ASSEMBLY,  
ALONG OGUNYOMI CRESCENT, OFF SEYI OMOGUNWA ROUNDABOUT  
LAKOWE PHSE 2 , IBEJU LEKKI.**



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |
| • Other Observation | Inadequate Set back |

**THE REDEEMED CHRISTIAN CHURCH OF GOD,  
IGBOLOKO ADEBA, LAKOWE, IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | Two (2)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |
| • Other Observation | Inadequate Set back |



**THE REDEEMED CHRISTIAN CHURCH OF GOD,  
ALMIGHTY AREA (AREA 25) HQ,  
ALONG SEYI OMOGUNWA STREET, LAKOWE PHASE2, IBEJU LEKKI**



**DETAILS OF STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |
| • Other Observation | Inadequate Set back |

**CHRIST WORLD OF SALVATION CHURCH,  
18 SEYI OMOGUNWA STREET, LAKOWE PHASE2, IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**THE REDEEMED CHRISTIAN CHURCH OF GOD  
APAPA FAMILY AREA 14, ZONE 5**

*TAYO MASARI STREET, LAKOWE IBEJU LEKKI*



**DETAILS OF STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

## ANGLICAN CHURCH OF THE LIVING FAITH (ANCOLIF)

*1 TAYO MASARI STREET, OFF OGUNYOMI CRESCENT, SCHOOL GATE  
BUS-STOP, LAKOWE PHASE 2, IBEJU LEKKI*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### DETAILS OF THE STRUCTURE

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |



**THE REDEEMED CHRISTIAN CHURCH OF GOD, LIVING HOPE  
PARISH,  
SEYI OMOGUNWA STREET, AJEBO JUNCTION, LAKOWE PHASE2,  
IBEJU LEKKI.**



**DETAILS OF THE STRUCTURE**

- Defects detected **N\A**
- Use **Place of Worship**
- Number of Floors **One (1)**
- Type of Structure **Permanent structure**
- Type of Use **Purposefully built**

**THE REDEEMED CHRISTIAN CHURCH OF GOD  
THE CONQUERORS COURT,  
ADEBA, LAKOWE PHASE II, IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**THE REDEEMED CHRISTIAN CHURCH OF GOD,  
ADEBA, LAKOWE PHASE II, IBEJU LEKKI**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use None Purposefully built

**THE REDEEMED CHRISTIAN CHURCH OF GOD,  
ADEBA, LAKOWE PHASE II, IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- **Defects detected** N\A
- **Use** Place of Worship
- **Number of Floors** One (1)
- **Type of Structure** Permanent structure
- **Type of Use** Purposefully built

**FOURSQUARE GOSPEL CHURCH ELEMORO**  
**ALONG ALHAJI SHAKIRU STREET, OFF LEKKI EPE EXPRESS WAY, ELEMORO,**  
**IBEJU LEKKI.**




**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |



**THE REDEEMED CHRISTIAN CHURCH OF GOD, RESTORATION  
TABERNACLE**

**OTUNLA AREA, OFF LEKKI-EPE, EXPRESSWAY, IBEJU**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N/A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**SIGNS AND WONDERS PRAYER MOUNTAIN  
WATCH TOWER AREA, ELEMORO, BOGIJE, IBEJULEKKI.**



**DETAILS OF THE STRUCTURE**

- |                     |                             |
|---------------------|-----------------------------|
| • Defects detected  | N\A                         |
| • Use               | Place of Worship            |
| • Number of Floors  | One (1)                     |
| • Type of Structure | Permanent structure         |
| • Type of Use       | Purposefully built          |
| • Other Observation | Structure not yet completed |

**LONG LIFE COVENANT ASSEMBLY  
ELEMORO, BOGIJE, IBEJU LEKKI.**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**FAMILY LIFE RENOVATION REVIVAL MINISTRY  
INTERNATIONAL  
ELEMORO, BOGIJE, IBEJU LEKKI.**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure
- Type of Use Purposefully built

# THE REDEEMED CHRISTIAN CHURCH OF GOD, FOUNTAIN OF GRACE,

*ADEBA LAKOWE, IBEJU LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

## DETAILS OF THE STRUCTURE

- Defects detected **N\A**
- Use **Place of Worship**
- Number of Floors **Two (2)**
- Type of Structure **Permanent structure**
- Type of Use **Purposefully built**



**CELESTIAL CHURCH OF CHRIST**  
**OTUNLA AREA, OFF LEKKI-EPE, EXPRESSWAY, IBEJULEKKI.**



(PLACES OF WORSHIP) | 9/21/2022

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built
- Other Observation Inadequate Airspace

CHURCHES & MOSQUES

COMPEDIUM OF



**THE REDEEMED CHRISTIAN CHURCH OF GOD,  
CITY OF ABUNDANCE PARISH.  
OTUNLA AREA, OFF LEKKI-EPE, EXPRESSWAY, IBEJULEKKI**



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |

## NEW JOY BAPTIST CHURCH

*PLOT 6-8, NEW JOY BAPTIST STREET, ADJACENT OTUNLA HEALTH CENTRE,  
OTUNLA, KAJOLA BUS STOP, IBEJULEKKI*



### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**ANGLICAN CHURCH ON THE ROCK**  
**ALONG GENERAL LIFE JEBBA STREET, OFF GBETU ROAD, OFF LEKKI-EPE**  
**EXPRESSWAY, GBETU IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**DOMINION CITY, AWOYAYA**  
*ALONG LEKKI-EPE EXPRESSWAY, OPPOSITE LIVING SPRING SCHOOL*  
*AWOYAYA, IBEJU LEKKI.*



**DETAILS OF STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure
- Type of Use Purposefully built

**ANGLICAN CHURCH**  
**ALONG AN EXISTING STREET BESIDE GREEN SPRING SCHOOL, OFF LEKKI-  
EPE EXPRESSWAY, AWOYAYA, IBEJU LEKKI**



**DETAILS OF STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Three (3)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**BROOKS CHRISTIAN WORSHIP CENTRE**  
*ALONG LEKKI- EPE EXPRESSWAY, BANKOLE, IBEJU LEKKI*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

COMPEDIUM OF



**ALATISE COMMUNITY MOSQUE**  
*ALONG ALATISE STREET, BESIDE BAALE PALACE, OFF LEKKI-EPE  
EXPRESSWAY, ALATISE, IBEJU LEKKI*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected **N\A**
- Use **Place of Worship**
- Number of Floors **One (1)**
- Type of Structure **Permanent structure**
- Type of Use **Purposefully built**

## CHRIST APOSTOLIC CHURCH (WONDERLAND)

ALONG BANKOLE STRET, GULF ROAD, LAKOWE,, IBEJU LEKKI



### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure(Wooden)
- Type of Use Temporarily built



# FOUR SQUARE GOSPEL CHURCH

ALONG ALATISE STREET, OFF LEKKI-EPE EXPRESSWAY, IBEJU LEKKI



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

## DETAILS OF STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



# THE REDEEMED CHRISTIAN CHURCH OF GOD, WORSHIP CENTRE

ALONG BAFAJ CRESCENT, OFF LEKKI-EPE EXPRESSWAY, BAFAJ IBEJULEKKI.



## DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully Built

## ***NEW JOY BAPTIST CHURCH***

***ALONG FESTUS STREET, OTUNLA, OFF LEKKI –EPE EXPRESS WAY,  
IBEJU LEKKI***



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### **DETAILS OF THE STRUCTURE**

- **Defects detected** N\A
- **Use** Place of Worship
- **Number of Floors** One (1)
- **Type of Structure** Permanent structure
- **Type of Use** Purposefully built

## ***TESMOT OJUOLAPE ELEMORO MEMORIAL MOSQUE***

***BEHINDE ELEMORO PALACE, OFF LEKKI-EPE EXPRESSWAY, ELEMORO, BOGIJE, LAKOWE, IBEJU LEKKI.***



### **DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**REDEEMED CHRISTIAN CHURCH OF GOD, GLORIOUS PLACE**  
*ALONG LEKKI-EPE EXPRESSWAY, BESIDE FIDELITY BANK, ELESEKAN,  
IBEJU LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**REDEEMED CHRISTIAN CHURCH OF GOD, WELL OF LIFE PARISH  
ALONG LEKKI-EPE EXPRESSWAY, BESIDE SPRING OF LIFE SCHOOL LAKOWE,  
IBEJU LEKKI.**



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | Two (2)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |

# REDEEMED CHRISTIAN CHURCH OF GOD, GRACE PAVILION PARISH.

*ALONG GULF ROAD, OFF LEKKI EPE EXPRESSWAY, IBEJU LEKKI*



## DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure
- Type of Use Purposefully built



**REDEEDEM CHRISTIAN CHURCH OF GOD (RCCG), BEAUTIFUL GATE.**

**ALONG, LEKKI-EPE EXPRESSWAY BEHINDE DUNNAMIS INTERNATIONAL GOSPEL CENTRE, ADEBA, LAKOWE, IBEJU LEKKI.**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure

COMPEDIUM OF

- Type of Use

Purposefully built

**REDEEDEM CHRISTIAN CHURCH OF GOD**

**GOSPEL CENTRE, ADEBA, LAKOWE, IBEJU LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

COMPEDIUM OF

**REDEEMED CHRISTIAN CHURCH OF GOD**  
*ALONG BANKOLE STREET, OFF LEKKI-EPE EXPRESSWAY, BANKOLE,*  
*IBEJU LEKKI*



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |



**CHRIST APOSTOLIC CHURCH**  
*ALONG ALATISE STREET, OFF LEKKI-EPE EXPRESSWAY,  
BESIDE LAURAT HILL SCHOOL, ALATISE IBEJU LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**REDEEMED CHRISTIAN CHURCH OF GOD (RCCG), LIBETY  
PAVILLON**

**ALONG ADEWALE ANJORIN STREET, OFF ALATISE STREET, ALATISE IBEJU  
LEKKI**



**DETAILS OF THE STRUCTURE**

- Defects detected Exposure of concrete slab gallery over a period. Hence dampness and Deterioration of the first floor gallery and columns is observed.
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

## KINGDOM ACHIEVERS CHURCH

*ALONG ABULE PARAPO STREET, BESIDE ATTWOOL SCHOOL, OFF LEKKI-EPE EXPRESSWAY, AWOYAYA, IBEJU LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**REDEEMED CHRISTIAN CHURCH OF GOD**  
*ALONG ABULE PARAPO STREET, OFF LEKKI-EPE EXPRESSWAY, AWOYAYA,*  
*IBEJU LEKKI.*



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | Two (2)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |

**REDEEMED CHRISTIAN CHURCH OF GOD**  
**ALONG NOJEEH ODUNLAMI STR, OFF LEKKI-EPE EXPRESSWAY, GBETU,**  
**IBEJU LEKKI**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

## WINNERS SATELLITE CHURCH OF GOD

ADEBA, IBEJU LEKKI



### DETAILS OF STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**REDEEMED CHRISTIAN OF GOD (RCCG), DAVID TABERNACLE ,  
ALONG LEKKI-EPE EXPRESSWAY, BESIDE DANCO PETROL FILLING STATION,  
EPUTU, IBEJU LEKKI**



**DETAILS OF STRUCTURE**

- |                     |  |
|---------------------|--|
| • Defects detected  | N\A  |
| • Use               | Place of Worship   |
| • Number of Floors  | One (1)  |
| • Type of Structure | Permanent structure                                      |
| • Type of Use       | Purposefully built<br>(Structure attached to wall fence) |

## CHARISMATICS RENEWAL MINISTRIES

*ALONG LEKKI-EPE EXPRESSWAY, BESIDE CHEERHUB DOOR, EPUTU, IBEJU  
LEKKI*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

COMPEDIUM OF

**CELESTIAL CHURCH OF CHRIST, MERCY CATHEDRAL  
ALONG GBETU STREET, OFF LEKKI-EPE EXPRESSWAY, GBETU, IBEJU-LEKKI**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**REDEEMED CHRISTIAN CHURCH OF GOD  
ALONG AN EXISITING STREET WITHIN LAKOWE COMMUNITY,  
LAKOWE,IBEJU-LEKKI**



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**ASSEMBLY HALL OF JEHOVAH WITNESS  
ALONG AN WATCH TOWER STREET, OFF LEKKI EPE EXPRESS WAY,  
ELEMORO BOGIJE, IBEJU-LEKKI.**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure
- Type of Use Purposefully built

## **REDEEMED CHRISTIAN CHURCH OF GOD, BEACHWOOD ESTATE.**

*WITHIN BEACHWOOD ESTATE, SHAPATI, ALONG LEKKI EPE EXPRESS WAY, IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### **DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Temporary structure
- Type of Use Purposefully built



**VICTORY INTERNATIONAL MINISTRIES**  
TRANSFORMER AREA, ADEBA, LAKOWE, *IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
  - Use Place of Worship
  - Number of Floors One (1)
  - Type of Structure Permanent structure
  - Type of Use None Purposefully built
- CELESTIAL CHURCH OF CHRIST (THE LORDS PLACE)**

*ALONG BABATUNDE ANJOIS STREET, OFF GULF ROAD, LEKKI EPE EXPRESS WAY, LAKOWE, IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**FOURSQUARE GOSPEL CHURCH , ABULE PARAPO**  
*ABULE PARAPO, OFF GBETU ROAD, AWOYAYA, IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Purposefully built



**CHRIST EMBASSY CHURCH, GBETU**  
*GBETU , AWOYAYA, IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors Two (2)
- Type of Structure Permanent structure
- Type of Use Non- Purposefully built (Mixed Use)

## CELESTIAL CHURCH OF CHRIST (TIWA NI JESU)

*NO 1, TIWA NI JESU STREET, OGUNFAYO ESTATE GBETU, AWOYAYA, IBEJU-LEKKI.*



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

### DETAILS OF THE STRUCTURE

- Defects detected N\A
- Use Place of Worship
- Number of Floors Three (3)
- Type of Structure Permanent structure
- Type of Use Purposefully built (Under construction)

**REDEEMED CHRISTIAN CHURCH OF GOD, ROYAL  
PRIESTHOOD ASSEMBLY.**

*ALONG, TIWA NI JESU STREET, OGUNFAYO ESTATE GBETU,  
AWOYAYA, IBEJU-LEKKI.*



**DETAILS OF THE STRUCTURE**

- |                     |                     |
|---------------------|---------------------|
| • Defects detected  | N\A                 |
| • Use               | Place of Worship    |
| • Number of Floors  | One (1)             |
| • Type of Structure | Permanent structure |
| • Type of Use       | Purposefully built  |



**REDEEMED CHRISTIAN CHURCH OF GOD, HOLY HEIGHTS.  
ADEBA, LAKOWE PHASE II, IBEJU-LEKKI.**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPILIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**HADIATU MOSQUE**  
*ADEBA, LAKOWE PHASE II, IBEJU-LEKKI.*



**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built

**CHRIST APOSTOLIC CHURCH**  
**GBETU AWOYAYA , IBEJU-LEKKI.**



(PLACES OF WORSHIP) | 9/21/2022

CHURCHES & MOSQUES

COMPEDIUM OF

**DETAILS OF THE STRUCTURE**

- Defects detected N\A
- Use Place of Worship
- Number of Floors One (1)
- Type of Structure Permanent structure
- Type of Use Purposefully built




## 5.0 CONCLUSION

---

The importance of regular audits of existing places of worship cannot be overemphasized as a stitch in time saves nine. This audit brings to light issues that need to be addressed, especially structural defects that can be corrected before the structure becomes distressed.

The fore mentioned are all in line with fulfilling LASBCA's mandate of ensuring zero building collapse.



**THANK YOU**

