



LAGOS STATE BUILDING CONTROL AGENCY



IKOYI/OBALENDE & IRU/VICTORIA ISLAND


DISTRICT

CHURCHES AND MOSQUES
COMPILATION

CONTENTS

- Google Map Showing Churches and Mosques in the Districts
- Names of Officers Covering Ikoyi/Obalende
- Names of Officers Covering Iru/ Victoria Island
- Churches in **Ikoyi/Obalende**
- Mosques in **Ikoyi/Obalende**
- Churches in **Iru/Victoria Island**
- Mosques in **Iru/Victoria Island**





Christ Embassy Ikoyi

"Excellent ace to worship in Ikoyi"

Dominion City Ikoyi

Ikoyi Baptist Church

"A place to worship God without inhibition..."

The Apostolic Church

The Agape Church

RCCG Living Spring Parish Ikoyi Lagos

Church Of The Resurrection

Children Clothing Lekki Palms ...

Gospel Pillars Church IKOYI



NAMES OF OFFICERS IN IKOYI DISTRICT

- ❖ Engr. Oluwagbenga A. Aileru **(Supervising Director)**
- ❖ Arc. Ahmed Sanni Agbolade
- ❖ Arc Onakoya Moyinoluwa Onatunde
- ❖ Engr. Alli-Oke Kehinde Temitayo
- ❖ Engr. Awotidebe Abayomi Samuel
- ❖ Adebote Samuel Funmi



NAMES OF OFFICERS IN VICTORIA ISLAND DISTRICT

- ❖ Engr. Oluwagbenga A. Aileru **(Supervising Director)**
- ❖ Engr. Folorunsho Olasunkanmi
- ❖ Davies Comfort Kofoworola
- ❖ Olawale Adeyemi Afeez



SUMMARY

CHURCHES &
MOSQUES

PURPOSE BUILT – 33

CONVERTED - 11

54

TEMPORARY – 7

MAKE SHIFT – 1

UNDER
CONSTRUCTION/RENO
VATION – 2



CHURCHES IN IKOYI/OBALENDE



THE REDEEMED CHRISTIAN CHURCH OF GOD

Living Spring Parish Awolowo, road Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED FROM RESIDENTIAL





IKOYI BAPTIST CHURCH

Lateef Jakande Avenue Off Burdilon
Road, Ikoyi Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





THE REDEEMED CHRISTIAN CHURCH OF GOD

53, Glover Road, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





14 Sep 2022 11:37:07
Lagos



CHRIST EMBASSY CHURCH

14

15, Glover Road, Mackee Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY STRUCTURE - TENT





CELESTIAL CHURCH OF CHRIST

(ITUNU OLUWA PARISH)

Dolphin Estate, Ikoyi Lagos.

16

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





CHURCH OF ASSUMPTION

Falomo, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





DEEPER LIFE BIBLE CHURCH

20

Polo Road, Off Ribadu Road, Ikoyi

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	Bungalow
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





ST. JOHN ANGLICAN CHURCH

20 Akanbi Danmole, off Ribadu, Ikoyi

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	4 (FOUR)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





EL-SHADDAI GRACE CATHEDRAL CHURCH

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO) and 4 (FOUR)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





WESLEY METHODIST CHURCH

Obalende, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	3 (THREE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





CHURCH OF NATIVITY

Parkview, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT FOR WORSHIP





FOURSQUARE GOSPEL CHURCH

98, Norman Williams Off Keffi Street,

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	Bungarlow
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY STRUCTURE





MOUNTAIN OF FIRE AND MIRACLE MINISTRY

32

(Sanctuary of Mercy)

Norman Williams Off Keffi Street, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





REDEEMED CHRISTIAN CHURCH OF GOD

Norman Williams str, off keffi street, Ikoyi

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





ST GREGORY CATHOLIC CHURCH

Toyran Street,obanlede

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT






ST. JOHN'S ANGLICAN CHURCH

Falomo, Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 BUILDINGS 1 (ONE) AND 4 (FOUR) FLOORS
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





REDEEMED CHRISTIAN CHURCH OF GOD


40

(Jesus family parish)

20, Sumbo Jibowu street, Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





FORCE OF GRACE MINISTRY

9, Alfred Rewane road, Ikoyi.

42

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT






CHRIST EMBASSY

Along Glover road, Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY TENT





REDEEMED CHRISTIAN CHURCH OF GOD


46

(Throne of God)

32, Glover road, Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY TENT






REDEEMED CHRISTIAN CHURCH OF GOD

48

(The Trinity temple)
Along Glover road.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





ELEVATION CHURCH

Alfred Rewane road, Ikoyi.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





SUMMARY

IKOYI/OBALENDE CHURCHES

PURPOSE BUILT - 14

CONVERTED - 4

22

TEMPORARY
STRUCTURES - 4

MAKE SHIFT - 0

UNDER
CONSTRUCTION/RENO
VATION - 0



MOSQUES IN IKOYI/OBALENDE



UNKNOWN MOSQUE

Along Ruston Road, Ikoyi, Lagos

54

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (FLOORS)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





IKOYI DOLPHIN CENTRAL MOSQUE

Corporate Drive Dolphin Estate, Ikoyi,

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (FLOORS)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





SYRIAL CENTRAL MOSQUE

14, Ribadu Road, Ikoyi, Lagos.

58

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (FLOORS)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





ODO MOSQUE

60

45, Odo Street, Obalende, Ikoyi Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





SUMMARY

PURPOSE BUILT - 2

CONVERTED - 2

4

TEMPORARY
STRUCTURES - 0

MAKE SHIFT - 0

UNDER
CONSTRUCTION/RENO
VATION - 0



CHURCHES IN IRU/VICTORIA ISLAND



THE REDEEMED CHRISTIAN CHURCH OF GOD

(The City of David Parish)

64

COD church road, dude Olu Estate, off Ligali Ayorinde, victoria Island

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	12 FLOORS
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





THE REDEEMED CHRISTIAN CHURCH

Along Water Corporation Oniru Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	3 (THREE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





CHRIST EMBASSY CHURCH

Oniru Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	NOT AVAILABLE
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





OVERCOMER CHURCH (Graceland)

21 Admiralty Way, Lekki Eti-osa, Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





15 Sept 2022 9:17:57 am
21 Admiralty Way
Lekki
Eti Osa
Lagos



THE REDEEMED CHRISTIAN CHURCH OF GOD

Admiralty Way, Lekki Eti-osa, Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





DEEPER LIFE BIBLE CHURCH

23, Idowu Martins Street, Eti-osa Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





THE REDEEMED CHRISTIAN CHURCH OF GOD

76

7a, Akinolugbade Street, Eti-osa, Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





ST. JOHN ANGLICAN CHURCH

78

1b, Abimbola Awniyi Close, Eti-osa, Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





15 Sept 2022 10:56:19 am
1b Abimbola Awoniyi Close
Eti Osa
Lagos



MOUNTAIN OF FIRE & MIRACLES MINISTRIES

80

Sanusi Fafunwa Street, Victoria Island, Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





REDEEMED CHRISTIAN CHURCH OF GOD

(Redemption Pavilion)

Jide Oki Street, Eti-osa, Lagos.

82

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





15 Sept 2022 12:32:17 pm
Jide Oki Street
Eti Osa
Lagos



CHURCH OF THE RESSURECTION

(Diocese of Lagos)

84

1004 Federal Housing Complex Road, Victoria Island Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 BUILDINGS 3 (THREE) FLOORS EACH
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT



BUILDING CONTROL



PERPETUAL HELP CHURCH

14b Musa Yahadua, Victoria Island, Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	3 (THREE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





FOUR SQUARE GOSPEL CHURCH

1004 Victoria Island, Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT






GLORY OF GOD CHRIST CHURCH

Eternal Cooperation, Oniru Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	4 (FOUR)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT



Water Corporation Road
Eti-Osa
Lagos
Nigeria
23 Sep 2022, 12:27:16



REDEEMED CHRISTIAN CHURCH OF GOD

25, Kofo Abayomi Street, Eti-osa Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	CONVERTED





REDEEMED CHRISTIAN CHURCH OF GOD

(Flourishing House Parish)

Ologun Agbaje, Victoria Island.

94

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	2 (TWO)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	MAKE SHIFT - RESTAURANT





REDEEMED CHRISTIAN CHURCH OF GOD

(Agape Parish)

Along Bishop Oluwole Street. Victoria island.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	4 (FOUR)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





ASSEMBLIES OF GOD CHURCH

Along Bishop Oluwole street.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	4 (FOUR)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	RENOVATION





Bishop Oluwole Street
Eti-Osa
Lagos
Nigeria
23 Sep 2022, 14:41:46



TRINITY HOUSE CHURCH

Trinity Avenue by Water Coperation Road, Oniru.


DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY STRUCTURE (TENT)





Trinity Avenue
Eti-Osa
Lagos
Nigeria

23 Sep 2022 12:32:51



Trinity Avenue
Eti-Osa
Lagos
Nigeria

23 Sep 2022, 12:34:04



MOUNTAIN OF FIRE AND MIRACLE MINISTRY



102

(Lagos Region 84)

Water Cooperation drive, Opposition Glory of God Christ Church

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





REDEEMED CHRISTIAN CHURCH OF GOD

Peace Assembly

Water cooperation drive, Victoria Island Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	3 (THREE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





Water Corporation Road
Eti-Osa
Lagos
Nigeria
23 Sep 2022, 12:16:42



Water Corporation Road
Eti-Osa
Lagos
Nigeria
23 Sep 2022, 12:17:25



THE PRAISETORIUM

8, Akiogun Road, Beside New Market,
Victoria Island

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY STRUCTURE (TENT)





REDEEMED CHRISTIAN CHURCH OF GOD

Temple of God

Lai Yussuf Crescent Victoria Island Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	TEMPORARY STRUCTURE (TENT)





DAVID BAPTIST CHURCH

110

Prince Yomi Daramola Street Victoria Island Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	5 (FIVE)
TYPE OF USE	CHRISTIAN PLACE OF WORSHIP
TYPE OF STRUCTURE	UNDER CONSTRUCTION



E BUILDING CONTROL



BC



SUMMARY

PURPOSE BUILT - 13

CONVERTED - 5

24

TEMPORARY - 3

MAKE SHIFT - 1

UNDER
CONSTRUCTION/RENO
VATION - 2



MOSQUES IN IRU/VICTORIA ISLAND



UNKNOWN MOSQUE

114

Along Bishop Oluwole Street Victoria Island Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT



Bishop Oluwole Street
Eti-Osa
Lagos
Nigeria
23 Sep 2022, 16:15:26



MURI OKUNOLA CENTRAL MOSQUE

Victoria Island, Lagos.

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





1004 CENTRAL MOSQUE

1004 Federal Housing Complex Road, Eti-osa

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	3 (THREE)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





ONIRU CENTRAL MOSQUE

16 Place Road, Iru Lagos

DEFECT DETECTED	NONE
APPROVAL STATUS	
NO. OF FLOORS	1 (ONE)
TYPE OF USE	MUSLIM PLACE OF WORSHIP
TYPE OF STRUCTURE	PURPOSELY BUILT





SUMMARY

PURPOSE BUILT - 4

CONVERTED - 0

4

TEMPORARY - 0

MAKE SHIFT - 0

UNDER
CONSTRUCTION/RENO
VATION - 0





THANK YOU

LASBGA

