



LAGOS STATE BUILDING CONTROL AGENCY (LASBCA)
HEAD QUARTERS ANNEX I & II, MUIZ BANIRE STREET,
IKEJA GRA, IKEJA, LAGOS.

www.lasbca.lagosstate.gov.ng

PLACE *of* WORSHIP

(CHURCHES AND MOSQUES)
YABA DISTRICT.

PRESENTED TO:

LAGOS STATE BUILDING CONTROL
AGENCY HEAD QUARTER OBA-AKINJOBI WAY,
IKEJA, LAGOS STATE.

COMPILED BY:

BASHUA FUNMILAYO A. - ACTO (ARCH). BLDR BALOGUN GANIYU A. - PBO
ENGR AKINOLA YOMI O. - SCE. ENGR BASHORUN OLASUPO,
ENGR ALABI TOHEEB - SME. ENGR OYEBOLA LATIFAT - STO (CIVIL).

3D LASBCA VIEW



LAGOS STATE BUILDING CONTROL AGENCY 3D DRAWING .

3D

LSBCA
PROPOSE
SIDE
VIEW



REFERENCES

Lagos State Physical Planning Permit Authority (LASPPPA)

Yaba Local Council Development Authority

www.google.com

https://en.m.wikipedia.org/wiki/Yaba,_Lagos

<https://guardian/art/yaba-british-influence-in-colonial-lagos-reloaded/>

CONTENTS

1 - INTRODUCTION

2 - AIM

3 - MAP

4 - MAP

5 - PICTORIAL & ANALYSIS

6- CONCLUSION

7 - REFERENCE



Yaba is a suburb located in Lagos Mainland, Lagos; it is also known as THE HEARTBEAT OF LAGOS. In pre-colonial Lagos, Yaba was known as OKE ODO; during the colonial period, it was known as GARDEN CITY or YABA ESTATE.

Yaba is often regarded as the heartbeat of Lagos Mainland. It is one of the most popular suburbs located in Lagos Mainland Local Government which includes Makoko community, Akoka, Sabo, Ebute Metta, Jibowu, Herbert Macaulay Way, Commercial Avenue, Alagomeji, Tejuosho amongst others.

Yaba is predominantly a Christian settlement by virtue of the Portuguese who brought Christianity by way of trading; slave trade in the 19th century. The first church was built in 1920 while Islam entered Nigeria in the 15th century.

Yaba Local Council Development Area (LCDA) was created in 1977 from the Old Lagos Mainland Local Government. For effective coverage, Lagos State Building Control Agency, tolled this line with an office for Yaba; located at 168 Herbert Macaulay

CONCLUSION

The data below gives credence to the earlier assertion that the **HEARTBEAT OF LAGOS** is indeed predominantly Christians; with respect to the number

S/N	ITEM	CHURCH	MOSQUE
1	TOTAL NO. OF CHURCHES	60	13
2	TOTAL NO. OF APPROVED	37	4
3	UNAPPROVED	20	7
4	YET TO ASCERTAIN THE APPROVAL STATUS	3	2
5	TOTAL NO. OF PURPOSE BUILT	48	7
6	TOTAL NO. OF CONVERTED	6	NIL
7	TOTAL NO. OF DISTRESSED	1	NIL
8	TOTAL NO. OF NON - DISTRESSED	59	NIL

AIM

This report sheds more light on the number of places of Worship; Churches and Mosques within **Yaba LCDA**. With a view to ascertaining their Approval status, Level of conformity and the state of the individual structure; distressed or not.



ALHAJI & ALHAJA AYINDE RAHIM. AJAGA CENTRAL MOSQUE

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE	
2 & 2 FLOORS	APPROVED	MOSQUE	NONE	
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS
NO PROVISION	GOOD	NON CONFORMING	MIXED - USE	NON DISTRESSED



 **SATELLITE MAP**
VIEW OF YABA DISTRICT.



 **YABA COLLEGE OF TECHNOLOGY
CENTRAL MOSQUE**

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE
1 FLOOR	NOT APPROVED	MOSQUE	NONE

PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS
INADEQATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED



 **SATELLITE MAP VIEW OF YABA DISTRICT.**

 **UNILAG CENTRAL MOSQUE
AKOKA YABA**

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE	
2 FLOORS	APPROVED	MOSQUE	NONE	
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED



REDEEMED CHURCH.
NO 232 HERBERT MACAULAY WAY, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
4 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



AJAYI BEMBE MOSQUE .
ALONG AJAYI BEMBE, ABULE-OJA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	MOSQUE	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



**AHMADIYA MUSLIM JUMAT
OF NIGERIA MOSQUE**
1 ELEJI STREET, ABULE IJESHA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



**HOARSE MEMORIAL
METHODIST CHURCH.**
HERBERT MACAULAY WAY, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 & 4 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



YABA BAPTIST CHURCH .
NO 19/23 COMMERCIAL AVENUE,
SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
5 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



ANIMASHAUN SM MOSQUE.
AYODELE STREET BY BORNO WAY, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	MOSQUE	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
NO PROVISION	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	





**YUSUF ENIYAN GBAGBE,
OLUWA RANTI MOSQUE.**
BALOGUN SQUARE, ABULE-OJA, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



CHRIST EMBASSY.
NO 25/27 RAYMOND STREET, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FL & 1 FL	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	CONVERTED	NON DISTRESSED	



ALL SAINST ANGLICAN CHURCH
ALONG MONTEGERY ROAD, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 & 3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



AHMADIYQ MOVEMENT MOSQUE.
NO 49 ARAROMI STREET OFF
BARIKISU IYEDE STREET, ONIKE, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



**JAMAAT ARAROMI ADUNSE
CENTRAL MOSQUE .**

14 ARAROMI STREET OFF
BARIKISU IYEDE STREET, ONIKE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	MOSQUE	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDDEMED CHURCH .

NO 9 THORBURN AVENUE, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	COMMERCIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	





REDEEMED CHURCH .
AT MURITALA MUHAMMED WAY
BY AJE STREET, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
5 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



CENTRAL MOSQUE.
BY IWAYA ROAD/ONIKE ROAD,
YABA, LAGOS.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
NO PROVISION	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



CENTRAL MOSQUE .
NO 91 OLD YABA ROAD, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
4 FLOORS	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED - USE	NON DISTRESSED	



CAC VINEYARD OF MERCY
NO 45/47 COMMERCIAL AVENUE,
SABO, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





REDEEMED CHURCH .
NO 4 KOFOWOROLA STREET, SABO, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



SABO MARKET CENTRAL MOSQUE

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	MOSQUE	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





MAKOKO CENTRAL MOSQUE.
MAKOKO ROAD YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	MOSQUE	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



VICTORY APOSTOLIC CHURCH .
NO 5/7 LANCASTER STREET BY
ALARA STREET,SABO,YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	DISTRESSED	NON CONFORMING	PURPOSE BUILT	DISTRESSED	



REDEEMED CHRISTIAN CHURCH.
AT ANDOYI STREET, ONIKE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



SAINT THOMAS ANGLICAN
YABATECH YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDDEMED CHURCH ALL SAINT CHURCH .
AT OLONODE STREET
BY PETGRAVE, ALAGOMEJI, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



EVANGELICAL CHURCH OF GOD UNIVERSAL .
NO 309 BORNO WAY, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE CONVERTED	NON DISTRESSED	



SEVETH DAY ADVENTIST
 NO 7 MOLEYE STREET
 BY OLD YABA ROAD, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



KINGSVILLE CHURCH.
 2 AKINWUNMI STREET ALAGOMEJI YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BULT	NON DISTRESSED	



THE ETERNAL SACRED ORDER OF CERUBUM AND SERAPHIN.
 NO 15 ISHOLA STREET OFF CASINO CINEMA, ALAGOMEJI, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



JEHOVAH WITHNESS CHURCH
 NO 64 OLD YABA ROAD, ADEKUNLE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BULT	NON DISTRESSED	



RCCG

NO 15B ISHOLA OFF CASINO CINEMA,
ALAGOMEJI.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



RCCG

NO 13 ALARA STREET,SABO,YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BULT	NON DISTRESSED	





PISON COURT
AT NO 3 IWAYA ROAD, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 & 2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



JOHN ANGLICAN CHURCH
AT 2 DACOSTA STREET,
OFF IWAYA ROAD, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BULT	NON DISTRESSED	





MFM NATIONAL HQ
AT IWAYA ROAD, ONIKE, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



TCCG CITY OF GOSHEN
NO 49 MAJARO STREET, ONIKE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BULT	NON DISTRESSED	





ONEBODY CHURCH IN NIGERIA
34 MCNEIL ROAD SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	



FOURSQUARE GOSPEL CHURCH
AT COMMERCIAL AVENUE, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	NOT APPROVED	COMMERCIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	





OAK HOUSE CHURCH.
OFF COMMERCIAL AVENUE SABO YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



FOURSQUARE HOSPEL.
AT ONITIRI AT NO 10 LAWANI STREET,
ONIKE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





SOUL WINNING CHURCH .
AT NO 277 BORNO WAY, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



BAPTIST CHURCH.
ONITIRI AT NO 14 LAWANI STREET,
ONIKE, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDEEMED CHRISTIAN CHURCH OF GOD (ROYAL COURT)
ALONG ALAKIJA ROAD OPP YABATECH, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



MOUNTAIN OF FIRE MINISTRY .
12 ALAKIJA ROAD JIBOWU, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



ST STEPHEN ANGLICAN CHURCH
NO 15 OWEH STREET JIBOWU, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



SAINT COMMUNITY CHURCH .
NO 6 OWEH STREET JIBOWU YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





HIGHLAND CHURCH .
NO 22 OWEH STREET, JIBOWU, YABA.


NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



THE STONE CHURCH.
NO 4 SHIRO STREET FADEYI YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	NOT APPROVED	COMMERCIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	





**REDEEMED CHRISTIAN CHURCH
OF GOD (MIRACLE MEGA PARISH)**
NO 5 ELMWS ROAD,
OFF EDMUND CRESCENT JIBOWU YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



COVENANT CHRISTIAN CENTER .
NO 404 HERBERT MACAULAY WAY

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





LAGOS PRESBYTERIAN CHURCH
NO 394 MURITALA MUHAMMED WAY YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDEEMED CHRISTIAN CHURCH OF GOD (SOUGHTOUT TABERNACLE)
NO 3 ALAKA STREET, ABULE, IJESHA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





REDEEMED CHRISTIAN CHURCH OF GOD . (PALACE OF PRAISE PARISH)
NO 19 ALAKA STREET ABULE IJESHA YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDEEMED CHRISTIAN CHURCH OF GOD (REIGNS PARISH)
NO 22 BAMGPOPA STREET, ABULE IJESHA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



FOURSQUARE GOSPEL CHURCH
NO 13 ELETU ODIBO STREET, ABULE IJESHA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



MOUNTAIN OF FIRE MINISTRY.
NO 4 ELETU ODIBO STREET,
ABULE OJA, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	NOT APPROVED	COMMERCIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	MIXED USE	NON DISTRESSED	





**REDEEMED CHRISTIAN
CHURCH OF GOD.**
NO 387, HERBERT MACAULAY WAY, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



RCCG .
NO 3 ELETU ODIBO STREET,
ABULE OJA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	NOT APPROVED	RESIDENTIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	CONVERTED	NON DISTRESSED	





ST DOMNIC CATHOLIC CHURCH.
NO 354, HERBERT MACAULAY WAY YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
ADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDEEMED CHRISTIAN CHURCH OF GOD.
NO 370, HERBERT MACAULAY WAY, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	NOT APPROVED	COMMERCIAL	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	CONVERTED	NON DISTRESSED	





**FOUR SQUARE GOSPEL CHURCH.
(LIGHT ARENA)**
NO 3, THORBURN AVENUE, SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



CHURCH OF CHRIST.
NO 404, HERBERT MACAULAY WAY

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





CELEBRATION CHURCH INTERNATIONAL.
OFF CUSTODIAN STREET SABO, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



REDEEMED CHRISTIAN CHURCH OF GOD. (SOLID ROCK PARISH)
NO 2, LATUNDE STREET, ADEKUNLE, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



**CELESTIAL CHURCH OF CHRIST.
HEAD QUARTERS.**

NO 2, CHURCH STREET, MAKOK, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



**REDEEMED CHRISTIAN CHURCH
OF GOD. (THE FOUNTAIN OF JOY)**

NO 32, OLD YABA ROAD, ADEKUNLE YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	NOT APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





FOURSQUARE GOSPEL CHURCH.
NO 62/66 AKINWUNMI STREET,
ALAGOMEJI, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
5 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



SAINT JOHN ANGLICAN CHURCH.
OFF DA COSTA IWAYA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
1 FLOOR	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	





SAINT STEPHEN CATHOLIC CHURCH.
NO 12, GBETO STREET, IWAYA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
3 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



CHAPEL OF LIGHT.
UNILAG, AKOKA, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



**THE CHURCH OF THE LORD
ALADURA.**
NO 21, AYINDE STREET, YABA

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
2 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
NO PROVISION	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	



CAPSTONE RESOURCE CENTRE
NO 25, AYINDE STREET, YABA.

NO FLOORS	APPROVAL STATUS	PURPOSE OF BUILDING	DEFECTS ON STRUCTURE		
4 FLOORS	APPROVED	CHURCH	NONE		
PARKING PROVISION	STATUS OF BUILDING	CONFORMITY STATUS	TYPE OF USE	STRUCTURAL STATUS	
INADEQUATE	GOOD	NON CONFORMING	PURPOSE BUILT	NON DISTRESSED	

