

# LAGOS STATE BUILDING CONTROL AGENCY ALIMOSHO DISTRICT

# COMPENDIUM OF VACANT PLOTS, ONGOING CONSTRUCTIONS, RENOVATIONS, RE-MODELLING AND ABANDONED STRUCTURES IN ALIMOSHO DISTRICT





PREPARED BY

Althode Lago


Althode Lago

ENGR AREMU H.A

SUPERVISING DIRECTOR ALIMOSHO DISTRICT



## **COVERAGE AREA**



# **STAFF STRENGTH**

S/N.	NAME	DESIGNATION	GRADE LEVEL	POSITION
1.	ENGR HEPHZIBAH AREMU	CHIEFTECHNICAL OFFICER	14	SUPERVISING DIRECTOR
2.	ARC JOSIAH OLUSOLA OLADIPO	SENIOR ARCHITECT	10	BUILDING INSPECTOR
3.	ENGR AGBONYIN OLUWAFEMI ADENIYI	SENIOR ENGINEER (CIVIL)	10	BUILDING INSPECTOR
4.	ENGR AWOLOLA AYOOLA HENRY	SENIOR ENGINEER (CIVIL)	10	BUILDING INSPECTOR
5.	AKINPELU IFEDAYO OLUWATOSIN	SENIOR ARCHITECT	10	BUILDING INSPECTOR
6.	BLDR LAWAL GANIYAT MOTUNRAYO	SENIOR BUILDING OFFICER	10	BUILDING INSPECTOR
	OJO OLAJUMOKE SIKIRAT	SENIOR TECHNICAL OFFICER	09	BUILDING INSPECTOR

## INTRODUCTION

This exercise is to prepare a compendium of all vacant plots, ongoing constructions, renovations and abandoned buildings within Alimosho district. The exercise involves;

Physical visitation of the highlighted structure types, determining their building permit status, stage of work, appraisal and level of deterioration.


# **ONGOING CONSTRUCTIONS**





#### 22 AJILEKEGE STREET, PIPELINE IDIMU, ALIMOSHO





ADDRESS: 22 AJILEKEGE STREET, ALIMOSHO


APPROVAL STATUS: PROV/221/AL


AUTHORIZATION STATUS: LASBCA/ALM/22/SC/024

STAGE OF WORK: FIRST FLOOR SLAB FORMWORK

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

#### 3 OWUTEDO STREET, OFF AWORI STREET, EGBEDA, ALIMOSHO





ADDRESS: 3 OWUTEDO STREET, ALIMOSHO


**APPROVAL STATUS: UNCERTAIN** 


**AUTHORIZATION STATUS: LASBCA/ALM/21/** 

STAGE OF WORK: ROOFED/ UNPLASTERED

STRUCTURAL DEFECTS:NONE

#### 8 OLUGBEDE STREET, PIPELINE, ALIMOSHO





ADDRESS: 8 OLUGBEDE STREET, ALIMOSHO


APPROVAL STATUS: DCB/PROV/167/EI


AUTHORIZATION STATUS: LASBCA/ALM22/SC/012

**STAGE OF WORK: FINISHES** 

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

#### 23 SOLOMON OKONKWO, OFF AWORI STREET, ALIMOSHO





ADDRESS: 23 SOLOMON OKONKWO STREET, ALIMOSHO


**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

STAGE OF WORK: ROOFED/UNPLASTERED

REMARKS: ALL STATUTORY NOTICES SERVED.
AWAITING RESPONSE FROM OWNER/DEVELOPER

#### JUST RITE: 117 AKOWONJO ROAD, JIMOH BUS STOP, ALIMOSHO



ADDRESS: 117 AKOWONJO ROAD, JIMOH BUS STOP, ALIMOS

APPROVAL STATUS: DCB/DO/859/AL

**AUTHORIZATION STATUS: UNCERTAIN** 

**STAGE OF WORK: FINISHES** 

**REMARKS: SEALED AND UNSEALED AT DISTRICT** 

**LEVEL** 

## 127 AKOWONJO ROAD, JIMOH BUS STOP, ALIMOSHO



ADDRESS: 127 AKOWONJO ROAD, ALIMOSHO

APPROVAL STATUS: UNCERTAIN

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: FORMWORK FOR FIRST FLOOR

**COLUMNS IN PLACE** 

#### TINUOLA CLOSE, OFF AKOWONJO ROAD, ALIMOSHO



ADDRESS: TINUOLA CLOSE, ALIMOSHO

APPROVAL STATUS:UNCERTAIN

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: FORMWORK FOR FOURTH FLOOR

**COLUMNS IN PLACE** 

REMARKS: SEALED BY CENTRAL ENFORCEMENT.

STILL AWAITING RESPONSE FROM

**OWNER/DEVELOPER** 

#### 14 ISIBA OLUWO STREET, OFF ORELOPE STREET, EGBEDA, ALIMOSHO



ADDRESS: 14 ISIBA OLUWO STREET

APPROVAL STATUS: DCB/DO/871/AL

**AUTHORIZATION STATUS: GREEN STICKER** 

**STAGE OF WORK: FOUNDATION** 

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

#### PROPERTY BESIDE ACCESS BANK, ALONG AKOWONJO RD, ALIMOSHO



ADDRESS: PROPERTY BESIDE ACCESS BANK, AKOWONJO RD


**APPROVAL STATUS: NIL** 


**AUTHORIZATION STATUS: NIL** 

STAGE OF WORK: FIRST FLOOR COLUMNS

**REMARKS: SITE SEALED AT DISTRICT LEVEL** 

#### PROPERTY ALONG ALH. ADETUTU STREET, ALIMOSHO





ADDRESS: PROPERTY ALONG ALH. ADETUTU STREET

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

**STAGE OF WORK: FINISHES** 

REMARKS: ALL STATUTORY NOTICES SERVED.AWAITING RESPONSE FROM

OWNER/DEVELOPER

#### PROPERTY AT 4 BUSARI STREET, MICCOM, EGBEDA, ALIMOSHO



ADDRESS: PROPERTY AT 4 BUSARI STREET


APPROVAL STATUS: AL2020/00/025/019

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: FIRST FLOOR SLAB

STRUCTURAL DEFECTS: NONE

#### PROPERTY AT BAKERY BUS STOP BESIDE EDULAND SCHOOLS, ALIMOSHO



ADDRESS: PROPERTY AT BAKERY BUS STOP, ALIMOSHO

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: SECOND FLOOR SLAB

**REMARKS: PARTIALLY DEMOLISHED AND SEALED BY** 

**CENTRAL ENFORCEMENT** 

#### PROPERTY AT SHASHA ROAD, ALIMOSHO



ADDRESS: PROPERTY AT SHASHA ROAD, ALIMOSHO

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

**STAGE OF WORK: FINISHES** 

**REMARKS: ALL STATUTORY NOTICES SERVED AND** 

SITE SEALED AT DISTRICT LEVEL

## PROPERTY AT SELIAT STREET, ALIMOSHO



ADDRESS: PROPERTY AT SELIAT STREET, ALIMOSHO

APPROVAL STATUS: PROV/149/AL

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 3<sup>rd</sup> FLOOR BLOCK SETTING

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

#### PROPERTY AT 16 OLATUNBOSUN STREET, ALIMOSHO




ADDRESS: PROPERTY AT 16 OLATUNBOSUN STREET

**APPROVAL STATUS: UNCERTAIN** 

AUTHORIZATION STATUS: LASBCA/ALM/22/SC/021

STAGE OF WORK: ROOFED/ FINISHES

#### PROPERTY AT 21 OLA AKINPELU STREET, ALIMOSHO



ADDRESS: PROPERTY AT 21 OLA AKINPELU STREET

APPROVAL STATUS: PROV/146/AL


AUTHORIZATION STATUS: LASBCA/ALM/22/SC/025

STAGE OF WORK: 1st FLOOR SLAB

STRUCTURAL DEFECTS: NONE

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

#### PROPERTY AT IREPODUN STREET, ALIMOSHO



ADDRESS: PROPERTY AT IREPODUN STREET

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 1st FLOOR SLAB

STRUCTURAL DEFECTS:NONE

**REMARKS: SEALED AT DISTRICT LEVEL** 

#### PROPERTY AT 45 ALIMOSHO ROAD, ALIMOSHO



ADDRESS: PROPERTY AT 45 ALIMOSHO ROAD

APPROVAL STATUS: DCB/DO/807/AL


**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 2<sup>nd</sup> FLOOR LINTEL

STRUCTURAL DEFECTS:NONE

**REMARKS: UNDER SUPERVISION** 

#### PROPERTY AT BLK 8 ALIMOSHO ROAD, ALIMOSHO



ADDRESS: PROPERTY AT BLK 8 ALIMOSHO ROAD


APPROVAL STATUS: PROV/2021/DP/183/AL

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: ROOFED/ FINISHES

**REMARKS: ALL STATUTORY NOTICES.** 

#### PROPERTY AT 44 AKINWOWO STREET, ALIMOSHO




ADDRESS: PROPERTY AT AKINWOWO STREET


**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 2<sup>nd</sup> FLOOR SLAB

#### PROPERTY AT 1 UNITY CLOSE, ALIMOSHO





ADDRESS: PROPERTY AT 1 UNITY CLOSE

APPROVAL STATUS: DCB/DO/871/AL

**AUTHORIZATION STATUS: UNCERTAIN** 

**STAGE OF WORK: ROOF CARCASS** 

#### PROPERTY AT 34 RAJI OBA STREET, ALIMOSHO




ADDRESS: PROPERTY AT 34 RAJI OBA STREET

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 1<sup>ST</sup> FLOOR SLAB

#### PROPERTY AT 4 ALIMOSHO ROAD



ADDRESS: PROPERTY AT 4 ALIMOSHO ROAD

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: 2<sup>ND</sup> FLOOR SLAB

**REMARKS: UNDERGOING STAGE CERTIFICATION** 

# **RENOVATIONS**





## PROPERTY ALONG TINUOLA STREET, ALIMOSHO



ADDRESS: PROPERTY ALONG TINUOLA CLOSE

**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

**STAGE OF WORK: CLADDING** 

#### PROPERTY AT 4 OLATUNBOSUN STREET, ALIMOSHO



ADDRESS: PROPERTY AT 4 OLATUNBOSUN STREET

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: BLOCK SETTING

#### PROPERTY AT 6 OYEMADE STREET, SANTOS LAYOUT, ALIMOSHO



ADDRESS: PROPERTY AT 6 OYEMADE STREET, SANTOS

**APPROVAL STATUS: UNCERTAIN** 

**AUTHORIZATION STATUS: UNCERTAIN** 

STAGE OF WORK: RENOVATION ONGOING

STRUCTURAL DEFECTS:NONE

# **ABANDONED BUILDINGS**





#### PROPERTY AT OLADIPUPO FAFOORE STREET, ALIMOSHO



ADDRESS: AT OLADIPUPO FAFOORE STREET, ALIMOSHO

**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

**STAGE OF WORK: ABANDONED** 

STRUCTURAL DEFECTS: DILAPIDATED ROOF

#### PROPERTY AT 1 OGUNDIPE STREET, ALIMOSHO



ADDRESS: AT 1 OGUNDIPE STREET, ALIMOSHO

**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

STRUCTURAL DEFECTS: DILAPIDATED ROOF

#### PROPERTY AT 34 OLUGBEDE STREET, ALIMOSHO




ADDRESS: AT 34 OLUGBEDE STREET, ALIMOSHO

**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

**STAGE OF WORK: ABANDONED** 

#### PROPERTY AT 17 OGBOMOSHO STREET, ALIMOSHO



ADDRESS: AT 17 OGBOMOSHO STREET, ALIMOSHO

**APPROVAL STATUS: NIL** 

**AUTHORIZATION STATUS: NIL** 

**STAGE OF WORK: ABANDONED** 

REMARKS: ALL STATUTORY NOTICES SERVED

AWAITING RESPONSE FROM OWNER/DEVELOPER

# **VACANT PLOTS**





#### PROPERTY AT 24 OLATUNBOSUN STREET, ALIMOSHO




ADDRESS: AT 24 OLATUNBOSU STREET, ALIMOSHO

## PROPERTY AT 3 AKANNI MAJIYAGBE STREET, ALIMOSHO




ADDRESS: AT 3 AKANNI MAJIYAGBE STREET, ALIMOSHO

# PROPERTY AT 24 ISIBA OLUWO STREET, ALIMOSHO




ADDRESS: AT 24 ISIBA OLUWO STREET, ALIMOSHO

#### PROPERTY AT AYODELE AMUSAT STREET, OFF GBELEYI STREET, ALIMOSHO



ADDRESS: AT AYODELE AMUSAT STREET, ALIMOSHO

#### PROPERTY AT 6 SAM ROSE STREET, ALIMOSHO



ADDRESS: AT 6 SAM ROSE STREET, ALIMOSHO

#### PROPERTY AT 4 ALIMOSHO ROAD, ALIMOSHO



ADDRESS: AT 4 ALIMOSHO ROAD, ALIMOSHO

# PROPERTY AT 181 AKOWONJO ROAD, ALIMOSHO




ADDRESS: AT 181 AKOWONJO ROAD, ALIMOSHO

## **CHALLENGES**

Some sites were locked thereby hindering access to enable us carry out proper inspection.

# CONCLUSION

A total of 23 ongoing constructions, 4 renovations, 9 abandoned and 8 vacant plots were captioned during this exercise.



# THANK YOU!