COMPEDIUN OF ONGOING CONSTRUCTION, RENOVATIONS / RESTRUCTURING, VACANT PLOTS AND ABANDONED STRUCTURES WITHIN BARIGA DISTRICT

SUBMITTED BY

- 1. Bldr. Olawuyi A.O
- 2. Otuyemi Olusegun
- 3. Alabi Abdulateef
- 4. Ajokotola Olufunmilola

INTRODUCTION

of Somolu Local Government in the year 2003 to bring socio-economic and infrastructural development to the people. In a bid to ensure close monitoring exercise within the area by LASBCA Officers, Bariga District was also carved out of Somolu district. Bariga district office is located at plot 6, Town planning way, Ilupeju, Lagos State.

COVERAGE AREA FOR BARIGA



BARIGA DISTRICT COVERAGE AREA

- GBAGADA OHASE I
- GBAGADA PHASE II
- ILAJE
- PEDRO
- ODO-OBA
- BARIGA NEW GARAGE
- ► LAD-LAK
- ODUNSI

SUMMARY PAGE

► ONGOING CONSTRUCTION: 88

► RENOVATION / RECONSTRUCTION: 9

► VACANT PLOTS: 41

► ABANDONED: 4

ONGOING CONSTRUCTION WITHIN BARIGA DISTRICT

27, EWENLA STREET BARIGA

LASEGA LASEGA

NO OF FLOORS: UNKNOWN

APPROVAL: NO NILL

AUTHORIZATION: NILL

STAGE OF WORK: FIRST

FLOOR SLAB

REMARK: SITE SEALED (
BREAK OF SEAL) TO BE

ENFORCED



LASE



WATCHMAN CHARISMATIC RENEWAL CHURCH OBANIKORO BARIGA

NO OF FLOORS:4

APPROVAL: APPROVED


AUTHORIZATION: YES

STAGE OF WORK:

PLASTERING

REMARK: UNDER STAGE

INSPECTION,





LASBOA LASBOA

NO OF FLOORS:3

APPROVAL: APPROVED


AUTHORIZATION: YES

STAGE OF WORK:

1ST SUSPENDED SLAB

REMARK: UNDER STAGE

INSPECTION








NO OF FLOORS:2

APPROVAL: NON

AUTHORIZATION: NON

STAGE OF WORK: RESTRUCTURING

REMARK: SEALED





SAFURATU SEKONI STREET, BARIGA (R.JOLAD)

NO OF FLOORS:6

APPROVAL: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: PLASTERING

REMARK: UNDER STAGEINSPECTION





51 SHOGBAMU STREET, BARIGA

NO OF FLOORS:3

APPROVAL: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FOUNDATION

REMARK: UNDER STAGE

INSPECTION



39 OKUTA ROAD, BARIGA



NO OF FLOORS: UNKNOWN

APPROVAL: UNKNOWN

AUTHORIZATION: UNKNOWN

STAGE OF WORK: FOUNDATION

REMARK: TO BE ENFORCED





1 AYODEJI OTEGBOLA STREET GBAGADA PHASE 1, BARIGA

NO OF FLOORS:3

APPROVAL: YES

AUTHORIZATION: YES

STAGE OF WORK: ROOF LEVEL

REMARK: UNDER STAGE

INSPECTION





1 ENGR. ABODUNRIN ADEBIMPE CLOSE, GBAGADA PHASE 1, BARIGA

NO OF FLOORS:2

APPROVAL: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: FINISHES

REMARK:





49, IGI OLUGBIN STREET, BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL: NO UNKNOWN

STAGE OF WORK: GROUND

FLOOR COLUMNS

REMARK: SITE SEALED



7 OGUNYADE STREET, GBAGADA PHASE 2 BARIGA



NO OF FLOORS:1 FLOOR

APPROVAL: NO UNKNOWN

STAGE OF WORK: ROOF

BEAM

REMARK: SITE TO BE

ENFORCED

LASE





NO11, TIJANI ASHOGBON STREET, BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL: UNKNOWN

AUTHORIZATION: NIL

STAGE OF WORK: 2ND

SUSPENDED SLAB

REMARK: SEAL BROKEN FOR

FURTHER ENFORCEMENT





65B OLORUNKEMI STREET,

BARIGA

NO OF FLOORS: 3

APPROVAL: EVIDENCE OF

SUBMISSION

AUTHORIZATION: NIL

STAGE OF WORK: IST FLOOR

SLAB

REMARK: SITE SEALED





CORNER PIECE OF KAJOLA STREET AND IGI- OLUGBIN ROAD BARIGA

NO OF FLOORS: 2

APPROVAL: SUBMISSION

AUTHORIZATION: NIL

STAGE OF WORK: FIRST

SUSPENDED SLAB

REMARK: SITE SEALED





STREET BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NIL

STAGE OF WORK: ROOF

CARCASS

REMARK: (SITE SEALED)FOR

FURTHER ENFORCEMENT









NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN


AUTHORIZATION: NIL

STAGE OF WORK: GROUND

FLOOR BLOCK WORK

REMARK: BREAK OF SEAL FURTHER ENFORCEMENT

REQUIRED







NO OF FLOORS: 3


APPROVAL STATUS: YES

AUTHORIZATION: NIL

STAGE OF WORK: GROUND

FLOOR COLUMNS

REMARK: SITE SEALED





8 ADEBAYO, STREET, OFF PEDRO BARIGA

NO OF FLOORS: 2 FLOORS

APPROVAL STATUS: YES

AUTHORIZATION: YES

STAGE OF WORK: 1ST FLOOR

LINTEL

REMARK: UNDER STAGE

INSPECTION









NO OF FLOORS: 2 FLOORS

APPROVAL STATUS: NILL

AUTHORIZATION: NILL

STAGE OF WORK: RESTRUCTURING

REMARK: USITE TO BE

ENFORCED







NO OF FLOORS: 2

APPROVAL STATUS: NO RENOVATIONS PERMIT

AUTHORIZATION: NIL

STAGE OF WORK: FINISHES

REMARK: SITE SEALED



LASEGA



4 OFO STREET, OFF PEDRO ROAD BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NIL

STAGE OF WORK: GROUND

FLOOR BLOCK SETTING

REMARK: SITE TO BE

ENFORECED





24 MUTAIRU STREET, OFF PEDRO ROAD BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NIL

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: SITE TO BE

ENFORECED





1 BAWALA STREET, OFF PEDRO ROAD BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: NIL

STAGE OF WORK: RENOVATION

REMARK: TO OBTAIN

AUTHORIZATION.



91, ILAJE ROAD BARIGA




NO OF FLOORS: 3

APPROVAL STATUS: NO AUTHORIZATION: NIL

STAGE OF WORK: FIRST FLOOR

BLOCK WORK

REMARK: SITE SEALED



13 WULEMOTU AJOKE STREET,

BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: NILL

NO AUTHORIZATION: NIL

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: SITE SEALED



LASBOA





NO OF FLOORS: 3

APPROVAL STATUS: YES

NO AUTHORIZATION: YES

STAGE OF WORK: FOUNDATION

REMARK: UNDER STAGE

INSPECTION





58/60 COMMUNITY ROAD, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: NO RENOVATIONS PERMIT

NO AUTHORIZATION: NIL

STAGE OF WORK: REMODELING

ONGOING

REMARK: SITE SEALED





5 BABS KAZEEM STREET, BARIGA

NO OF FLOORS: 2

APPROVAL STATUS: UNKOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: PLASTERING

REMARK: SITE SEALED



9 TAPA STREET, BARIGA




NO OF FLOORS: 2

APPROVAL STATUS: UNKOWN

NO AUTHORIZATION: NIL

STAGE OF

REMARK: SITE SEALED BY CENTRAL ENFORCEMENT







NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKOWN

NO AUTHORIZATION: NIL

STAGE OF

REMARK: ENFORCEMENT

REQUIRED





CORNER PIECE OF ALLAJI ALLIMI AND OLATUNJI STREET, BARIGA

NO OF FLOORS: UNKNOWN


APPROVAL STATUS: UNKOWN

NO AUTHORIZATION: NIL

STAGE OF

REMARK: ENFORCEMENT

REQUIRED





10, BOLOWOSERE STREET BARIGA,

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFED

REMARK: SITE SEALED



LASBOA



13 TOLUWALASE STREET BARIGA,

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: GROUNG

FLOOR BLOCK WORK

REMARK: SITE SEALED



LASDOA

19 OGUNTONA STREET, GBAGADA BARIGA,

LASBGA PAGENCY

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFED,

WORK STOPEED

REMARK: TO ASCERTAIN

APPROVAL BEFORE

CONTINUATION OF

CONSTRUCTION WORKS



7 ADEFUYE LANE BARIGA



NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFED,

WORK STOPEED

REMARK: TO ASCERTAIN

APPROVAL BEFORE

CONTINUATION OF

CONSTRUCTION WORKS

REMARK: SITE SEALED



12 IGBEHIN ADUN STREET BARIGA



NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATIONUNKNOUN

STAGE OF WORK: FOUNDATION

REMARK: TO REMARK: SITE TO BE SEALED FOR COMPLIANCE



BABAJIDE EWULOMI OFF AWIN STREET BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: UNKNOUN

STAGE OF WORK: ROOF

REMARK: SITE SEALED

CONSTRUCTION STOPPED



LASDOA

8 MAJIYAGBE,OFF PEDRO ROAD BARIGA



NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

NO AUTHORIZATION: UNKNOUN

STAGE OF WORK: GROUNG

FLOOR BLOCK WORL

REMARK: SITE SEALED.

CONSTRUCTION STOPPED FOR

LONG





11 ODO-OBA STREET BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: FIRST

ROOF PARAPET

REMARK: BREAK OF SEAL



21 ALFA SANNI STREET BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: 3RD FLOOR

COLUNMS

REMARK:



8 SHOYINKA STREET, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFED

REMARK: SEALED, AND

WORK STOPPED







NO OF FLOORS: 2

APPROVAL STATUS:

SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFING

REMARK: SEALED.



4 OSOSA ROAD, BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: 3RD FLOOR

BLOCK WORK

REMARK:







NO OF FLOORS: 3


APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: SEALED





19 SERIKI ARO COMPUND, BARIGA

NO OF FLOORS: 2

APPROVAL STATUS: YES

NO AUTHORIZATION: YES

STAGE OF WORK: GROUND

FLOOR SLAB

REMARK: UNDER STAGE

INSPECTION







NO OF FLOORS: 2

APPROVAL STATUS: SUBMISSION

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFING

LEVEL

REMARK: SEALED.



6 OKUTA ROAD, BARIGA



NO OF FLOORS: 3

APPROVAL STATUS:

UNKNOWN

NO AUTHORIZATION: NIL

STAGE OF WORK: ROOFING

LEVEL

REMARK: SEALED.





BARIGA

NO OF FLOORS: 2

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FIRST FLOOR

BLOCK WORK

REMARK: UNDER STAGE

INSPECTION







EBUN FOLA JINADU STREET GBAGADA PHASE I, BARIGA (REGENCY ALLINACE)

NO OF FLOORS: 2

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: PLASTERED

REMARK: UNDER STAGE







NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 1ST SUSPENDED

SLABREMARK: UNDER STAGE





100 IGI OLUGBI100 IGI OLUGBIN ROAD, BARIGAN ROAD, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 2ND SUSPENDED

SLAB

REMARK: UNDER STAGE



LAS





NO OF FLOORS: 2, RENOVATION

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: RENOVATION

ONGOING

REMARK: UNDER STAGE





OPPOSITE CITY OF POWER CHURCH, OFF ADEBAYO STREET, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FINISHES

REMARK: UNDER STAGE

INSPECTION



40 ADARANIJO BY PEDRO ROAD, BARIGA

LASEGA LASEGA

NO OF FLOORS: 3


APPROVAL STATUS: APPROVED

APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FINISHES

REMARK:







NO OF FLOORS: 3

APPROVAL APPROVED

AUTHORIZATION: YES

STAGE OF WORK:

REMARK: SITE SEALED

(NO EVIDENCE OF STAGE

INSPECTION)





GBAGADA CENTRAL MOSQUE, 5 LANRE AWOLOKUN STREET BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: NILL

STAGE OF WORK: FORM WORK

TO FIRST SUSPENDED SLAB

REMARK: SEALED







NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: REMARK: CONSTRUCTION STOPPED



MOJOYINOLA STREET BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: NILL

AUTHORIZATION: NILL

STAGE OF WORK: 2ND

SUSPENDED SLAB

REMARK: SEALED, TOKED BY

ENFORCEMENT





REDEEMED CHRISTIAN CHURCH OF GOD, GBAGADA EXPRESS, BEHIND TREM.

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 3RD FLOOR

BLOCK WORK

REMARK: UNDER STAGE

INSPECTION



2 BANKOLE STREET, BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 3RD FLOOR

LINTEL LEVEL

REMARK: UNDER STAGE.
CONSTRUCTION STOPPED







NO OF FLOORS: 4

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: UNDER STAGE





16 OYEYEMI BY ODEREMO STREET, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 1ST FLOOR

SLAB

REMARK: UNDER STAGE





65 OLORUNKEMI STREET, BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: SEALED (NO EVIDENCE

OF STAGE INSPECTION)



3 ADEBAMBO STREET, OFF OBANIKORO BARIGA

NO OF FLOORS: 4

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: PLASTERING

REMARK: UNDER STAGE

INSPECTION





OPPOSITE 9 ORESEGUN STREET, BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: FOUNDATION

REMARK: ENFORCEMENT

REQUIRED







NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: UNKNOWN

STAGE OF WORK: PILLING

REMARK: TO BE ENFORCED







NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: ROOFED

REMARK: UNDER STAGE





18 JOHNSON STREET CORNER PIECE OF JOHNSON AND IJAGBEMI STREET,

BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: YES

AUTHORIZATION: YES

STAGE OF WORK: ROOF BEAM

REMARK: UNDER STAGE







NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN

AUTHORIZATION:

STAGE OF WORK: 2ND FLOOR

SLAB

REMARK: SITE SEALED







NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: PLASTERED

REMARK: UNSER STAGE

INSPECTION







NO OF FLOORS: UNKNOWN

APPROVALSTATUS: UNKNOWN

AUTHORIZATION: UNKNOWN

STAGE OF WORK: GROUND FLOOR BLOCK SETTING

REMARK: CONTRA AND STOP WORK NEWLY SERVED SITE TO BE SEALED





12 AYINKE STREET, BARIGA

NO OF FLOORS: 2 F

APPROVALSTATUS:S

AUTHORIZATION: N

STAGE OF WORK: P







NO OF FLOORS: 3 FLOOR

APPROVALSTATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: PLASTERED





14 IGBEHINADUN STREET, BARIGA

NO OF FLOORS: UNKNOWN

APPROVALSTATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: FOUNDATION





TIJANI ASHOGBON STREET, BARIGA (MARYADE SPECIALIST HOSPITAL)

NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK:PLACEMENT OF ROOF MEMBERS ON EXISTING

THREE FLOOR STRUCTURE







NO OF FLOORS:3

APPROVAL STATUS: APPROED

AUTHORIZATION: YES

STAGE OF WORK: RENOVATION

REMARK: UNDER STAGE

INSPECTION





9 OLATUNJI STREET OFF ILAJE ROAD BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: PLACEMENT OF

ROOF MEMBERS

REMARK: SITE TO BE

ENFORCED.



 $L\Delta$



NO 18 OYENUGA STREET, AKOKA BARIGA

NO OF FLOORS: 4

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FOURTH

FLOOR BLOCK WORK

REMARK: UNDER STAGE

INSPECTION







NO OF FLOORS: 2

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: PLASTERED





10/12 ONAJIMI STREET, AKOKA BARIGA

NO OF FLOORS: 2

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: PLASTERING

UNDER STAGE INSPECTION







NO OF FLOORS: 3


APPROVAL STATUS: UNKNOWN

AUTHORIZATION: UNKNOWN

STAGE OF WORK: 2ND FLOOR BLOCK WORK CONSTRUCTION

STOPPED

UNDERSITE SEALED



GBAGADA LANE, BARIGA



NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: 2ND SUSPENDED

SLAB

REMARK: UNSER STAGE

INSPACTION





7A BLOCK AB OBANIKORO OKE-IRA,, BARIGA

NO OF FLOORS: 2

APPROVAL STATUS: APPROVED

AUTHORIZATION: YES

STAGE OF WORK: FOUNDATION

UNDER STAGE INSPECTION



LAS



IGBAJA STREET OFF ABU STREET BARIGA

NO OF FLOORS: 3

APPROVAL STATUS: APPROVED

AUTHORIZATION: NILL

STAGE OF WORK: 1ST FLOOR

BLOCK WORK

REMARK: SITE SEALED







BADEJO STREET OFF ABU STREET

BARIGA

NO OF FLOORS: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: 2ND

SUSPENDED SLAB

REMARK: SITE TO BE ENFORCED





7 CHURCH STREET BARIGA (SIX HOMES)

NO OF FLOORS: 3

APPROVAL STATUS: YES

AUTHORIZATION: YES

STAGE OF WORK: FINISHES

REMARK: UNDER STAGE

INSPECTION





CORNER PIECE OF OLANREWAJU

STREET

NO OF FLOOR: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: GROUND

FLOOR COLUMNS

REMARK: TO BE ENFORCED





CORNER PIECE OF OLANREWAJU STREET

NO OF FLOOR: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: GROUND

FLOOR BLOCK WALL

REMARK: TO BE ENFORCED





BEND OF RESIDENCE ROAD GBAGADA PHASE 2

NO OF FLOOR: UNKNOWN

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: FOUNDATION

REMARK: TO BE ENFORCED





NO OF FLOOR: 2

APPROVAL STATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: PLASTERING





NO OF FLOOR: 2

APPROVAL STATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: PLASTERING






NO OF FLOOR: 2 PLUS PENT

APPROVAL STATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: ROOFED





NO OF FLOOR: 2

APPROVAL STATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: BLOCK WORK

TO 2ND FLOOR COMPLETED





CORNER PIECE OF AYODELE AND AYINKE STREET BARIGA

NO OF FLOOR: 4

APPROVAL STATUS: UNKNOWN

AUTHORIZATION: NILL

STAGE OF WORK: RENOVATION





NO OF FLOOR: 2

APPROVAL STATUS: SUBMISSION

AUTHORIZATION: NILL

STAGE OF WORK: FOUNDATION






7 MOSHOOD BAKARE STREET BARIGA





7 ODUKOYA STREET, BARIGA





11 SOGBAMU STREET, BARIGA





21 SOGBAMU STREET, BARIGA







12 OGUNYEMI STREET, OFF IGBEYIN ADUN STREET BARIGA

VACANT PLOT

LASE




12 DANMOLE STREET, BARIGA





NO 7 ILAJE ROAD BARIGA





3B WULEMOTU AJOKE STREET, BARIGA







NO 6 BABAJIDE EWULOMI STREET BARIGA, OFF AWIN STREET, BARIGA



13 TESLIM NOSIRU STREET, BARIGA









BESIDE NUMBER 5 TESLIM NOSIRUSTREET, BARIGA



5 CHURCH STREET, BARIGA







OLANREWAJU STREET OFF WULEMOYU AJOKE STREET, BARIGA



ALONG OKUTA ROAD BARIGA





ALONG OKUTA BESIDE MFM CHURCH BARIGA






105 ILAJE ROAD, BARIGA



VACANT PLOT

LASE



7 TOWOBOLA STREET GBAGADA PHASE 2,

BARIGA












17 ADEPEJU STREET, BARIGA





21 OLANIYI STREET, LADI-LAK BARIGA







CORNER PIECE OF SHOGBAMU AND OGUNDERO STREET, BARIGA



9 LANRE AWOLOKUN STREET, BARIGA








PLOT 19, SHITU ANIMASHAUN STREET GBAGADA PHASE 2, BARIGA







BESIDE PLOT 11 RESIDENCE ROAD BGBAGADA PHASE 2, BARIGA



END OF ADEBAYO MUNIS CLOSE, GBAGADA

PHASE 2, BARIGA





40 OGUNTANA CRESENT, BARIGA





9 ADEBAYO STREET, BARIGA





12 ADEBAYO STREET, BARIGA







27 CITY OF POWER CLOSE, OFF ADEBAYO STREET, BARIGA





17, LAYI OTEGBOLA STREET, BARIGA





17, MUTAIRU STREET, OFF PEDRO BARIGA





15, MUTAIRU STREET, OFF PEDRO BARIGA





10 ONISEMO STREET, OFF PEDRO ROAD BARIGA

LASBGA LASBGA





108 IGI OLUGBIN ROAD,OFF PEDRO ROAD BARIGA





17 AWOFODU STREET, OFF PEDRO ROAD BARIGA



9 AWOFODU STREET, OFF PEDRO ROAD BARIGA



7 SANYAOLU STREET, BARIGA






80 ODUNSI STREET, BARIGA





7 IFELODUN STREET, BARIGA





30 ODO OBA STREET, BARIGA





11 AYOKA STREET, BARIGA







1 AWOFODU STREET, BARIGA



ABANDONED CONSTRUCTION AT FIRST SUSPENDED SLAB





LAULA IBRAHIM STREET, OPPOSITE HOUSE 5 RICKET, BARIGA

ABANDONED TWO FLOOR STRUCTURE



7 AWOFODU STREET, BARIGA



ABANDONED CONSTRUCTION, GROUND FLOOR BLOCK WORK





BESIDE CITY OF POWER BIBLE CHURCH, OFF ADEBAYO STREET, BARIGA

ABANDONED CONSTRUCTION,



