

LAGOS STATE BUILDING CONTROL AGENCY. MAINLAND DISTRICT OFFICE COMPENDIUM FOR ONGOING CONSTRUCTION, RENOVTION/ REMODELING, VACANT SITE AND ABANDONED SITE.



13TH OCTOBER, 2022

COMPILED BY

SUPERVISING DIRECTOR- IMAM A.O

ENGR. BAKARE OLUKEMI A.

ENGR. OGIDIOLU OLUTOBA I.

ENGR. FASHAKIN TAOHEED A.

ENGR. AFEEZ LANRE

**COMPENDIUM OF VACANT SITES IN LAGOS STATE
MAINLAND DISTRICT**



LOCATION: ALONG WILLOUGHBY STREET, BESIDE AMSAT PRIVATE SCHOOL, EBUTE-METTA

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 19 WILLOUGHBY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION:13 CEMETERY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: 36 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: ALONG HERBERT MACAULAY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: 6 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: 8 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 4 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: ALONG OLOTO STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: 40 WILLOUGBY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 79 BOLA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 61 BOLA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 81 BOLA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 65 JEBBA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 54 JEBBA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: OPPOSITE FOURSQUARE CHURCH AT NO 46A JEBBA

LGA/LCDA: MAINLAND

STAGE OF WORK:VACANT

LAND APPROVAL /TITTLE:N/A

DATE:N/A



LOCATION: 32 HERBERT MACAULAY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A



LOCATION: 82 CEMETERY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: VACANT

LAND APPROVAL /TITLE: N/A

DATE: N/A

COMPENDIUM OF ABANDONED STRUCTURES IN LAGOS STATE
MAINLAND DISTRICT



LOCATION: ALONG CEMETERY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

DESCRIPTION OF PROPERTY: ABANDONED

STAGE OF WORK: STILL ABANDONED

DEVELOPMENT PERMIT STATUS: N/A



LOCATION: 88 CEMETERY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

DESCRIPTION OF PROPERTY: ABANDONED

STAGE OF WORK: STILL ABANDONED

DEVELOPMENT PERMIT STATUS: N/A

COMPENDIUM OF STRUCTURES UNDERGOING RENOVATION AND
REMODELLING WORKS IN LAGOS STATE
MAINLAND DISTRICT



LOCATION: END OF SHACKLEFORD STREET, EBUTE- METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: RENOVATION ONGOING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A



LOCATION: 13 JEBBA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: RENOVATION IN PROGRESS

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A



LOCATION: 15 COATES STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: RENOVATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A



LOCATION: 8 JEBBA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: RENOVATION WORK ON GOING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

COMPENDIUM OF STRUCTURES UNDER CONSTRUCTION IN LAGOS STATE
MAINLAND DISTRICT



LOCATION: 81 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR POST LINTEL

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/178M/178

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 70 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 76 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 68 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: ROOFED (PRIOR TO PLASTERING)

DEVELOPMENT PERMIT STATUS: YA2020/DO/081/49

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 23 TAPA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: THIRD FLOOR SLAB

DEVELOPMENT PERMIT STATUS: YA18/DO/082/49

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 10B SIMPSON STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR SLAB (FORM WORK)

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2022/299M/299

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 17A SIMPSON STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: THIRD SUSPENDED FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 16 MOLONEY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR LINTEL (FORM WORK)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 27 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/317M/317

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 28/30 NIGER STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 44 OLOTO STREET,EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: YA19/DO/065/49

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 2 TAPA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 50A JOSEPH LAMBO STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR SLAB

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 50B JOSEPH LAMBO STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 10 BABANI STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 11 BABANI STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2022/269M/269

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 25 NIGER STREET,EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: SECOND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 33B ABULE-NLA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR SLAB (FORM WORK)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 28 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/51M/51

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 33 JEBBA STREET, EBUTE-METTA LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2022/285M/285

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 67 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR SLAB

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 103 HERBERT MACAULAY WAY, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 19 SIMPSON STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: THIRD FLOOR SLAB

DEVELOPMENT PERMIT STATUS: YA19/D0/010/47

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 6 SIMPSON STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 13 MARKET STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: SECOND FLOOR SLAB

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 39 KADARA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: SECOND FLOOR BLOCK WORK

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/192M/192

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: BABANI STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: ROOFED (PRIOR TO FINISHING)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 11 ONDOSTREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: ROOFED (FINISHING)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 49 COASTES STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: SECOND FLOOR SLAB

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2022/332M/332

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 47 COASTES STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 98 BRICKFIELD STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FINISHING/ FIRST FLOOR SLAB WORK

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 51 OKEOLU STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 43 MOSHALASHI STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: AVAILABLE

STAGE CERTIFICATION:N/A



LOCATION: 42 IBADAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: YA2022/DO/05849

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 12 PATIENCE STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION: N/A



LOCATION: 6 CEMENTARY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOUR COLUMN

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/172M/172

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 49 MC-CULLUM STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR SLAP FORM WORK

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 6 ADEMUYIWA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FIRST FLOOR (POST LINTEL)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 3 SIMPSON STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 95 CEMENTARY STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 20 ADEMUYIWA STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 7 IYA AGAN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR WITH VISIBLE COLUMN REINFORCEMENT

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 4 OLAOGUN STREET, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: SECOND FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 13 FAGBAYIMU STREET BY BRICKFIELD, EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 2 SONUOLA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FINISHING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 39 ASHAKA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FIRST FLOOR (BLOCK WORK)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 1 ABULE-NLA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FOUNDATION

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: END OF THOMAS STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR SLAB

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 92 IBADAN STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : ROOFING (CARCASS ONGOING)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 87A KANO STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR (FORM WORK)

DEVELOPMENT PERMIT STATUS: YA2020/DO/036/49

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 11 MARKURDI STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : PARAPET FORM WORK

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: OJO ONIYUN OPPOSITE CENTRE EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR LINTEL

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 41 APAPA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR LINTEL

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 22 ADEMUYIWA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FIRST FLOOR BLOCK WORK

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 15 IYA AGAN STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FIRST FLOOR (FORM WORK)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: END OF MC CULLUM STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : THIRD FLOOR (BLOCK WORK)

DEVELOPMENT PERMIT STATUS: YAB/EPPID/179M/179

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 34 OKE-OLU STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FINISHING

DEVELOPMENT PERMIT STATUS: YA2020/DO/057/51

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 66 JEBBA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR BLOCK WORK

DEVELOPMENT PERMIT STATUS: YAB/EPPID/2021/145M/145

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 99 FREEMAN STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FINISHING

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 26A JEBBA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : SECOND FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 41 VANGHAN STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FIFTH FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 7 ODALIKI STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : FIRST FLOOR SLAB (FORM WORK)

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 49 ODALIKI STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : THIRD FLOOR

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A



LOCATION: 60 ABULE-NLA STREET EBUTE-METTA, LAGOS

LGA/LCDA: MAINLAND

STAGE OF WORK: GROUND : ROOF BEAM

DEVELOPMENT PERMIT STATUS: N/A

AUTHORIZATION ON STATUS: N/A

STAGE CERTIFICATION:N/A