

PRESENTATION OF ON-GOING CONSTRUCTION, RENOVATION/REMODELLING AND VACANT SITES WITHIN SURULERE DISTRICT, SURULERE, L.G.A, LAGOS.



PRESENTATION BY:

ENGR. JAMES A. O. (SD SURULERE DISTRICT) ENGR. OLOJEDE A.A (BUILDING INSPECTOR) BLRD. AJAYI A. A (BUILDING INSPECTOR)

OCTOBER 2022

TABLE OF CONTENT

Compendium Of Vacant Sites	
Compendium Of Abandoned Structures	
Compendium Of Structures Undergoing Renovation And Remodelling	5
Compendium Of Structures Under Construction	6
Introduction	9
Aim And Objectives Of This Study	10
Map	11
39, Owukori Crescent Alaka Estate, Surulere	13
Two Separate Structure At Oghoetomau Alaka Estate, Surulere	14
Three Separate Structure At Oghoetomau Alaka Estate, Surulere	15
3, Biney Street, Off Ojuelegba Raod, Surulere	16
24, Akinhanmi Street Off Fashoro Street, Surulere	17
11, Fagbero Square, Surulere	18
21, Akerele Street, Surulere	19
Beside Heritage Bank Akerele, Surulere	20
5, Faro Ojora Close, Off James Robertson Street, Surulere	21
50, James Robertson Street, Off Alhaji Masha Road, Surulere	22
46, Oyekan Street, Off Alhaji Masha Road, Surulere	23
42, Oyekan Street Off Ogunlana Drive, Surulere	24
16, Oyekan Street, Off Alhaji Masha Road, Surulere	
113, Alhaji Masha Road, Surulere	
5, Adedapo Street, Off Awonaike Street, Surulere	27
11, Alade Close Off Adeniran Ogunsanya, Surulere	
44, Adeniran Ogunsanya, Surulere	
Corner Piece Of Tafa Balewa Crescent And Adeniran Ogunsanya, Surulere	30
43, Tafa Balewa Crescent Off Adeniran Ogunsanya, Surulere	31
43, Tafa Balewa Crescent Off Adeniran Ogunsanya, Surulere	32
61, Tafa Balewa Off Adeniran Ogunsanya, Surulere	33
36, Tafa Balewa Crescent Off Adeniran Ogunsanya, Surulere	34
2, Tafa Balewa Crescent Off Adeniran Ogunsanya, Surulere	
4, Laboye Layele Close Off Adeniran Ogunsanya, Surulere	36
5, Laboye Layele Close Off Adeniran Ogunsanya, Surulere	
17, Tafa Balewa Crescent Off Adeniran Ogunsanya, Surulere	
Corner Piece Of Modupe Johnson And Adeniran Ogunsanya, Surulere	39
Property Beside Ventage High School, Jalupon Street Off Adeniran Ogunsanya, Surulere	
6, Jalupon Close Off Adeniran Ogunsanya Road, Surulere	
71, Adeniran Ogunsanya Road, Surulere	
94, Adeniran Ogunsanya Road, Surulere	
26, Modupe Johnson Crescent, Off Adeniran Ogunsanya, Surulere	
84, Bode Thomas Road, Surulere	
8, Amosun Street, Off Bode Thomas Road, Surulere	
18, Amosun Street Off Bode Thomas, Surulere	47
4, Kernel Street, Off Amosun Street, Bode Thomas, Surulere	
21, Amosun Street, Off Bode Thomas, Surulere	
Property Beside Itolo High School Off Bode Thomas, Surulere	
3, Itolo Street, Off Bode Thomas, Surulere	
12, Johnson Street, Off Bode Thomas, Surulere	
7, Bode Thomas Street, Surulere	
7, Animashaun Bode Thomas Street, Surulere	
PPP Eric More Road, Surulere	
21, Eric More Close Off, Eric Moore Road, Surulere	
6A, Pilot Close, Off Bode Thomas, Surulere	
9, Pilot Close, Off Bode Thomas, Surulere	

3, Pilot Close, Off Bode Thomas, Surulere	
11, Sabiu Ajose Street, Off Adeniran Ogunsanya, Surulere	60
18, Oseni Close, Off Adeniran Ogunsanya, Surulere	61
16, Oseni Close, Off Adeniran Ogunsanya, Surulere	62
76, Modupe Johnson, Off Adeniran Ogunsanya, Surulere	63
138, Akerele Street, Surulere	64
45, Randle Avenue, Off Akerele Road, Surulere	65
43, Akerele Street, Surulere	66
132, Ogunlana Drive, Surulere	67
98, Ogunlana Drive, Surulere	68
136, Ogunlana Drive, Surulere	69
125, Ogunlana Drive, Surulere	70
124, Ogunlana Drive, Surulere	71
114, Ogunlana Drive, Surulere	72
101, Ogunlana Drive, Surulere	73
83, Ogunlana Drive, Surulere	
78, Ogunlana Drive, Surulere	
73, Ogunlana Drive, Surulere	76
64, Ogunlana Drive, Surulere	
33, Itire Road, Surulere	
23, Itire Road, Surulere	
Corner Piece Of Ibidun And Itire Road, Surulere	80
50a, Karimu Street, Off Ojuelegbea Road, Surulere	
20, Ayilara Street, Off Ojuelegbea Road, Surulere	
14, Ayilara Street, Off Ojuelegbea Road, Surulere	
13, Ayilara Street, Off Cole Street, Surulere	
6, Clegg Street Off Ojulegba Road, Surulere	
53, Olukole Street, Off Olufemi Road, Surulere	
25, Ajao Road, Off Olufemi Road, Surulere	
70, Ajao Road, Off Olufemi Road, Surulere	
1, Rasaq Balogun Street, Off Adebola Street, Surulere	
9, Augusto Close, Off Rasaq Balogun Street, Surulere	90
67, Rasaq Balogun Street, Off Adebola Street, Surulere	91
48, Rasaq Balogun Street, Off Adebola Street, Surulere	92
35, Adebola Street, Off Adeniran Ogunsanya Street, Surulere	93
33, Ishaga Road, Off Itire Road, Surulere	94
28, Mabo Street, Surulere	
Corner Piece Of Mabo And Apena, Surulere	
19, Apena Street Off Mabo, Surulere	97
13, Apena Street Off Mabo, Surulere	98
51, Haastrup Street, Off Cole Street, Surulere	99
64, Haastrup Street, Off Cole Street, Surulere	
106, Ibidun Off Western Avenue, Surulere	101
9, Abeo Street Off Western Avenue, Surulere	102
97, Western Avenue, Surulere	103
64, Ayilara Street, Off Cole Street, Surulere	104
13, Karimu Street, Off Cole Street, Surulere	105
11, Karimu Street, Off Cole Street, Surulere	106
18, Karimu Street, Off Cole Street, Surulere	107
4, Mathew Street, Off Ojuelegba Road, Surulere	108
39, Tejuosho Road, Surulere	
29, Olajuwon Street, Off Tejuosho Road, Surulere	
3/5 Ajibola Street, Off Ojuelegba Road, Surulere	
23, Western Avenue, Ojuelegba, Surulere	112
Summary Of The Datas Collated For This Study	

LAGOS STATE BUILDING CONTROL AGENCY COMPENDIUM OF VACANT SITES IN LAGOS STATE

S/N	LOCATION	LGA/LCDA	STAGE OF WORK	LAND APPROVAL/TITLE	DATE	REMARKS
1.	11, ALADE CLOSE OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
2.	BESIDE HERITAGE BANK AKERELE	SURULERE	VACANT	NIL	23/09/2022	
3.	21, AKERELE STREET	SURULERE	VACANT	NIL	23/09/2022	
4.	50, JAMES ROBERTSON STREET, OFF ALHAJI MASHA ROAD	SURULERE	VACANT	NIL	23/09/2022	
5.	46, OYEKAN STREET, OFF ALHAJI MASHA ROAD	SURULERE	VACANT	NIL	23/09/2022	
6.	16, OYEKAN STREET, OFF ALHAJI MASHA ROAD	SURULERE	VACANT	NIL	23/09/2022	
7.	44, ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
8.	CORNER PIECE OF TAFA BALEWA CRESCENT AND ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
9.	43, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
10.	36, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
11.	2, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
12.	4, LABOYE LAYELE CLOSE OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
13.	94, ADENIRAN OGUNSANYA STREET	SURULERE	VACANT	NIL	29/09/2022	
14.	PROPERTY BESIDE ITOLO HIGH SCHOOL OFF BODE THOMAS	SURULERE	VACANT	NIL	29/09/2022	
15.	7, BODE THOMAS STREET	SURULERE	VACANT	NIL	29/09/2022	
16.	7, ANIMASHAUN BODE THOMAS STREET	SURULERE	VACANT	NIL	29/09/2022	
17.	11, SABIU AJOSE STREET, OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
18.	76, MODUPE JOHNSON, OFF ADENIRAN OGUNSANYA	SURULERE	VACANT	NIL	29/09/2022	
19.	124, OGUNLANA DRIVE	SURULERE	VACANT	NIL	29/09/2022	
20.	101, OGUNLANA DRIVE	SURULERE	VACANT	NIL	29/09/2022	
21.	83, OGUNLANA DRIVE	SURULERE	VACANT	NIL	29/09/2022	
22.	CORNER PIECE OF IBIDUN AND ITIRE ROAD	SURULERE	VACANT	NIL	29/09/2022	
23.	13, AYILARA STREET, OFF COLE STREET	SURULERE	VACANT	NIL	29/09/2022	
24.	28, MABO STREET	SURULERE	VACANT	NIL	04/10/2022	
25.	19, APENA STREET OFF MABO	SURULERE	VACANT	NIL	04/10/2022	
26.	13, APENA STREET OFF MABO	SURULERE	VACANT	NIL	04/10/2022	
27.	51, HAASTRUP STREET, OFF COLE STREET	SURULERE	VACANT	NIL	04/10/2022	
28.	64, HAASTRUP STREET, OFF COLE STREET	SURULERE	VACANT	NIL	04/10/2022	
29.	97, WESTERN AVENUE	SURULERE	VACANT	NIL	04/10/2022	
30.	64, AYILARA STREET, OFF COLE STREET	SURULERE	VACANT	NIL	04/10/2022	
31.	13, KARIMU STREET, OFF COLE STREET	SURULERE	VACANT	NIL	04/10/2022	
32.	18, KARIMU STREET, OFF COLE STREET	SURULERE	VACANT	NIL	04/10/2022	

LAGOS STATE BUILDING CONTROL AGENCY

COMPENDIUM OF ABANDONED STRUCTURES IN LAGOS STATE

1. 61, TAFA BALEWA OFF ADENIRAN OGUNSANYA 2. 5, LABOYE LAYELE CLOSE OF ADENIRAN OGUNSANYA 3. CORNER PIECE OF MODUPE JOHNSON AND ADENIRAN OGUNSANYA 4. PROPERTY BESIDE VENTAGE HIGH SCHOOL, JALUPON STREET OFF ADENIRAN OGUNSANYA 5. 12, JOHNSON STREET, OFF BODE THOMAS SURULERE ABANDON NIL NIL 29/09/2022 ABANDON NIL NIL 29/09/2022 29/09/2022 ABANDON NIL NIL 29/09/2022 29/09/2022 29/09/2022 29/09/2022 29/09/2022	REMARKS
OFF ADENIRAN OGUNSANYA 3. CORNER PIECE OF MODUPE JOHNSON AND ADENIRAN OGUNSANYA 4. PROPERTY BESIDE VENTAGE HIGH SCHOOL, JALUPON STREET OFF ADENIRAN OGUNSANYA 5. 12, JOHNSON STREET, OFF BODE THOMAS SURULERE ABANDON NIL NIL 29/09/2022 29/09/2022 ABANDON NIL NIL 29/09/2022 29/09/2022	
MODUPE JOHNSON AND ADENIRAN OGUNSANYA 4. PROPERTY BESIDE VENTAGE HIGH SCHOOL, JALUPON STREET OFF ADENIRAN OGUNSANYA 5. 12, JOHNSON STREET, OFF BODE THOMAS 6. 33, ITIRE ROAD, SURULERE ABANDON NIL NIL NIL 29/09/2022	
VENTAGE HIGH SCHOOL, JALUPON STREET OFF ADENIRAN OGUNSANYA 5. 12, JOHNSON STREET, OFF BODE THOMAS 6. 33, ITIRE ROAD, SURULERE ABANDON NIL NIL SURULERE ABANDON NIL NIL 29/09/2022	
6. 33, ITIRE ROAD, SURULERE ABANDON NIL NIL 29/09/2022	
SURULERE	
7. 23, ITIRE ROAD, SURULERE ABANDON NIL NIL 29/09/2022	
SURULERE	
8. 1, RASAQ BALOGUN STREET, OFF ADEBOLA STREET STREET STREET SURULERE ABANDON NIL NIL 30/09/2022	
9. 98, OGUNLANA DRIVE SURULERE ABANDON NIL NIL 29/09/2022	
10.	

LAGOS STATE BUILDING CONTROL AGENCY

COMPENDIUM OF STRUCTURES UNDERGOING RENOVATION AND REMODELLING WORKS IN LAGOS STATE

S/N	LOCATION/ADDRESS	LGA/LCDA	DESCRIPTION	STAGE OF	DEVELOPMENT	AUTHORIZATION	PICTURES	DATE	REMARKS
			OF PROPERTY	WORK	PERMIT STATUS	STATUS			
1.	18, AMOSUN STREET OFF BODE THOMAS	SURULERE	TWO FLOOR STRUCTURE	RENOVATION				29/09/2022	
2.	6, CLEGG STREET OFF OJULEGBA ROAD	SURULERE	THREE FLOOR STRUCTURE	REMODELLING				29/09/2022	
3.	70, AJAO ROAD OFF OLUFEMI STREET	SURULERE	TWO FLOOR STRUCTURE	REMODELLING	DCB/Do/PROV/3 95/SL	LASBCA/SLR/22/SC060	**************************************	30/09/2022	UNDER STAGE
4.	9, AUGUSTO CLOSE, OFF RASAQ BALOGUN STREET	SURULERE	TWO FLOOR STRUCTURE	REMODELLING	DCB/Do/PROV/2 48/SL	LASBCA/SLR/22/SC/03		30/09/2022	
5.	35, ADEBOLA STREET, OFF ADENIRAN OGUNSANYA STREET	SURULERE	BUNGALOW	REMODELLING				30/09/2022	
6.	64, OGUNLANA DRIVE	SURULERE	TWO FLOOR STRUCTURE	RENOVATION				29/09/2022	
7.	CORNER PIECE OF MABO AND APENA	SURULERE	THREE FLOOR STRUCTURE	REMODELLING				29/09/2022	
8.	23, WESTERN AVENUE, OJUELEGBA	SURULERE	TWO FLOOR STRUCTURE	REMODELLING				29/09/2022	
9.	23, WESTERN AVENUE, OJUELEGBA	SURULERE	TWO FLOOR STRUCTURE	REMODELLING		LASBCA/SLR/22/SC048		29/09/2022	
10.									

LAGOS STATE BUILDING CONTROL AGENCY

COMPENDIUM OF STRUCTURES UNDER CONSTRUCTION IN LAGOS STATE

S/N	LOCATION/ADDRESS	LGA/LCDA	DESCRIPTION OF PROPERTY	STAGE OF WORK	DEVELOPMENT PERMIT STATUS	AUTHORIZATION STATUS	STAGE CERTIFICATION (IF ANY)	REMARKS
1.	21, ERIC MORE CLOSE OFF, ERIC MOORE ROAD	SURULERE	UNDER CONSTRUCTION	GROUND SLAB	LASBCA/SLR/22/S LO49		UNDER STAGE	IN PROGRESS
2.	39, OWUKORI CRESCENT ALAKA ESTATE	SURULERE	UNDER CONSTRUCTION	PILE CAP	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
3.	TWO SEPARATE STRUCTURE AT OGHOETOMAU ALAKA ESTATE	SURULERE	TWO FLOOR	FINISHING STAGE	NO EVIDENCE OF PERMIT	NO EVIDENCE OF AUTHORIZATION	NIL	UNDER SEAL
4.	THREE SEPARATE STRUCTURE AT OGHOETOMAU ALAKA ESTATE	SURULERE	THREE FLOOR	FINISHING STAGE	NO EVIDENCE OF PERMIT	NO EVIDENCE OF AUTHORIZATION	NIL	UNDER SEAL
5.	26 MODUPE JOHNSON CRESCENT, SURULERE	SURULERE	TWO FLOOR	FINISHING STAGE	DCB/DO/767/SL	LASBCA/SLR/SC/ O ₃₄	UNDER STAGE	IN PROGRESS
6.	3, BINEY STREET, OFF OJUELEGBA RAOD	SURULERE	UNDER CONSTRUCTION	FIRST FLOOR SUSPENDED SLAB	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
7.	24, AKINHANMI STREET OFF FASHORO STREET	SURULERE	UNDER CONSTRUCTION	FIRST SUSPENDED SLAB	YET TO BE OBTAINED	YET TO BE OBTAINED	NIL	CN SERVED
8.	11, FAGBERO SQUARE	SURULERE	UNDER CONSTRUCTION	GROUND BEAM	DCB/DO/825/SL	LASBCA/SLR/22/ SC/059	UNDER STAGE	IN PROGRESS
9.	5, FARO OJORA CLOSE, OFF JAMES ROBERTSON STREET	SURULERE	UNDER CONSTRUCTION	GROUND FLOOR LINTEL LEVEL	DCB/DO/822/SL	LASBCA/SLR/22/ SC054	NIL	IN PROGRESS
10.	42, OYEKAN STREET OFF OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	GROUND FLOOR COLUMN	DCB/DO/PROV/SL	LASBCA/SLR/22/ SC055	UNDER STAGE	IN PROGRESS
11.	45, RANDLE AVENUE, OFF AKERELE ROAD	SURULERE	UNDER CONSTRUCTION	FOUNDATION BEAM	DCB/DO/296/SL	LASBCA/SLR/22/ Sc050	UNDER STAGE	IN PROGRESS
12.	5, ADEDAPO STREET, OFF AWONAIKE STREET	SURULERE	TWO FLOOR	FIRST SUSPENDED LINTEL LEVEL	DCB/DO/PROV/29 9/SL	LASBCA/SLR/22/ SC024	UNDER STAGE	IN PROGRESS
13.	113, ALHAJI MASHA ROAD	SURULERE	TWO FLOOR	ROOF BEAM			NIL	UNSEALED / PENAL PAID
14.	6, JALUPON CLOSE OFF ADENIRAN OGUNSANYA ROAD	SURULERE	UNDER CONSTRUCTION	SECOND SUSPENDED FLOOR BLOCK SETTING ON- GOING	DCB/DOPROV/22 5/SL	LASBCA/SLR/22/ SC/0 10	UNDER STAGE	IN PROGRESS
15.	71, ADENIRAN OGUNSANYA ROAD	SURULERE	UNDER CONSTRUCTION	FIRST SUSPENDED COLUMN	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS

16.	84, BODE THOMAS ROAD	SURULERE	UNDER CONSTRUCTION	ROOF PARAPET ON-GOING	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
17.	8, AMOSUN STREET, OFF BODE THOMAS ROAD	SURULERE	UNDER CONSTRUCTION	GROUND FLOOR COLUMN RAINFORCEMENT	YET TO BE OBTAINED	YET TO BE OBTAINED	NIL	IN PROGRESS
18.	4, KERNEL STREET, OFF AMOSUN STREET, BODE THOMAS	SURULERE	TWO FLOOR	FINISHING STAGE	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE	IN PROGRESS
19.	21, AMOSUN STREET, OFF BODE THOMAS	SURULERE	THREE FLOOR	FINISHING STAGE	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	IN PROGRESS
20.	3, ITOLO STREET, OFF BODE THOMAS	SURULERE	UNDER CONSTRUCTION	GROUND BEAM	DCB/DO/776/SL	LASBCA/SLR/22/ SC011	UNDER STAGE	IN PROGRESS
21.	PPP ERIC MORE ROAD	SURULERE	UNDER CONSTRUCTION	THIRD SUSPENDED FLOOR COLUMN	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
22.	9, PILOT CLOSE, OFF BODE THOMAS	SURULERE	TWO FLOOR	FINISHING STAGE	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE	IN PROGRESS
23.	6A, PILOT CLOSE, OFF BODE THOMAS	SURULERE	TWO FLOOR	ROOF	DCB/Do/PROV/26 3/SL	LASBCA/SLR/21/S C042	UNDER STAGE	IN PROGRESS
24.	3, PILOT CRESCENT, OFF BODE THOMAS	SURULERE	UNDER CONSTRUCTION	FIRST FLOOR SLAB	DCB/Do/PROV/08 2/SL	LASBCA/SLR/22/ SC005	UNDER STAGE	IN PROGRESS
25.	18, OSENI CLOSE, OFF ADENIRAN OGUNSANYA	SURULERE	UNDER CONSTRUCTION	GROUND FLOOR COLUMN	DCB/DO/834/SL	LASBCA/SLR/22/ SC068	UNDER STAGE	IN PROGRESS
26.	16, OSENI CLOSE, OFF ADENIRAN OGUNSANYA	SURULERE	THREE FLOOR	ROOF BEAM	DCB/DO/PROV/ 320/SL	LASBCA/SLR/22/ SC/025	UNDER STAGE	IN PROGRESS
27.	138, AKERELE STREET	SURULERE	UNDER CONSTRUCTION	FIRST SUSPENDED FLOOR BLOCK SETTING	DCB/DO/818/SL	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
28.	43, AKERELE STREET	SURULERE	TWO FLOOR	ROOF	DCB/DO/701/SL		UNDER STAGE	IN PROGRESS
29.	78, OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	FIRST SUSPENDED FLOOR COLUMN	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
30.	73, OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	FLAT ROOF COMPLETED	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
31.	136, OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	SECOND SUSPENDED FLOOR LINTEL LEVEL	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
32.	125, OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	SECOND SUSPENDED SLAB	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
33.	114, OGUNLANA DRIVE	SURULERE	THREE FLOOR	FINISHING LEVEL	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	IN PROGRESS

34.	132, OGUNLANA DRIVE	SURULERE	UNDER CONSTRUCTION	ROOF PARAPET	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
35.	50A, KARIMU STREET, OFF OJUELEGBEA ROAD	SURULERE	UNDER CONSTRUCTION	ROOF COMPLETED	YET TO BE OBTAINED	YET TO BE OBTAINED	NIL	UNDER SEAL
36.	20, AYILARA STREET, OFF OJUELEGBEA ROAD	SURULERE	UNDER CONSTRUCTION	SECOND SUSPENDED FLOOR CAST COMPLETED	YET TO BE OBTAINED	YET TO BE OBTAINED	NIL	UNDER SEAL
37•	14, AYILARA STREET, OFF OJUELEGBEA ROAD	SURULERE	FOUR FLOOR	FINISHES STAGE	DCB/Do/PROV/217 /SL	LASBCA/SLR/SC/ 025	UNDER STAGE	IN PROGRESS
38.	53, OLUKOLE STREET, OFF OLUFEMI ROAD	SURULERE	UNDER CONSTRUCTION	GROUND BEAM	DCB/Do/84o/SL		NOT STAGE	IN PROGRESS
39.	25, AJAO ROAD, OFF OLUFEMI ROAD	SURULERE	UNDER CONSTRUCTION	ERECTION OF STEEL STANCHION	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	UNDER SEAL
40.	67, RASAQ BALOGUN STREET, OFF ADEBOLA STREET	SURULERE	TWO FLOOR	FINISHES LEVEL	DCB/Do/PROV/25 o/SL	LASBCA/SLR/SC OO ₇	UNDER STAGE	IN PROGRESS
41.	48, RASAQ BALOGUN STREET, OFF ADEBOLA STREET	SURULERE	UNDER CONSTRUCTION	ROOF	DCB/Do/827/SL	LASBCA/SLR/22/ SC/040	UNDER STAGE	IN PROGRESS
42.	33, ISHAGA ROAD, OFF ITIRE ROAD	SURULERE	UNDER CONSTRUCTION	FIRST SUSPENDED SLAB	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	CN AND SW SERVED
43.	106, IBIDUN OFF WESTERN AVENUE	SURULERE	UNDER CONSTRUCTION	FIRST FLOOR SUSPENDED BLOCK WALL	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	UNDER SEAL
44.	9, ABEO STREET OFF WESTERN AVENUE	SURULERE	UNDER CONSTRUCTION	FIRST FLOOR SUSPENDED COLUMN	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	UNDER SEAL
45.	11, KARIMU STREET, OFF COLE STREET	SURULERE	UNDER CONSTRUCTION	FINISHING LEVEL	DCB/Do/PROV/35 5/SL	LASBCA/SLR/22/ SC058	UNDER STAGE	IN PROGRESS
46.	4, MATHEW STREET, OFF OJUELEGBA ROAD	SURULERE	UNDER CONSTRUCTION	SECOND SUSPENDED FLOOR COLUMN	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
47.	39, TEJUOSHO ROAD	SURULERE	UNDER CONSTRUCTION	PARAPET WALL COMPLETED	YET TO BE OBTAINED	YET TO BE OBTAINED	UNDER STAGE BY CENTRAL	IN PROGRESS
48.	29, OLAJUWON STREET, OFF TEJUOSHO ROAD	SURULERE	UNDER CONSTRUCTION	FOURTH FLOOR SLAB	DCB/Do/671/SL	LASBCA/SLR/22/ SC/033	UNDER STAGE	IN PROGRESS
49.	3/5 AJIBOLA STREET, OFF OJUELEGBA ROAD	SURULERE	UNDER CONSTRUCTION	FOUNDATION BASEMENT	YET TO BE OBTAINED	YET TO BE OBTAINED	NOT STAGE	CN SERVED

INTRODUCTION

LAGOS STATE IN THE NATIONAL CONTEXT

Lagos State (Yoruba: Ìpínlè Èkó) is a state in southwestern Nigeria. Of the 36 states, it is both the most populous and smallest in area. Bounded to the south by the Bight of Benin and to the west by the international border with Benin Republic, Lagos State borders Ogun State to the east and north making it the only Nigerian state to border only one other state. Named for the city of Lagos the most populous city in Africa—the state was formed from the Western Region and the former Federal Capital Territory on 27 May 1967.

Geographically, Lagos State is dominated by bodies of water with nearly a quarter of the state's area being lagoons, creeks, and rivers. The largest of these bodies are the Lagos and Lekki lagoons in the state's interior with the Ogun and Osun rivers flowing into them. Many other rivers and creeks flow throughout the state and serve as vital means of transportation for people and goods. On land, non-urbanized areas are within the tropical Nigerian lowland forests eco region with natural areas containing threatened populations of mona monkey, tree pangolin, and hooded vulture along with a transitory population of African bush elephants. Offshore, the state is also biodiversity as there are large fish populations along with African manatees and crocodiles.

Lagos State has been inhabited for years by various indigenous ethnic groups, primarily the majority Yoruba people that live throughout the state but also the Ewe and Ogu peoples in the far west. As a result of migration since the nineteenth century, Lagos State also has large populations of non-native Nigerian ethnic groups with Edo, Fulani, Hausa, Igbo, Ijaw, Ibibio, and Nupe peoples among other Nigerian groups. There are also groups from outside of Nigeria's modern borders with the Saro (Sierra Leonean) and Amaro (Brazilian) groups being descendants of formerly enslaved people that returned to Africa in the 1800s with a longstanding Middle Eastern Nigerian community (mainly Syrian and Lebanese Nigerians)also forming a significant part of Lagos' population along with recent immigrants from Benin Republic, China, Ghana, India, Togo, and the United Kingdom. Religiously the state is also diverse as about 55% of the state's population are Christian with around 40% being Muslim and the remaining 5% following traditional ethnic religions or other religions

BRIEF HISTORY ON SURULERE

Surulere local government area is one of the twenty LGAs found in Lagos state, South-west geopolitical zone of Nigeria. The LGA comprises of several districts which include Ojuelegba, Shitta, Ogunlana, Orile, Ikate, Ibire, Adeniran, Ogunsanya, and Gbaja. The current estimated population of Surulere LGA is put at 645,713 inhabitants with the LGA hosting members of several ethnic groups. The Yoruba language is commonly spoken in Surulere LGA while the religions of Islam and Christianity are widely practiced in the area. Notable landmarks in Surulere LGA include the National Sports Stadium, Lagos, the Teslim Balogun Stadium, and the National Arts Theatre.

Surulere is a residential and commercial Local Government Area located on the mainland of Lagos in Lagos State, Nigeria, with an area of 23 km2 (8.9 sq mi). At the last census in the year 2006, there were 503,975 inhabitants, with a population density of 21,864 inhabitants per square kilometer. The local government area is bordered by Yaba, Mushin and Ebute-Metta.

GEOGRAPHY OF SURULERE

Surulere LGA occupies a total area of 23 square kilometres and has an average temperature of 26 degrees centigrade. The total precipitation in the LGA is put at 2550 mm of rainfall per annum while the average humidity level in the area is put at 69 percent.

ECONOMY OF SURULERE

Surulere LGA is in an ultra-cosmopolitan area of the Lagos city and hosts several financial institutions, hotels, relaxation spots, eateries, schools, as well as government owned enterprises with all these contributing to the economy of the LGA. The LGA also has a vibrant trade sector and hosts a number of markets such as the Tejuosho and Idi Araba markets which provide platforms for the exchange of a variety of goods and services.

AIM AND OBJECTIVES OF THIS STUDY


AIM

The aim of this project is to appraise the existing On-going Construction, Renovation/Remodelling and Vacant Pilot at different locations within the scope limit of the district and identify the abnormalities of the properties for probable solution.

OBJECTIVES


- To help ensure that there is orderliness in the allocation of land for the various elements that makes a religious property.
- · Ensure that proper planning standards are adhered to within the vicinity
 - To ensure that there is compatibility between the elements that constitutes the overall land use.

MAP OF NIGERIA SHOWING LAGOS STATE IN A NATIONAL CONTEXT




SOURCE: GOOGLE PHOTOS, 2022


MAP OF LAGOS STATE SHOWING SURULERE











LOCATION/ADDRESS 39, OWUKORI CRESCENT ALAKA ESTATE SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK PILE CAP

DEVELOPMENT YET TO BE OBTAINED

AUTHORIZATION YET TO BE OBTAINED

REMARKS UNDER STAGE BY CENTRAL

Network: Sep 20, 2022 12:17:55 PM GMT+01:00 Local: Sep 20, 2022 12:17:54 PM GMT+01:00 6°29'39.03"N 3°21'55.02"E

Owukori Cresceni Surulere

Lagos



LOCATION/ADDRESS

TWO SEPARATE STRUCTURE AT OGHOETOMAU ALAKA ESTATE, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

FINISHING STAGE

DEVELOPMENT PERMIT STATUS

NO EVIDENCE OF PERMIT

AUTHORIZATION STATUS

NO EVIDENCE OF AUTHORIZATION

REMARKS

UNDER SEAL

Network: Sep 20, 2022 12:17:43 PM GMT+01:00 Local: Sep 20, 2022 12:17:42 PM GMT+01:00 6°29'39,144"N 3°21'54,792"E 99 Owukori Crescent

Surulere Lagos



LOCATION/ADDRESS THR

THREE SEPARATE STRUCTURE AT OGHOETOMAU ALAKA ESTATE, SURULERE

DESCRIPTION OF PROPERTY

THREE FLOOR

STAGE OF WORK

FINISHING STAGE

DEVELOPMENT PERMIT STATUS

NO EVIDENCE OF PERMIT

AUTHORIZATION STATUS


NO EVIDENCE OF AUTHORIZATION

REMARKS

UNDER SEAL




LOCATION/ADDRES	3, BINEY STREET, OFF OJUELEGBA RAOD, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	FIRST FLOOR SUSPENDED SLAB
DEVELOPMENT PERMIT STATUS	YET TO BE OBTAINED
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	UNDER STAGE BY CENTRAL



DESCRIPTION OF UNDER CONSTRUCTION STAGE OF WORK FIRST SUSPENDED SLAB DEVELOPMENT YET TO BE OBTAINED AUTHORIZATION YET TO BE OBTAINED REMARKS CN SERVED



LOCATION/ADDRES	11, FAGBERO SQUARESURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	GROUND BEAM
DEVELOPMENT PERMIT STATUS	DCB/D0/825/SL
AUTHORIZATION STATUS	LASBCA/SLR/22/SC/059
REMARKS	UNDER STAGE



LOCATION/ADDRESS 21, AKERELE STREET, SURULERE


DESCRIPTION OF PROPERTY VACANT

STAGE OF WORK VACANT

DEVELOPMENT PERMIT STATUS NIL

AUTHORIZATION NIL

REMARKS NIL



LOCATION/ADDRESS

BESIDE HERITAGE BANK AKERELE, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL

Network: Sep 23, 2022 11:32:21 AM GMT+01:00 Local: Sep 23, 2022 11:32:20 AM GMT+01:00 6°30'14.61''N 3°21'10.158''E 3 Faro Ojora Close Surulere Lagos



LOCATION/ADDRESS

5, FARO OJORA CLOSE, OFF JAMES ROBERTSON STREET, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

GROUND FLOOR LINTEL LEVEL

DEVELOPMENT PERMIT STATUS


DCB/D0/822/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC054

REMARKS

NOT STAGE



LOCATION/ADDRESS 50, JAMES ROBERTSON STREET, OFF ALHAJI MASHA ROAD, SURULERE


DESCRIPTION OF PROPERTY VACANT

STAGE OF WORK VACANT

DEVELOPMENT NIL

AUTHORIZATION NIL

REMARKS NIL



LOCATION/ADDRESS 46, OYEKAN STREET, OFF ALHAJI MASHA ROAD, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS

42, OYEKAN STREET OFF OGUNLANA DRIVE, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

GROUND FLOOR COLUMN

DEVELOPMENT PERMIT STATUS

DCB/DO/PROV/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC055

REMARKS

UNDER STAGE



LOCATION/ADDRESS 16, OYEKAN STREET, OFF ALHAJI MASHA ROAD, SURULERE DESCRIPTION OF PROPERTY VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS 113, ALHAJI MASHA ROAD, SURULERE DESCRIPTION OF TWO FLOOR STAGE OF WORK ROOF BEAM DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL REMARKS UNSEALED / PENAL PAID

Network: Sep 23, 2022 1:19:03 PM GMT+01:00 Local: Sep 23, 2022 1:19:01 PM GMT+01:00 6°30'18.228"N 3°22'2.412"E





LOCATION/ADDRESS

5, ADEDAPO STREET, OFF AWONAIKE STREET, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

FIRST SUSPENDED LINTEL LEVEL

DEVELOPMENT PERMIT STATUS

DCB/DO/PROV/299/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC024

REMARKS

UNDER STAGE



LOCATION/ADDRESS

11, ALADE CLOSE OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS


NIL

REMARKS

NIL



LOCATION/ADDRESS 44, ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF PROPERTY STAGE OF WORK VACANT DEVELOPMENT PERMIT STATUS NIL REMARKS NIL



LOCATION/ADDRESS CORNER PIECE OF TAFA BALEWA CRESCENT AND ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL

REMARKS


NIL



LOCATION/ADDRESS 43, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS 43, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS

61, TAFA BALEWA OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

ABANDON

STAGE OF WORK

ABANDON

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL




LOCATION/ADDRESS 36, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS 2, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL NIL

REMARKS

NIL



LOCATION/ADDRESS 4, LABOYE LAYELE CLOSE OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF PROPERTY VACANT STAGE OF WORK VACANT DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL REMARKS NIL



LOCATION/ADDRESS	5, LABOYE LAYELE CLOSE OFF ADENIRAN OGUNSANYA, SURULERE
DESCRIPTION OF PROPERTY	ABANDON
STAGE OF WORK	ABANDON
DEVELOPMENT PERMIT STATUS	NIL
AUTHORIZATION STATUS	NIL
REMARKS	NIL



17, TAFA BALEWA CRESCENT OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

BUNGALOW

STAGE OF WORK

REMODELLING

DEVELOPMENT PERMIT STATUS


NIIL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC048

REMARKS


NIL



LOCATION/ADDRESS CORNER PIECE OF MODUPE JOHNSON AND ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF ABANDON STAGE OF WORK ABANDON DEVELOPMENT PERMIT STATUS NIL REMARKS NIL



LOCATION/ADDRESS PROPERTY BESIDE VENTAGE HIGH SCHOOL, JALUPON STREET OFF ADENIRAN OGUNSANYA, SURULERE DESCRIPTION OF PROPERTY ABANDON STAGE OF WORK ABANDON DEVELOPMENT PERMIT STATUS NIL REMARKS NIL



6, JALUPON CLOSE OFF ADENIRAN OGUNSANYA ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

SECOND SUSPENDED FLOOR BLOCK SETTING ON-GOING

DEVELOPMENT PERMIT STATUS


DCB/DO/PROV/225/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC/010

REMARKS

UNDER STAGE



71, ADENIRAN OGUNSANYA ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

FIRST SUSPENDED COLUMN

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



LOCATION/ADDRESS 94, ADENIRAN OGUNSANYA ROAD, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS SEALED



26, MODUPE JOHNSON CRESCENT, OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

FINISHING STAGE

DEVELOPMENT PERMIT STATUS

DCB/D0/767/SL

AUTHORIZATION STATUS

LASBCA/SLR/SC/034

REMARKS

UNDER STAGE

Neiwork: Sep 29, 2022 10:46:38 AM GMT+01:00 Local: Sep 29, 2022 10:46:36 AM GMT+01:00 6°29'24,054"N 3°21'21,828"E 59 Adeniran Ogunsanya Street Surulere



LOCATION/ADDRESS

84, BODE THOMAS ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

ROOF PARAPET ON-GOING

DEVELOPMENT PERMIT STATUS


YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



8, AMOSUN STREET, OFF BODE THOMAS ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTIONG

STAGE OF WORK

ROUND FLOOR COLUMN RAINFORCEMENT

DEVELOPMENT PERMIT STATUS


YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE



LOCATION/ADDRESS

18, AMOSUN STREET OFF BODE THOMAS, SURULERE

DESCRIPTION OF TWO FLOOR STRUCTURE

STAGE OF WORK

RENOVATION

DEVELOPMENT YET TO BE OBTAINED

AUTHORIZATION YET TO BE OBTAINED

REMARKS

NIL



LOCATION/ADDRESS 4, KERNEL STREET, OFF AMOSUN STREET, BODE THOMAS, SURULERE DESCRIPTION OF PROPERTY TWO FLOOR STAGE OF WORK FINISHING STAGE DEVELOPMENT PERMIT STATUS YET TO BE OBTAINED AUTHORIZATION STATUS YET TO BE OBTAINED REMARKS NIL



21, AMOSUN STREET, OFF BODE THOMAS, SURULERE

DESCRIPTION OF PROPERTY

THREE FLOOR

STAGE OF WORK

FINISHING STAGE

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS


NIL

REMARKS

ABANDON



LOCATION/ADDRESS PROPERTY BESIDE ITOLO HIGH SCHOOL OFF BODE THOMAS, SURULERE DESCRIPTION OF PROPERTY VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



3, ITOLO STREET, OFF BODE THOMAS, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

GROUND BEAM

DEVELOPMENT PERMIT STATUS


DCB/D0/776/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC011

REMARKS

UNDER STAGE



12, JOHNSON STREET, OFF BODE THOMAS, SURULERE

DESCRIPTION OF PROPERTY

ABANDON

STAGE OF WORK

ABANDON

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL



7, BODE THOMAS STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS


NIL

REMARKS

NIL



LOCATION/ADDRESS 7, ANIMASHAUN BODE THOMAS STREET, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



PPP ERIC MORE ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

THIRD SUSPENDED FLOOR COLUMN

DEVELOPMENT PERMIT STATUS


YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



LOCATION/ADDRESS	21, ERIC MORE CLOSE OFF, ERIC MOORE ROAD, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	GROUND SLAB
DEVELOPMENT PERMIT STATUS	NIL
AUTHORIZATION STATUS	LASBCA/SLR/22/SL049
REMARKS	UNDER STAGE





6A, PILOT CLOSE, OFF BODE THOMAS, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

FINISHING STAGE

DEVELOPMENT PERMIT STATUS

DCB/DO/PROV/263/SL

AUTHORIZATION STATUS


LASBCA/SLR/21/SC042

REMARKS

UNDER STAGE



DESCRIPTION OF TWO FLOOR STAGE OF WORK ROOF DEVELOPMENT PERMIT STATUS YET TO BE OBTAINED AUTHORIZATION YET TO BE OBTAINED REMARKS UNDER STAGE



LOCATION/ADDRESS

3, PILOT CRESCENT, OFF BODE THOMAS, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK FIRST FLOOR SLAB

DEVELOPMENT DCB/DO/PROV/082/SL

AUTHORIZATION LASBCA/SLR/22/SC005

REMARKS UNDER STAGE



11, SABIU AJOSE STREET, OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL



LOCATION/ADDRESS

18, OSENI CLOSE, OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK

GROUND FLOOR COLUMN

DEVELOPMENT DCB/DO/834/SL

AUTHORIZATION LASBCA/SLR/22/SCO68

REMARKS

UNDER STAGE



DESCRIPTION OF THREE FLOOR PROPERTY STAGE OF WORK ROOF BEAM DEVELOPMENT DCB/DO/PROV/320/SL **PERMIT STATUS AUTHORIZATION** LASBCA/SLR/22/SC/025 **STATUS** REMARKS



76, MODUPE JOHNSON, OFF ADENIRAN OGUNSANYA, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS

NIL

REMARKS


NIL



LOCATION/ADDRESS	138, AKERELE STREET, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	FIRST SUSPENDED FLOOR BLOCK SETTING
DEVELOPMENT PERMIT STATUS	DCB/D0/818/SL
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	UNDER STAGE BY CENTRAL



LOCATION/ADDRESS 45, RANDLE AVENUE, OFF AKERELE ROAD, SURULERE DESCRIPTION OF UNDER CONSTRUCTION STAGE OF WORK FOUNDATION BEAM DEVELOPMENT PERMIT STATUS DCB/DO/296/SL AUTHORIZATION LASBCA/SLR/22/SC050 REMARKS UNDER STAGE



43, AKERELE STREET, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

ROOF

DEVELOPMENT PERMIT STATUS

DCB/D0/701/SL

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE



LOCATION/ADDRESS

132, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK

ROOF PARAPET


DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED


AUTHORIZATION YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



LOCATION/ADDRESS	98, OGUNLANA DRIVE, SURULERE
DESCRIPTION OF PROPERTY	ABANDON
STAGE OF WORK	ABANDON
DEVELOPMENT PERMIT STATUS	NIL
AUTHORIZATION STATUS	NIL
REMARKS	NIL



136, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

SECOND SUSPENDED FLOOR LINTEL LEVEL

DEVELOPMENT PERMIT STATUS


YET TO BE OBTAINED

AUTHORIZATION STATUS


YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



DESCRIPTION OF UNDER CONSTRUCTION STAGE OF WORK SECOND SUSPENDED SLAB DEVELOPMENT YET TO BE OBTAINED AUTHORIZATION YET TO BE OBTAINED REMARKS UNDER STAGE BY CENTRAL



124, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL


REMARKS

NIL





LOCATION/ADDRES	114, OGUNLANA DRIVE, SURULERE
DESCRIPTION OF PROPERTY	THREE FLOOR
STAGE OF WORK	FINISHING LEVEL
DEVELOPMENT PERMIT STATUS	YET TO BE OBTAINED
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	NOT STAGE



101, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL



LOCATION/ADDRESS 83, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF VACANT

STAGE OF WORK VACANT

DEVELOPMENT NIL

AUTHORIZATION NIL

REMARKS NIL



LOCATION/ADDRESS

78, OGUNLANA DRIVE, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK

FIRST SUSPENDED FLOOR COLUMN

DEVELOPMENT DCB/DO/823/SL

AUTHORIZATION YET TO BE OBTAINED


REMARKS

UNDER STAGE BY CENTRAL





LOCATION/ADDRES	73, OGUNLANA DRIVE, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	FLAT ROOF COMPLETED
DEVELOPMENT PERMIT STATUS	YET TO BE OBTAINED
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	UNDER STAGE BY CENTRAL



64, OGUNLANA DRIVESURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR STRUCTURE

STAGE OF WORK

GENERAL RENOVATION

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

NIL



LOCATION/ADDRES	33, ITIRE ROAD, SURULERE
DESCRIPTION OF PROPERTY	ABANDON
STAGE OF WORK	ABANDON
DEVELOPMENT PERMIT STATUS	NIL
AUTHORIZATION STATUS	NIL
REMARKS	NIL

Neiwork: Sep 29, 2022 12:27:13 PM GMT+01:00 Local: Sep 29, 2022 12:27:11 PM GMT+01:00 6°30'43.218"N 3°21'27.3"E 87 Ojuelegba Road Surulere



LOCATION/ADDRESS

23, ITIRE ROAD, SURULERE

DESCRIPTION OF PROPERTY

ABANDON

STAGE OF WORK

ABANDON

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS


NIL

REMARKS

NIL



LOCATION/ADDRESS CORNER PIECE OF IBIDUN AND ITIRE ROAD, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT NIL AUTHORIZATION NIL REMARKS NIL



50A, KARIMU STREET, OFF OJUELEGBEA ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

ROOF COMPLETED

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS


UNDER SEAL



LOCATION/ADDRESS	20, AYILARA STREET, OFF OJUELEGBEA ROAD, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	SECOND SUSPENDED FLOOR CAST COMPLETED
DEVELOPMENT PERMIT STATUS	YET TO BE OBTAINED
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	UNDER SEAL



LOCATION/ADDRESS 14, AYILARA STREET, OFF OJUELEGBEA ROAD, SURULERE DESCRIPTION OF FOUR FLOOR STAGE OF WORK FINISHES STAGE DEVELOPMENT DCB/DO/PROV/217/SL AUTHORIZATION LASBCA/SLR/SC/025 REMARKS UNDER STAGE



13, AYILARA STREET, OFF COLE STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL



6, CLEGG STREET OFF OJULEGBA ROAD, SURULERE

DESCRIPTION OF PROPERTY

THREE FLOOR STRUCTURE

STAGE OF WORK

REMODELLING

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER SEAL



LOCATION/ADDRESS 53, OLUKOLE STREET, OFF OLUFEMI ROAD, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK GROUND BEAM

DEVELOPMENT DCB/DO/840/SL

AUTHORIZATION YET TO BE OBTAINED

REMARKS NOT STAGE



LOCATION/ADDRESS 25, AJAO ROAD, OFF OLUFEMI ROAD, SURULERE

DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK ERECTION OF STEEL STANCHION

DEVELOPMENT YET TO BE OBTAINED

AUTHORIZATION YET TO BE OBTAINED

REMARKS UNDER SEAL





70, AJAO ROAD, OFF OLUFEMI ROAD, SURULERE

DESCRIPTION OF PROPERTY

TWO FLOOR

STAGE OF WORK

INTRODUCTION OF COLUMN

DEVELOPMENT PERMIT STATUS

DCB/DO/PROV/395/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC060

REMARKS

UNDER STAGE



LOCATION/ADDRESS 1, RASAQ BALOGUN STREET, OFF ADEBOLA STREET, SURULERE DESCRIPTION OF PROPERTY ABANDON STAGE OF WORK ABANDON DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL REMARKS



LOCATION/ADDRESS

9, AUGUSTO CLOSE, OFF RASAQ BALOGUN STREET, SURULERE

DESCRIPTION OF TWO FLOOR STRUCTURE

STAGE OF WORK


REMODELLING

DEVELOPMENT DCB/DO/PROV/248/SL


AUTHORIZATION LASBCA/SLR/22/SC/033

REMARKS

NOT STAGE



LOCATION/ADDRESS 67, RASAQ BALOGUN STREET, OFF ADEBOLA STREET, SURULERE DESCRIPTION OF TWO FLOOR STRUCTURE STAGE OF WORK FINISHES LEVEL DEVELOPMENT DCB/DO/PROV/250/SL AUTHORIZATION LASBCA/SLR/SCOO7 REMARKS UNDER STAGE



LOCATION/ADDRESS

48, RASAQ BALOGUN STREET, OFF ADEBOLA STREET, SURULERE

DESCRIPTION OF TWO FLOOR STRUCTURE

STAGE OF WORK

PLASTERING / FINISHES LEVEL

DEVELOPMENT DCB/DO/827/SL

AUTHORIZATION LASBCA/SLR/22/SC/040

REMARKS

UNDER STAGE



Network: Sep 30, 2022 1:48:43 PM GMT+01:00 Local: Sep 30, 2022 1:48:41 PM GMT+01:00 6°29'49.23"N 3°21'37.548"E 42 Adebola Street Surulere Lagos



LOCATION/ADDRESS

35, ADEBOLA STREET, OFF ADENIRAN OGUNSANYA STREET, SURULERE

DESCRIPTION OF PROPERTY

BUNGALOW

STAGE OF WORK

REMODELLING

DEVELOPMENT PERMIT STATUS


NIL

AUTHORIZATION STATUS

NIL

REMARKS

NIL



33, ISHAGA ROAD, OFF ITIRE ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

FIRST SUSPENDED SLAB

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

CN AND SW SERVED



28, MABO STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



LOCATION/ADDRESS CORNER PIECE OF MABO AND APENA, SURULERE DESCRIPTION OF PROPERTY THREE FLOOR STRUCTURE STAGE OF WORK REMODELLING DEVELOPMENT PERMIT STATUS YET TO BE OBTAINED AUTHORIZATION STATUS YET TO BE OBTAINED REMARKS SITE SEAL



19, APENA STREET OFF MABO, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK


VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



13, APENA STREET OFF MABO, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK


VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



51, HAASTRUP STREET, OFF COLE STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK


VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



64, HAASTRUP STREET, OFF COLE STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK

VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



54 Haastrup Street





LOCATION/ADDRESS

106, IBIDUN OFF WESTERN AVENUE, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

FIRST FLOOR SUSPENDED BLOCK WALL

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS


YET TO BE OBTAINED

REMARKS

UNDER SEAL



LOCATION/ADDRESS 9, ABEO STREET OFF WESTERN AVENUE, SURULERE DESCRIPTION OF UNDER CONSTRUCTION STAGE OF WORK FIRST FLOOR SUSPENDED COLUMN DEVELOPMENT YET TO BE OBTAINED AUTHORIZATION YET TO BE OBTAINED REMARKS UNDER SEAL



LOCATION/ADDRESS 97, WESTERN AVENUE, SURULERE DESCRIPTION OF PROPERTY VACANT STAGE OF WORK VACANT DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL REMARKS



64, AYILARA STREET, OFF COLE STREET, SURULERE

DESCRIPTION OF PROPERTY

VACANT

STAGE OF WORK


VACANT

DEVELOPMENT PERMIT STATUS

NIL

AUTHORIZATION STATUS

NIL



LOCATION/ADDRESS 13, KARIMU STREET, OFF COLE STREET, SURULERE DESCRIPTION OF VACANT STAGE OF WORK VACANT DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL REMARKS



11, KARIMU STREET, OFF COLE STREET, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

FINISHING LEVEL

DEVELOPMENT PERMIT STATUS


DCB/DO/PROV/355/SL

AUTHORIZATION STATUS

LASBCA/SLR/22/SC058

REMARKS


UNDER STAGE




DESCRIPTION OF PROPERTY VACANT STAGE OF WORK VACANT DEVELOPMENT PERMIT STATUS NIL AUTHORIZATION NIL

18, KARIMU STREET, OFF COLE STREET, SURULERE

LOCATION/ADDRESS



LOCATION/ADDRESS	4, MATHEW STREET, OFF OJUELEGBA ROAD, SURULERE
DESCRIPTION OF PROPERTY	UNDER CONSTRUCTION
STAGE OF WORK	SECOND SUSPENDED FLOOR COLUMN
DEVELOPMENT PERMIT STATUS	YET TO BE OBTAINED
AUTHORIZATION STATUS	YET TO BE OBTAINED
REMARKS	UNDER STAGE BY CENTRAL



39, TEJUOSHO ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

PARAPET WALL COMPLETED

DEVELOPMENT PERMIT STATUS


YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

UNDER STAGE BY CENTRAL



LOCATION/ADDRESS 29, OLAJUWON STREET, OFF TEJUOSHO ROAD, SURULERE


DESCRIPTION OF UNDER CONSTRUCTION

STAGE OF WORK FOURTH FLOOR SLAB

DEVELOPMENT DCB/DO/671/SL

AUTHORIZATION LASBCA/SLR/22/SC/033

REMARKS UNDER STAGE



3/5 AJIBOLA STREET, OFF OJUELEGBA ROAD, SURULERE

DESCRIPTION OF PROPERTY

UNDER CONSTRUCTION

STAGE OF WORK

FOUNDATION BASEMENT

DEVELOPMENT PERMIT STATUS

YET TO BE OBTAINED

AUTHORIZATION STATUS

YET TO BE OBTAINED

REMARKS

CN SERVED



LOCATION/ADDRESS

23, WESTERN AVENUE, OJUELEGBA, SURULERE

DESCRIPTION OF TWO FLOOR STRUCTURE

STAGE OF WORK

REMODELLING

DEVELOPMENT YET TO BE OBTAINED

AUTHORIZATION YET TO BE OBTAINED

REMARKS

UNDER SEAL

SUMMARY OF THE DATAS COLLATED FOR THIS STUDY

SURULERE SUMMARY OF THE VACANT, ABANDONED, REMODELLING/RENOVATION, AND ONGOING CONSTRUCTION CAPTURED WITHIN THE DISTRICT.

LABEL	NUMBER CAPTURED
VACANT PLOTS	32
ABANDONED BUILDINGS	9
REMODELLING / RENOVATED BUILDINGS	9
ONGOING CONSTRUCTIONS	49
TOTAL	99

