

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
1	The property at 9/11, Abiola Street, off Oriola Street, Ketu	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been marked with red oxide	Distressed			
2	33, Bakare Makinde Street, Off Agidi Road, Alapere, Lagos	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Spalling on wall, exposed reinforcement and dampness.			
3	6, Shabiola Close, Off Rasheed Oyekan Street, Ketu, Lagos	Agboyi Ketu	3	Under illegal remodeling	Contravention Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide, Stop work	Spalling, visible cracks and dampness.			
4	6 Ojurayo Street, off Lawal Street, Oshogun, Alapere, Lagos	Agboyi Ketu	Bungalow	Abandoned	Contravention Notice, Seal up Notice, Demolition Notice, Site has been sealed up, Site has been marked with red oxide	Visible cracks			
5	66, Agidi Road, Off Demurin Street, Alapere, Lagos	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Exposed reinforcement.			
6	At the corner piece of Igboho Street by Ondo Street, Agboyi, Lagos	Agboyi Ketu	2 floor plus pent	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Dampness, Differential settlement and cracks			
7	Along Ikorodu Road, Ajegunle Bus Stop, Lagos	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks and exposed reinforcement			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
8	along Orisigun Street, off Ikorodu Road, Ketu	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been marked with red oxide	Partial collapse, visible cracks and dampness			
9	Property along Oguntoriti Street, beside Harbour of Knowledge, Ketu	Agboyi Ketu	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been sealed up	Cracks and settlement			
10	The property along Ola Bello Street, off Doyin Omololu Street, Ketu, Lagos	Agboyi Ketu	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Cracks, exposed reinforcement and dampness			
11	The property beside Inland Specialist Hospital along Bola Owodunni Street, Alapere, Lagos	Agboyi Ketu	3	Partially Occupied	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Dampness and cracks			
12	The property along Onasanya Street, off Utuh Street, Araromi Quarters, Oshogun, Lagos	Agboyi Ketu	2 floor plus pent	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Cracks and tilted backward			
13	The property along Awolaja Street, Off Aminu Street, Ketu, Lagos	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Partial collapse and cracks			
14	3, Modupe Street, off Kazeem Street, Ketu, Lagos	Agboyi Ketu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Cracks, exposed reinforcement and tattered roof			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
15	The property at 9/11, Abiola Street, off Oriola Street, Ketu, Lagos	Agboyi Ketu	2 blocks of 2floor	In use	Contravention Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Cracks			
16	The property at 7, Abiola Street, off Oriola Street, Ketu, Lagos	Agboyi Ketu	3	In use	Contravention Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Cracks and dampness			
17	Property at house 29A, marcury close Raji Razaki estate, Amuwo odofin.	Ajeromi Ifelodun	2	In use	Contravention Notice, Seal up Notice, Stop work	Dampness			
18	No 15 Aro Lane, Amukoko, Ajeromi Ifelodun	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposed reinforcements at the sofit of the slab, visible cracks on walls, concrete spalling, General wall dampness			
19	No 8 Okulaja street, Olodi apapa, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, deecurve plumbing fittings			
20	No 23 Bale Aiyetoro street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, deecurve plumbing fittings			
21	No 9 Bale Aiyetoro street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
22	No 16 Itire Road, off Ojo Road, Ifelodun	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness			
23	No 21 Muyibi street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls			
24	No 150 Muyibi street, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls			
25	4 Mission street, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls			
26	Along Alabede street off ishaga close, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and defective plumbing			
27	6 Salubi street, off Tolu road, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT)	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			
28	No 22 Ezeagu street, off Ojo Road, Ifelodun	Ajeromi Ifelodun	2 floors and bungalow	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
29	No 220 Idewu street, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			
30	No 214 Idewu street, Ajegunle	Ajeromi Ifelodun	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			
31	No 67 Alaafia street, Amukoko, Ifelodun	Ajeromi Ifelodun	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, beams and exposed reinforcement , General wall dampness and greenings along walls, defective plumbing fittings			
32	No 19 Ajadi street, off Ojoku street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
33	No 177 kirikiri road, Ajegunle	Ajeromi Ifelodun	2 numbers of 3 floors	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
34	93 Baale Adeyemo street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
35	38 Kirikiri Road(Muyibi street), Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
36	Beside No 60 Town hall street, Amukoko, Ifelodun	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
37	No 47 Ibafor street, off Apapa-oshodi expressway, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
38	No 1 Prince Fadina street, Ajegunle	Ajeromi Ifelodun	2	Abandoned	Contravention Notice, Seal up Notice, Demolition Notice, Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings, blown off roof			
39	10 oduduwa street, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
40	Corner piece of Musial oluwa road/New creature Avenue, Ajegunle	Ajeromi Ifelodun	3	In use	Contravention Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide, Stop work	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
41	corner piece of Ogunmade street and wilmer crescent, Ajegunle	Ajeromi Ifelodun	4	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
42	31 Jones Waribi street, Ajegunle	Ajeromi Ifelodun	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
43	No 44 Osho Drive, Ajegunle	Ajeromi Ifelodun	3	In use	Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
44	36 Opaleye Street, Off Aiyetoro street, Ajegunle	Ajeromi Ifelodun	2nos of 3 floors	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks along walls, slabs and beams, concrete spalling and exposed reinforcement ,differential settlement, General wall dampness and greenings along walls, defective plumbing fittings			
45	Property at No 33, Ogunrombi Road, Idimu Alimosho	Alimosho	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Spalling(Exposed Reinforcement), Cracks, Differential Settlement.			
46	Property At The Cornerpiece Of Lawal And Olisa Street, Idimu Alimosho.	Alimosho	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Spalling (Exposed Reinforcement), Lateral Cracks, Differential Settlement.			
47	Property at No 2 Ogodan close, off Babarinde street, Shasha road, Shasha Alimosho	Alimosho	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Spalling(Exposed Reinforcement),Cracks, Differential Settlement			
48	Property at No 3 Ponle Street, Egbeda Alimosho.	Alimosho	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Spalling(Exposed Reinforcement), Cracks(Slab), Differential Settlement.			
49	PROPERTY at 10 Adeyemi Daramola Close, Off Alhaji Adisa Balogun Street, Shasha Alimosho	Alimosho	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposed Reinforcement, Cracks, Partial Settlement.			




List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
50	Property Along Ponle street, off egbeda Idimu road, Alimosho Lagos.	Alimosho	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Cracks on Walls, Exposed Reinforcement, Spalling.			
51	Property at block 7, 51 road Festac town Amuwo odofin.	Amuwo Odofin	4	In use	Contravention Notice, Quit Notice	Crack of wall			
52	Property at no.51A diamond close Raji Razaki Amuwo odofin.	Amuwo Odofin	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Partial collapse rotness of roof carvass			
53	Property at house 29B, marcury close Raji Razaki estate, Amuwo odofin.	Amuwo Odofin	2	Abandoned	Contravention Notice, Seal up Notice, Stop work	Partial collapse			
54	Property Beside Chillers Hotel Oteyi Gani Adams Road Abule Ado Amuwo Odofin L.GA	Amuwo Odofin	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Tilting of Building Suspected Foundation Failure Undulating surrounding within the compound			
55	Property Behind chillers Hotel Oteyi Gani Adams Road Abule Ado Amuwo Odofin LGA	Amuwo Odofin	2	In use	Contravention Notice, Quit Notice, Seal up Notice	Tilting of Building Suspected Foundation failure			
56	Along Alhaji S.A. Eniafe Street, off Joseph Dosu Road, Badagry	Badagry	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	1. Spalling of concrete soffit . 2. Noticeable vertical and horizontal cracks along the wall. 3 Exposed reinforcement at the slab and beam.			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
57	Opposite Gloryland children school, along Tolulope Road, Ajara Topa, Badagry.	Badagry	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	1. Spalling of concrete soffit 2. Dampness of the walls 3. Noticeable vertical and horizontal cracks along walls 4. Exposed reinforcement at the slab			
58	Opposite Palace Bay, along Marina Road, Badagry	Badagry	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	1. Spalling of concrete soffit 2. Noticeable vertical and horizontal cracks along the wall 3. Exposed reinforcement at the slab			
59	Along Posikoh Tande road, Ajara Henkinawa, Badagry	Badagry	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	1. Spalling of concrete soffit 2. Noticeable vertical and horizontal cracks along the wall 3. Exposed reinforcement			
60	At Binti Laye Estate, Afoyonde, Badagry	Badagry	3	In use	Contravention Notice, Site has been marked with red oxide	1. Spalling of concrete soffit 2. Noticeable vertical and horizontal cracks along the wall 3. Exposed reinforcement			
61	Opposite 19A obanikoro compound.	Bariga	2	In use	Contravention Notice, Quit Notice	Distressed (2) floors structure with noticeable crack along the vertical and horizontal building. Dampness on wall. No roof.			
62	Adjacent no.5, Shola osaso street, obanikoro.	Bariga	2	Illegal demolition	Contravention Notice, Stop work	Cracks on the wall. Tattered roof. Dampness on the wall. Illegal demolition.			
63	38, fetuga street, bariga	Bariga	2	In use	Contravention Notice, Quit Notice, Seal up Notice	Distressed structure. Crack on the wall. Spalling on the wall.			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
64	No. 5/7 Kudaki street, Agodo	Egbe Idimu	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Cracks on columns and walls, Spalling of concrete slab, Dampness on walls, vegetation growth			
65	No. 17 Oremeji street, off Liasu road	Egbe Idimu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks on columns and walls, Dampness on walls, Growth of vegetation			
66	No. 30/32 Lamina Street, off Liasu road	Egbe Idimu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Spalling of concrete slab, Exposed reinforcement, Dampness on walls			
67	At the end of Ambali Street, off Liasu road	Egbe Idimu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT)	Dampness on walls, Cracks on columns and walls, Growth of vegetation, Spalling of concrete, Dilapidated roof			
68	No. 33 Egbe road, Ikotun-Isolo Road	Egbe Idimu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Cracks on walls and structural members, Dampness on walls and structural members, Concrete spalling, Tattered roof			
69	Beside No. 33 Along Ikotun-Isolo Road	Egbe Idimu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposed reinforcement, Concrete spalling, Introduction of props to support the structure, Cracks on walls and structural members, Tattered roof			
70	Along Yusuf Bishi Street, off Community Street, Agodo	Egbe Idimu	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Differential settlement, Cracks on wall			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
71	No. 19 Ogbewi Sreet, Agodo	Egbe Idimu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks on wall and beams, Spalling of concrete slab, Exposed reinforcement, Dampness on walls, Growth of vegetation and algae walls.			
72	At the end of Abati Street, Agodo	Egbe Idimu	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Differential settlement, Cracks on walls			
73	No. 3 Ambali Street, off Liasu road	Egbe Idimu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide, Stop work	Cracks on walls and columns, Growth of vegetation and growth of algae, Spalling on concrete slab, Dampness on walls, Poor plumbing works			
74	No. 13 Lamina Street, off Liasu road	Egbe Idimu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks on walls, slab, beams and columns. Exposed beams and slab reinforcement. Dampness and algae on walls. Dilapidated roof			
75	Along Emmanuel Chukwu close, off Ade Olohunwa Crescent, Cele Egbe	Egbe Idimu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Differential settlement			
76	At the Cornerpiece of Emmanuel Chukwu/Ade Olohunwa Crescent, Cele Egbe	Egbe Idimu	Bungalow	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been marked with red oxide	Differential settlement. Major vertical and horizontal cracks on all structural elements of the structure and walls			
77	Opposite No. 27 OlaSheu Yissa Street, off Kudaki road, Agodo	Egbe Idimu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Cracks on all structural members. Dampness Direct exposure to weather. Exposed reinforcement			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
78	PROPERTY AT PLOT 235 ALONG KUSENLA ROAD, OFF LEKKI-EPE EXPRESSWAY, ETI OSA, LAGOS STATE.	Eti Osa West 1	6	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Spalling of concrete on slabs, beams, facial concrete are observed Flaking of paints on wall are as well noticed Displaced roofing sheets and claddings are observed Noticeable dampness on walls and structural members			
79	PROPERTY AT NO 4, AWUDU EKPEKHA BLVD STREET, OFF ADMIRALTY WAY, LEKKI PHASE 1, ETI OSA, LAGOS STATE	Eti Osa West 1	2	In use	Contravention Notice, Quit Notice, Seal up Notice	i. Cracks on wall and some structural members ii. Spallation of concrete on structural members iii. Flushing of paint on wall iv. Exposed reinforcement on structural members			
80	Along Jerry close, sureddwell estate ibeju lekki	Ibeju Lekki West	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Settlement, the structure has tilted			
81	At the corner piece of musbah ogunla awayaya ibeju lekki	Ibeju Lekki West	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide,	The structure has tilted to the back side			
82	CAC along hon idowu eletu awayaya ibeju lekki	Ibeju Lekki West	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been sealed up, Site has been marked with red oxide	Dampness Structural cracks			
83	Km 32 lekki epe Expressway eko akete ibeju lekki	Ibeju Lekki West	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Stop work	The structure has tilted to the side			
84	Distressed structure at greenwood Park estate abijo ibeju lekki	Ibeju Lekki West	2	In use	Contravention Notice, Seal up Notice, Demolition Notice, Site has been marked with red oxide	Dampness Dilapidated The two buildings has tilted to the side			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
85	No. 25 Dolamu street, off Community Street, Agodo	Ibeju Lekki West	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Differential settlement. Exposed reinforcement due to spalling. Visible cracks on walls. Dampness on walls			
86	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice	Dilapidated Roofs Exposed Reinforcement Cracks on walls Spalling of concrete Evidence of weak column and slab			
87	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Stop work	Exposed reinforcement Spalling of concrete Dampness on building Cracks on slab			
88	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice, Demolition Notice	Dilapidated roof Exposed reinforcement observed on the reinforced slab due to failure of concrete floor			
89	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice	Visible cracks Exposed reinforcement Water ingress from foundation			
90	Ifako	Ifako Ijaiye	3	In use	Contravention Notice, Quit Notice	Visible sign of dilapidation with deteriorated finishes Components of the structure are in a state of despair indicating prolonged lack of maintenance			
91	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Seal up Notice	Dilapidated roofs Cracks on the wall			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
92	Ifako ijaiye	Ifako Ijaiye	3	In use	Contravention Notice, Seal up Notice	Cracks on the wall Dampness on the wall Exposed slab reinforcement			
93	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dilapidated roof Crack on the wall Exposed reinforcement			
94	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice	Dilapidated roofs Dampness on the wall			
95	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dilapidated roof Cracks on first floor slab Exposed reinforcement observed Spalling of concrete			
96	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dilapidated roof Crack an on the wall Structural settlement			
97	Ifako ijaiye	Ifako Ijaiye	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been sealed up, Site has been marked with red oxide	Exposed reinforcement Cracks on wall Dampness on structure Spalling of concrete			
98	Property at NO 17 opposite NO 16 along Kehinde Oseni street, Off Igbogbo road, Igbogbo, Ikorodu, Lagos state.	Igbogbo/Baiyeku	2	In use	Contravention Notice, Site has been marked with red oxide, Stop work	1. Structural wall crack 2. Wall dampness on the building			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
99	Property along Adebambo street within liberty estate Igbe laara ijede ikorodu.	Ijede	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Dampness on building walls 2nd floor exposed roof carcass			
100	Property at coner piece baale ayinde omoyele street off amuda ogo palace igbe laara	Ijede	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up	Expose reinforcement on the columns No connection between columns and Beans Expose reinforcement on slab and beans			
101	Property beside No 14, Jericho Street off Igboya road ijede Ikorodu.	Ijede	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up	Weak first floor slab/Sagging slab Dampness on walls, beams columns Expose reinforcement on Columns			
102	Property along Gberigbe road, ijede Ikorodu.	Ijede	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up	Weak first floor slab Dampness on wall beam & columns			
103	Property at Niniola Tiamiyu street igboken off unilag museum estate Ginti ijede Ikorodu.	Ijede	Bungalow	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been sealed up	Expose reinforcement on beams Cracks on the columns & beams Dampness on beams, wall & columns			
104	Property at Concord along Igbe ijede road ijede Ikorodu. D	Ijede	3	Abandoned	Contravention Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	1. Cracks on the columns beams 2.Dampness all over the walls of the building 3. Expose reinforcement on the beams , columns and slab			
105	OPPOSITE, OMINI STREET OFF ANIBABA STREET IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, exposed reinforcement, wall cracks.			






List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
106	AT 15 EKETUNDE STREET OFF ANIBABA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT)	Diagonal wall cracks, Concrete spalling on first floor slab.			
107	ALONG ANIBABA STREET IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Dilapidated slab, exposed reinforcement/Spalling of Concrete, Rising wall dampness, visible cracks			
108	ALONG ANIBABA STREET IKORODU.	Ikorodu Central	2	In use	Request for Non Destructive Test (NDT)	Concrete spalling.			
109	OPPOSITE 8 (NO 13) EMMANUEL IKUBOLAJE STREET OFF ANIBABA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Damp walls, Spalling of concrete.			
110	ALONG AUNTY KENNY STREET ANIBABA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Dilapidated roof, exposed reinforcement, visible cracks, wall dampness.			
111	ALONG INDIAN MALAIKA OFF OLUROGA STREET AGA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete spalling, wall dampness			
112	ALONG ASHIRU RAJI STREET IKORODU.	Ikorodu Central	3	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Invisible cracks, column and slab cracks.			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
113	ALONG ASHIRU RAJI STREET AGA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete spalling, cracks, dilapidated roof			
114	ALONG ASHIRU RAJI STREET AGA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Column cracks, concrete spalling, damp walls.			
115	ALONG ASHIRU RAJI AGA IKORODU.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete spalling, exposed reinforcement			
116	ALONG ALIYU IMAM OFF OBAFEMI TAIWO OFF IGBOGBO ROAD IKORODU.	Ikorodu Central	3	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Damp walls, concrete spalling, exposed reinforcement.			
117	ALONG ALIYU IMAM & OBAFEMI TAIWO STREET IGBOGBO ROAD IKORODU.	Ikorodu Central	3	In use	Contravention Notice, Request for Non Destructive Test (NDT)	concrete spalling, damp concrete water tower, exposed reinforcement.			
118	Property Along Ifayemi Ayeni Street, Solomade, Ikorodu.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Visible wall cracks, Concrete Spalling, Exposed reinforcement			
119	Opposite No 7, Olateru Street, Aruna Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Partial Collapse/Distressed structure, Dilapidated roof.			







List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
120	No 10 Mount Carmel Street, Ikorodu.	Ikorodu Central	3	Abandoned	Contravention Notice, Request for Non Destructive Test (NDT)	Visible Cracks, exposed reinforcement, Concrete Spalling			
121	No 19 Oriwu Road, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Exposed reinforcement, Slab spalling, Wall cracks.			
122	Corner of Inatomwo & Borokini Street, Ikorodu	Ikorodu Central	3	Abandoned	Contravention Notice, Request for Non Destructive Test (NDT)	Cracks, Exposed reinforcement, Concrete Spalling.			
123	No 6 Borokini Street, Aga Ikorodu	Ikorodu Central	3	Abandoned	Contravention Notice, Request for Non Destructive Test (NDT)	Dilapidated roof, exposed reinforcement			
124	No 5 Odufeko Street Solebo (Ile-Baale), Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Cracks, Spalling, Exposed reinforcement, Dilapidated roof			
125	No 23/24 Ireshe Road Off Aga, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Weak slab, Rusted reinforcement, Wall cracks			
126	No 3 Ebuwawa Street Off Pasuko Street, Aga Ikorodu	Ikorodu Central	Bungalow	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Partial wall collapse, Weak slab, Wall Dampness, Concrete spalling			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
127	Property along Obafemi Taiwo, Off Igbogbo-Igbe road, Ikorodu	Ikorodu Central	3	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Damp Walls, Concrete Spalling, Exposed reinforcement, Cracks			
128	Property Along Ijalabgbo Street, Ikorodu.	Ikorodu Central	3	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			
129	No 26 Adaraloye Street, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Cracks, exposed reinforcement, column cracks			
130	Property Along Ijalabgbo Street, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			
131	Property at No 40, Shamsudeen Jaiyesimi Street, Aga, Ikorodu.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			
132	Property At Aunty Rita, Street, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			
133	Property along Ireshe Road, by Anibaba, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
134	Property Along Olusesi Street, Anibaba, Ikorodu.	Ikorodu Central	3	Abandoned	Contravention Notice, Request for Non Destructive Test (NDT)	Concrete Spalling, Exposed reinforcement, Horizontal and vertical cracks			
135	Property along Aunty Rita, by Anibaba, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Exposed reinforcement, Visible cracks			
136	Property along Aunty Rita, by Anibaba, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Exposed reinforcement, Visible cracks, Concrete Spalling			
137	Property along Aunty Rita, by Anibaba, Ikorodu	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Visible wall cracks, Concrete Spalling, Exposed reinforcement.			
138	Property Along Ifayemi Ayeni Street, Solomade, Ikorodu.	Ikorodu Central	2	In use	Contravention Notice, Request for Non Destructive Test (NDT)	Visible wall cracks, Concrete Spalling, Exposed reinforcement.			
139	Along Juwon Oshibadu street, off Ijede road, Itamaga Ikorodu	Ikorodu North	2	Abandoned	Contravention Notice, Seal up Notice, Demolition Notice, Site has been sealed up, Site has been marked with red oxide	Spalling, exposed reinforcements, Damaged roofed, overall dilapidation of the building.			
140	Along Ijede road, adjacent Be Happy Hotel, Itamaga Ikorodu	Ikorodu North	3	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible lateral and horizontal cracks in structural members, Spalling, exposed reinforcement, Dampness, Growth of plants on structural members, Dilapidation of the entire building			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
141	ALONG ABIOLA ADEYEMI STREET, OFF GOVERNORS ROAD. IKOTUN	Ikotun Igando	3	In use	Contravention Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	CRACKS, DAMPNES, SPALLING.			
142	ALONG SEAWEEED STREET OFF COMMUNITY ROAD IJEGUN.	Ikotun Igando	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	CRACKS, DAMPNES, SPALLING.			
143	3, LATEEF BELLO STREET, OFF IGE ADUBI WAY, ONIMABA ESTATE, IKOTUN-IGANDO ROAD.	Ikotun Igando	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS, DAMPNES, SPALLING.			
144	ALONG OGUNTUNWASHE STREET, OFF OLD OBADORE ROAD, IGANDO	Ikotun Igando	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	DILAPIDATED ROOF, DAMPNES, CRACKS, SPALLING, EXPOSED REINFORCEMENT.			
145	50, AMAZING GRACE STREET, OFF ISUTI ROAD, EGAN.	Ikotun Igando	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	SETTLEMENT AT THE REAR.			
146	AT 28 TOLUWANI STREET OFF ISOLO ROAD, ISHERI OSHUN.	Ikotun Igando	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	EXCESSIVE CONCRETE SAPLLING, WIDE CRACKS, EXPOSED SLAB, HIGH CORRODED REINENFORCEMENT.			
147	ALONG SHARAF A MBALI STREET, OFF ISOLO ROAD, ISHERI OSHUN	Ikotun Igando	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS, DAMPNES, SPALLING.			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
148	ALONG OBINNA ONURAH STREET, OFF ILE EJA ROAD, OKERUBE	Ikotun Igando	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS, DAMPNES, SPALLING.			
149	PROPERTY ALONG OSHODI APAPA EXPRESS ROAD ISOLO	Isolo	3	Abandoned	Contravention Notice, Seal up Notice, Demolition Notice	THE DISTRESS FEATURES IN THE BUILDING INCLUDE SEVERE CRACK, DAMPNES AND SEVERE BIOLOGICAL GROWTH.			
150	PROPERTYAT NO 4 UNITY STREET OKOTA	Isolo	2	In use	Contravention Notice, Quit Notice, Seal up Notice	THE DISTRESS FEATURES ON THE STRUCTURE INCLUDES: SEVERE CRACKS, SPALLING, PEELING AND DAMPNES.			
151	OROPERTY ALONG YEKINI OMONITAN STREET OKOTA	Isolo	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	THE DISTRESS FEATURES INCLUDES DIFFERENTIAL SETTLEMENT, CRACKS AND DAMPNES WITH BIOLOGICAL GROWTH.			
152	PROPERTYALONG LADI AJOMALE STREET PEACE ESTATE	Isolo	2	Abandoned	Contravention Notice, Seal up Notice, Demolition Notice	THE DISTRESS FEATURES ON THE STRUCTURE INCLUDES: SEVERE CRACKS, SPALLING, PEELING AND DAMPNES.			
153	No. 85 Lawanson Road, Itire Ikate.	Itire Ikate	2	In use	Site has been sealed up	Exposed Reinforcement Visible cracks			
154	No. 47 Owoseni Street, Itire-Ikate.	Itire Ikate	2	Abandoned	Site has been sealed up	Visible cracks Settlement			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
155	No. 30 Shobande Street, Itire-Ikate.	Itire Ikate	2	In use	Quit Notice	Evidence of concrete spalling Evidence of exposed reinforcement Visible cracks seen on the building			
156	Property at Jimoh Agunbiade Street, Itire-Ikate.	Itire Ikate	2	Abandoned	Site has been marked with red oxide	Exposed reinforcement			
157	No 19 Omilade Street, Itire-Ikate.	Itire Ikate	2	In use	Contravention Notice, Quit Notice	Visible cracks seen on the building Exposed reinforcement			
158	No. 18 Okeolorun- tedo Street, Itire-Ikate.	Itire Ikate	2	In use	Contravention Notice, Quit Notice, Seal up Notice	Visible cracks seen on the building . Exposed reinforcement . Concrete Spalling.			
159	No 14 Arowosere Street, Off Karounwi Street, Itire-Ikate	Itire Ikate	3	In use	Contravention Notice, Quit Notice, Seal up Notice	Visible cracks seen on building Exposed reinforcement			
160	NO 7 OLATUNJI STREET, OFF OGUDU ROAD. KOSOFE, LAGOS	Kosofe	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks on all structural member			
161	NO 3 ONDO STREET, OFF OBA OLORUNTOYIN WAY, OLORUNSHOKI, KOSOFE LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks on all structural member			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
162	NO 38 SURULERE STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks on all structural member			
163	NO 66 KUJORE STREET, OFF OGUDU ROAD, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks on all structural member			
164	NO 16 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
165	NO 17 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
166	NO 25 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
167	NO 23 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
168	NO 20 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
169	NO 22 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
170	NO 18 ABIOLA STREET OFF ADENIJI STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
171	NO 20 OLAYIWOLA STREET, OWO -IYA STREET, OWORONSHOKI, KOSOFE, LAGOS	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
172	NO 46 VICTORIA STREET, OJOTA, KOSOFE, LAGOS	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
173	NO 69 OLATUNJI STREET, OFF OGUDU ROAD, OJOTA, KOSOFE LAGOS	Kosofe	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
174	NO 17 VICTORIA STREET, OFF OGUDU ROAD, OJOTA, KOSOFE, LAGOS	Kosofe	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural members			
175	NO 6/8 AJOKE SALAKO STREET, OFF AJAYI AINA STREET, IFAKO GBAGADA, KOSOFE, LAGOS	Kosofe	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural members			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
176	ALONG GAFARI BALOGUN STREET, OGUDU, KOSOFE	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
177	NO. 25 ADEBARE STREET, OFF OGUDU RD. OGUDU, KOSOFE	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
178	NO 9 TAOFIK OYESIJI STREET, OFF ADEGBENRO STREET, IFAKO, GBAGADA	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
179	NO. 24 OWORO RD. OWORONSHOKI, KOSOFE	Kosofe	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
180	NO. 24 PALACE STREET, OFF OGUDU RD. KOSOFE	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
181	ALONG BAYO OSINOWO STREET, OFF SAMSON AYORINDE STREET, OGUDU	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
182	CORNERPIECE OF ADEYEYE STREET, BY BAMIDELE ADEYANJU STREET, MILLENIUM ESTATE, KOSOFE	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
183	RED-ROOFED BUILDING ALONG OMOYELE STREET, IFAKO, GBAGADA, KOSOFE	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
184	PROPERTY BESIDE NO. 37 OGUDU RD. OGUDU, KOSOFE	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
185	NO. 151 ALHAJI AMOO STREET, OJOTA	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
186	NO. 130 VICTORIA STREET, OJOTA, KOSOFE	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
187	NO. 120 VICTORIA STREET, OJOTA, KOSOFE	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
188	NO. 130 KUJORE STREET, OJOTA, KOSOFE	Kosofe	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			
189	NO. 5B ARAN-ORIN STREET, IFAKO, GBAGADA, KOSOFE	Kosofe	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	Cracks on all structural member			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
190	113, Igboere Road, Lagos Island.	Lagos Island East	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Spallings, Exposed reinforcement, dampness and cracks			
191	No 33, Okesuna street, Lagos Island	Lagos Island East	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Exposed reinforcement, cracks, dampness and spallings			
192	No 28, Isale Igangan Street, Lagos Island	Lagos Island East	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dampness and Spallings			
193	No 51 Freeman Street, Lagos Island	Lagos Island East	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dampness and cracks			
194	20, Olowu Street, Lagos Island.	Lagos Island East	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks, Exposed reinforcement and Spallings			
195	59, Oshodi Street, Lagos Island	Lagos Island East	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks and exposed reinforcements			
196	No 51, Freeman Street, Lagos Island	Lagos Island East	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks, Dampness and exposed reinforcement			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
197	No 60, Evans street, Lagos Island	Lagos Island East	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Dampness, Cracks and Exposed reinforcement			
198	No 60, Evans Street, Lagos Island	Lagos Island East	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Cracks, Exposed reinforcement and Dampness			
199	6B BRIDGE STREET, LAGOS ISLAND	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS ON THE WALL TILTED TO THE LEFT HAND SIDE			
200	5 ATIN STREET, LAGOS ISLAND	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS ON THE COLUMNS AND BEAMS EXPOSED REINFORCEMENT ON SLABS DAMPNESS ON THE WALLS			
201	57 PALM CHURCH STREET, LAGOS ISLAND	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS EXPOSED REINFORCEMENT SPALLING LACK OF MAINTENANCE			
202	38 FOLAWIYO STREET, LAGOS ISLAND	Lagos Island Wesr	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	CRACKS LACK OF MAINTENANCE			
203	20 IDUMAGBO STREET LAGOS ISLAND	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks spalling exposed reinforcement differential settlement			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
204	45 balogun west street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks exposed reinforcement dampness and water seepage peeling of plasters and paints spalling and falling of concrete			
205	6a bridge street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks bulge and bowed wall exposed reinforcement			
206	46 folawiyo street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	differential settlement cracks spalling lack of maintenance			
207	60 idoluwo street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks differential settlement exposed reinforcement spalling dampness			
208	59 palm church street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	spalling dampness lack of maintenance			
209	77 ita alagba street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks lack of maintenance differential settlement			
210	73 ita alagba street lagos island	Lagos Island Wesr	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness patched spalling exposed reinforcement lack of maintenance			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
211	7 atin street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks exposed reinforcement dampness			
212	3 atin street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks spalling dampness			
213	6/8 church street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling cracks on the walls and columns			
214	17 iga iduganran street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks patched spalling			
215	4 bridge street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on the wall tilted to the left			
216	7 st john street lagos island	Lagos Island Wesr	3	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks underneath the slab columns and beams patched spalling			
217	14 agoro street lagos island	Lagos Island Wesr	3	In use	Request for Non Destructive Test (NDT)	cracks			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
218	fagborun court lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling underneath the slab and beam cracks on the walls and columns			
219	12 st john street lagos island	Lagos Island Wesr	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	exposed reinforcement cracks dampness on wall			
220	30 issa williams street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling cracks			
221	1 ashogbon street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling cracks			
222	2 liadi lane lagos island	Lagos Island Wesr	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	spalling cracks			
223	27 obun eko street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks exposed reinforcement			
224	38 seriki street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	dampness exposed reinforcement cracks			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
225	24b church street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	concrete spalling cracks			
226	9/10 fagborun court lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling cracks			
227	2/4 oki street lagos island	Lagos Island Wesr	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	concrete spalling cracks			
228	15 akapo street lagos island	Lagos Island Wesr	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness cracks exposed reinforcement			
229	35 Thomas street, ebute metta	Lagos Mainland	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	horizontal and vertical cracks, dampness on walls, patches on walls			
230	extreme end of Thomas street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on walls and structural members dampness on walls flaking of paint spalling of concrete			
231	8 Bola street, ebute metta	Lagos Mainland	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	exposed reinforcement cracks on structural members vertical and horizontal cracks dampness on walls spalling of concrete			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
232	behind 78 Kano street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	exposed reinforcement cracks on structural members dampness on walls vertical and horizontal cracks			
233	177/179 Borno way, ebute metta	Lagos Mainland	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls cracks on structural members vertical and horizontal cracks exposed reinforcement			
234	11 Berkley street, Ebute metta	Lagos Mainland	4	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	vertical and horizontal cracks cracks on structural members tattered roofs dampness on walls flaking of paint			
235	19 ibarapa street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls tattered roof flaking of paint exposed reinforcement spalling of concrete horizontal and vertical cracks			
236	17 ibarapa street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on walls dampness on walls horizontal and vertical cracks exposed reinforcement spalling of concrete			
237	18 Apapa road, ebute metta	Lagos Mainland	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on walls dampness on walls horizontal and vertical cracks exposed reinforcement spalling of concrete			
238	57 moshalashi street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on walls dampness on walls horizontal and vertical cracks exposed reinforcement spalling of concrete tattered roof			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
239	20 Iya Agan street, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	cracks on walls dampness on walls horizontal and vertical cracks exposed reinforcement spalling of concrete			
240	47 kano street, ebute metta	Lagos Mainland	5	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls flaking of paint vertical and horizontal cracks			
241	37 herbert macaulay street, ebute metta	Lagos Mainland	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls horizontal and vertical cracks flaking of paint			
242	196 borno way, ebute metta	Lagos Mainland	3	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls flaking of paint vertical and horizontal cracks			
243	43 raimi oladimeji street, ebute metta	Lagos Mainland	2	In use	Request for Non Destructive Test (NDT)	cracks on structural members dampness on walls exposed reinforcement spalling of concrete horizontal and vertical cracks			
244	5 moshalashi street, ebute metta	Lagos Mainland	3	In use	Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks on structural members dampness on walls flaking of paint patches on walls spalling of concrete			
245	7 moshalashi street, ebute metta	Lagos Mainland	3	In use	Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks on structural members dampness on walls flaking of paint patches on walls spalling of concrete			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
246	153 Borno way, ebute metta	Lagos Mainland	2	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	vertical and horizontal cracks dampness on walls flaking of paint exposed reinforcement spalling of concrete			
247	20 daodu lane, ebute metta	Lagos Mainland	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	dampness on walls horizontal and vertical cracks flaking of paint tattered roof spalling of concrete			
248	41 Abeokuta street, ebute metta	Lagos Mainland	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	horizontal and vertical cracks spalling of concrete dampness on walls exposed reinforcement			
249	51 kano street, ebute metta	Lagos Mainland	4	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	cracks on walls dampness on walls flaking of paint			
250	Along 3rd avenue 34 road Gowon estate Ipaja Lagos State	Mosan Okunola	3	Abandoned	Contravention Notice, Seal up Notice	Roof sheets appear loose and improperly fixed Surface cracks and patches on walls peeling plaster Column is weathered and rough			
251	Opposite no 26a salvation avenue, off pipeline okunola road, Egbeda Lagos.	Mosan Okunola	2	In use	Contravention Notice	Cracks Dilapidated Roof Exposed reinforcements Sagging of slab			
252	No 9 Adaranijo street off remi ogunjimi street Egbeda Lagos.	Mosan Okunola	4	In use	Request for Non Destructive Test (NDT), Site has been marked with red oxide, Contravention notice for distressed structure	Exposed reinforcements sagging of protruded cantilever Spalling Evidence of cracks			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
253	NO 70 ABIBU STREET OFF AGORO STREET, MUSHIN	Mushin	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Building weak			
254	CORNERPIECE OF AJAYI STREET MUSHIN	Mushin	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks			
255	NO 24 ODUSELU STREET, MUSHIN	Mushin	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks on the building			
256	NO 15 TAKURO STREET, IDI-ARABA MUSHIN	Mushin	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks			
257	NO 7 OLUSOGA STREET OFF ALAFIA STREET, MUSHIN	Mushin	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks			
258	ALONG OLAGBAIYE STREET OFF AKANRO STREET MUSHIN	Mushin	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Visible cracks			
259	OLUWAKEMI STREET BESIDE TELECOMMUNICATIO N MASS, ODI-OLOWO, MUSHIN.	Odi Olowo	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	DIFERANCIAL SETTLEMENT, TATTERED ROOF			


List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
260	PROPERTY AT NUMBER 22, OJELADE STREET, ODI-OLOWO, MUSHIN, LAGOS	Odi Olowo	3	In use	Contravention Notice, Quit Notice	CRACKS, FLAKING OF WALL PAINTS AND SPALLING			
261	PROPERTY AT NO 12 MUFUTAU STREET, OFF OLADITI STREET, ODI-OLOWO MUSHIN LAGOS	Odi Olowo	3	In use	Contravention Notice	DAMPNESS CRACKS EXPOSE OF REINFORCEMENT TALTERED ROOFING			
262	PROPERTY AT THE EXTREME END OF ANIFA STREET, ILUFE, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Site has been marked with red oxide	DIFFERENTIAL SETTLEMENT, EXPOSED REINFORCEMENT, CRACKS ON STRUCTURAL MEMBERS AND DAMPNESS ON WALLS.			
263	PROPERTY AT THE END OF OLABULO STREET, ILUFE, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	TILTED, CRACKS ON STRUCTURAL MEMBERS AND EXPOSED REINFORCEMENT.			
264	PROPERTY AT THE END OF SEVEN PILLARS STREET, MOSAFEJO, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	TILTED			
265	PROPERTY ALONG ANIFA STREET, OPPOSITE ECO PILLAR SCHOOL, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	DIFFERENTIAL SETTLEMENT, EXPOSED REINFORCEMENT, CRACKS ON STRUCTURAL MEMBERS AND DAMPNESS ON WALLS.			
266	PROPERTY AT NO 16, ILUFE ROAD, ILUFE, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	EXPOSED REINFORCEMENT, CRACKS ON WALL, DAMPNESS ON WALLS.			




List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
267	PROPERTY AT THE END OF DAUDA STREET, IRA QUARTERS, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	TILTED			
268	PROPERTY ALONG OKEMS STREET, OFF HASSAN STREET, ILUFE, OJO, LAGOS.	Ojo	2	In use	Contravention Notice, Quit Notice, Demolition Notice, Site has been marked with red oxide	EXPOSED REINFORCEMENT, CRACKS ON WALL, DAMPNES ON WALLS.			
269	Along Association Avenue, Off Zawiyat Street, Ajegunle, Ojokoro, Lagos	Ojokoro	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	The columns rebars are not properly connected to the existing beams rebars			
270	27/29 Jide Ogunbona Street, off Baale Animashaun Road, Ojokoro.	Ojokoro	Two numbers of four floors building	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	crack on walls, Concrete spalling, Partial collapse of balcony, Exposed Reinforcements, Dampness on walls.			
271	Cornerpiece of Oguntade Street & Alh. Omola Street, off Geniyu Oladeinde Road, off Baale Animashaun Road, Ojokoro.	Ojokoro	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exhibiting signs of Distress, Slab spalling, Exposed and corroded reinforcement, Growth of vegetations on external walls.			
272	No. 38 Olaniyi street, beside Mother Alcce Memorial School, off Agbe Road, Ojokoro.	Ojokoro	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exhibiting signs of Distress / Occupied, crack on walls, slab spalling, Exposed Reinforcements.			
273	No. 7 fred Williams Street, off Segun Adetiba Road, Ojokoro.	Ojokoro	4	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exhibiting signs of Distress, Exposed and Dulapidated roof, slab spalling, exposed and corroded reinforcement			



List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
274	Beside No 8 Idowu street off nureni Yusuf road, kola ojokoro.	Ojokoro	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exhibiting signs of Distress, crack on walls, slab spalling, Exposed Reinforcements.			
275	Corner piece of oremeji close and olufunsho Ayodele, off Abiodun Onitiri street, ojokoro	Ojokoro	4	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exhibiting signs of Distress			
276	Idoposi quarters, off akinyele compound, ilado, off iworo-ajido road, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed reinforcement 3. Tattered roof			
277	Along Lagos Badagry Expressway, Mowo busstop, Mowo, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed and corroded reinforcement 3. Deffect on the staircase			
278	Along ado-odo-ikoga road, akoro quarters, Mowo, Olorunda LCDA, Badagry, Lagos	Olorunda	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed and corroded reinforcement 3. Tattered roof 4. Cracks on structural members			
279	Mowo extension, off Lagos Badagry Expressway, Mowo, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed corroded reinforcement 3. Tattered roof 4. Notable cracks on structural members			
280	Yellow sewanu, checking point, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed corroded reinforcement 3. Cracks on structural members			



List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
281	Along odan-ilogbo, ireakari estate, comforter, Olorunda LCDA, Badagry, Lagos	Olorunda	Bungalow	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed corroded reinforcement 3. Tattered roof			
282	Along alhaja sinatu street, opposite celestial church, Morogbo, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Under construction	Contravention Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide, Stop work	1. Vertical and horizontal cracks on the walls 2. Exposed corroded reinforcement 3. Cracks on structural members 4. Failed foundation			
283	Along xylem street, off alfa oladokun street, Morogbo, Olorunda LCDA, Badagry, Lagos	Olorunda	Bungalow	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Vertical and horizontal cracks on the walls 2. Exposed corroded reinforcement 3. Settled foundation			
284	At chief Wayon, beside Caroline street, along iworo-ajido road, Olorunda LCDA, Badagry, Lagos	Olorunda	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Cracks on the walls 2. Exposed corroded reinforcement 3. Settled foundation			
285	Along fadahunsi street off umoru anthony street satellite town oriade LCDA	Oriade	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice	Exposed reinforcement, vertical and horizontal cracks.			
286	PROPERTY ALONG ALAHUN OSUBA STREET OFF HAPPY HOME AVENUE KIRIKIRI TOWN ORIADE LCDA	Oriade	2	In use	Contravention Notice, Quit Notice, Seal up Notice	Exposed reinforcement, dampness on the surface of the structure			
287	3, Ajiboye street, Off Lagos Abeokuta Expressway, Orile Agege	Orile Agege	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Exposed reinforcement on the soffit of the beams and slab. 2. Visible cracks on the columns and walls. 3. Dampness present on the wall. 4. Evidence of Concrete Spalling. 5. Severely dilapidated roof eaves			



List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
288	276, Along Lagos Abeokuta Expressway, Orile Agege	Orile Agege	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	1. Exposed reinforcement on the soffits of beams and slabs. 2. Evidence of concrete spalling. 3. Dampness present on the walls. 4. Visible cracks on the walls and columns. 5. An extremely dilapidated roof eaves.			
289	Property Along Solo Amahoatu Street Off Asa Afariogun Street, Ajao Estate, Oshodi	Oshodi	3	Abandoned	Contravention Notice, Demolition Notice	Visible Cracks			
290	Property at No. 12 Temidire Street, Oshodi	Oshodi	2	In use	Contravention Notice	Visible cracks			
291	Property at No. 24, Olusoji Street, Cornerpiece of Olusoji Street and Afariogun Street, Oshodi	Oshodi	3	In use	Contravention Notice, Stop work	1. Visible Cracks 2. Spalling			
292	Property at No. 5, Gbade Olabode Street, Ajao Estate, Oshodi	Oshodi	3	In use	Contravention Notice	1. Spalling 2. Visible cracks			
293	Property at No. 22, Shopeju Street, Ladipo, Oshodi.	Oshodi	2	In use	Contravention Notice	Visible cracks			
294	Property at No. 102, Mafoluku, Mafoluku, Oshodi.	Oshodi	2	In use	Contravention Notice	Spalling			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
295	Property at No. 21, Edun street, Ladipo, Oshodi	Oshodi	3	In use	Contravention Notice	Spalling			
296	Property at No. 21, Akinosho Street, Off Afariogun Street, Oshodi	Oshodi	2	In use	Contravention Notice	Cracks			
297	Property at No. 7, Dosunmu Street, Oshodi	Oshodi	2	In use	Contravention Notice, Seal up Notice	Visible Cracks			
298	Property at No. 2 Akeem Shittu street, Ajao Estate, Oshodi	Oshodi	4	In use	Contravention Notice	Visible cracks			
299	Property at No. 17 Old Ewu road, Mafoluku, Oshodi.	Oshodi	3	In use	Contravention Notice	Visible cracks			
300	Property at No. 85, Mafoluku road, Mafoluku, Oshodi	Oshodi	2	In use	Contravention Notice	Visible Cracks			
301	Property at No. 37 Alhaja Abibat Street, Majekodunmi, Shogunle, Oshodi	Oshodi	2	In use	Contravention Notice	Visible cracks			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
302	Property at No. 3 Peluola Street, Mafoluku, Oshodi	Oshodi	3	In use	Contravention Notice	Visible cracks			
303	Property at No. 22 Mafoluku road, Oshodi	Oshodi	2	In use	Contravention Notice	1. Spalling 2. Visible Cracks			
304	3, VINCENT STREET, OFF ONAFOWOKAN STREET, SOMOLU	Shomolu	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	1. Vertical cracks 2. Spalling of concrete column 3. Dilapidated of structure			
305	4, TOLA ODUNTAN STREET, SOMOLU	Shomolu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	1. Vertical cracks 2. Spalling of concrete slab 3. Dilapidated of structure			
306	27, OKUJJOBI STREET, SOMOLU	Shomolu	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	1. Vertical cracks 2. Spalling of concrete slab 3. Dilapidated of structure			
307	79, APATA STREET, SOMOLU	Shomolu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	1. Spalling of concrete slab 2. Vertical and Horizontal cracks 3. Tilting of structure 4. Dilapidation of structure			
308	6, BABAYEMI CRESCENT, SOMOLU	Shomolu	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	1. Horizontal crack on cantilever beam 2. Spalling of concrete slab 3. Dilapidation of structure			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
309	9, AYOADE STREET, SOMOLU	Shomolu	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT)	i. Horizontal cracks along beams. ii. Differential settlement of structure. iii. Presence of damp on walls.			
310	13, OWUKORI CRESCENT OFF WESTERN AVENUE WITHIN ALAKA ESTATE,SURULERE	Surulere	2	Abandoned	Contravention Notice, Quit Notice, Seal up Notice	ABANDONED			
311	39, BODE THOMAS OFF ADENIRAN OGUNSANYA, SURULERE	Surulere	3	Abandoned	Contravention Notice, Quit Notice, Seal up Notice	OPEN REINFORCEMENT DAMPNESS CRACKS			
312	13/15 Allen Road, Surulere	Surulere	2	Abandoned	ABANDONED	TATTERED ROOF CRACKS			
313	14 Johnson Street Surulere Lagos	Surulere	2	Abandoned	ABANDONED	DAMPNESS TATTARED ROOF CRACKS			
314	Behind 15, Igboji Sabe, Jibowu, Yaba	Yaba	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks on walls, Dampness.			
315	Behind 15 Igboji Sabe, Jibowu, Yaba.	Yaba	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposure of reinforcement Visible cracks on wall Dampness			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
316	Property at No 25/27 Igbogbi Sabe, Jibowu, Yaba	Yaba	3	In use	Contravention Notice, Quit Notice, Request for Non Destructive Test (NDT), Site has been marked with red oxide	Exposures of reinforcement Dampness Visible cracks			
317	Property At No 4 Adaramaja Street, Iwaya, Yaba.	Yaba	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Site has been sealed up, Site has been marked with red oxide	Dampness Visible cracks on wall			
318	Property At No 2 Shodende/Hughes Street Off Iwaya Road, Yaba	Yaba	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	No evidence of stage No evidence of authorization from LASBCA			
319	Property At No 2 Shodende/Hughes Street Off Iwaya Road, Yaba	Yaba	Bungalow	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	No evidence of stage No evidence of authorization from LASBCA			
320	Property At No 87B Olonode Street, Alagomeji, Yaba.	Yaba	2	In use	Contravention Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide, Stop work	Cracks on wall Sagging beam of slab Water leakage on wall and slab			
321	Property Behind No 15 Igbogbi Sabe jibowu, Yaba	Yaba	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposure of reinforcement Dampness Visible cracks on wall			
322	Property At No 11 Amen Street Abule Oja, Yaba.	Yaba	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposure of reinforcement Dampness Visible cracks on walls			

List of Distressed structures identified

SN	Address/Location	District	Number of Floors	Current Status	Statutory Notices Served/Action Taken	Defects Detected on the structure(Please list them)	Building Image 1	Building Image 2	Building Image 3
323	Property At No 20 Church Street Makoko, Yaba.	Yaba	3	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Visible cracks on wall Dampness Exposure of reinforcement Dilapidated roof			
324	Property Along Obadina Street Abule Oja, Yaba.	Yaba	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Demolition Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Exposure of reinforcement Visible cracks on wall Dampness			
325	Property at No 1 Ebub Street, Abule Oja, Yaba	Yaba	2	In use	Contravention Notice, Quit Notice, Seal up Notice, Request for Non Destructive Test (NDT), Site has been sealed up, Site has been marked with red oxide	Dampness Visible cracks on wall			