








DISTRESS BUILDING PICTURE

S/N	LOCATION	TYPE OF D EVT.	DATE OF ENFORCEMENT	DETAIL OF CONTRAVENTION	PIC. CONTR BEFORE ENFORCEMENT	PIC, AFTER ENFORCEMENT	REMRK
1	PROPERTY ALONG SIJUOLA STREET, OFF AGO OKOTA. OSOLO	RESIDENTIAL	16-10-2025	DISTRESS BUILDING			TOKED AND SEALED WITH STICKER AND CATION TAPE
2	PROPERTY AT NO 9, AKIJOBI STR, AGEGE	RESIDENTIAL	25-2-2026	DISTRESS BUILDING			TOTAL DEMOLITION
3	PROPERTY AT NO 12 OGUNJIMI STR, AGEGE	RESIDENTIAL	25-2-2026	DISTRESS BUILDING			TOTAL DEMOLITION
4	PROPERTY AT NO 2 GARUBA STREET, AJEGUNLE LAGOS	RESIDENTIAL	2-4-2026	DISTRESS BUILDING			TOTAL DEMOLITION


5	PROPERTY AT NO 36 SANUSI STREET IJESHA	RESIDENTIAL	2-4-2026	DISTRESS BUILDING	 A photograph of a multi-story building in a state of severe disrepair, with significant structural damage and debris scattered around the base. The building is located at 36 Sanusi street Ijesha.	 A photograph showing the demolition site of the building at 36 Sanusi street Ijesha, with a large pile of rubble and debris in the foreground.	TOTAL DEMOLITION
6	PROPERTY AT NO 21 EZEAGU LANE AJEGUNLE LAGOS	RESIDENTIAL	2-4-2026	DISTRESS BUILDING	 A photograph of a building at 21 Ezeagu lane Ajegunle Lagos, showing significant structural damage and debris. The building is in a state of distress.	 A photograph showing the demolition site of the building at 21 Ezeagu lane Ajegunle, with a large pile of rubble and debris in the foreground.	TOTAL DEMOLITION
7	PROPERTY AT NO 44 OSHO STREET AJEROMI	RESIDENTIAL	2-4-2026	DISTRESS BUILDING	 A photograph of a building at 44 Osho street Ajeromi, showing significant structural damage and debris. The building is in a state of distress.	 A photograph showing the demolition site of the building at 44 Osho drive Ajegunle Lagos, with a large pile of rubble and debris in the foreground.	TOTAL DEMOLITION
8	PROPERTY AT NO 4 AND 6 OWODUNNI STREET AMUWO	RESIDENTIAL	2-4-2026	DISTRESS BUILDING	 A photograph of a building at 4 and 6 Owodunni street Amukoko Lagos, showing significant structural damage and debris. The building is in a state of distress.	 A photograph showing the demolition site of the building at 4 and 6 Owodunni street Amukoko Lagos, with a large pile of rubble and debris in the foreground.	TOTAL DEMOLITION


9	PROPERTY AT NO 16 AKOREDE STREET IJORA BADIA	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
10	PROPERTY AT NO 31/40, LAYINKA STR, AJEGUNLE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
11	PROPERTY AT NO 26B, ALHAJA HASSANA STR ORILE IGANMU LAGOS	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
12	PROPERTY AT NO 34 AKOSILE STR APAPA LAGOS	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION

13	PROPERTY AT PLOT 36 OLAGOKE ALLEN AVENUE BEHIND SATELITE TOWN, IJEGUN	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
14	PROPERTY AT 57 MEBAMU STR OKOKOMAIKO ALONG BADAGRY EXPRESSWAY, OJO	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
15	PROPERTY AT NO 13 OBALE LANE (NOW OPELOYERU STREET) IJORA BEFORE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
16	PROPERTY BESIDE ALHAJI DAVIES STR, ORILE AGUDA SURULERE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION




17	PROPERTY ALONG OSOSA STR, BARIGA	RESIDENTIAL	11-4-2026	DISTRESS BUILDING			TOTAL DEMOLITION
18	PROPERTY AT NO 59 AYILARA STR, OJUELEGBA, SURULERE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
19	PROPERTY AT NO 63, OBALE STREET APAPA LAGOS	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
20	PROPERTY 2 GODWIN WAY IRE AKARI LAGOS	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION



21	PROPERTY AT NO 31 OYINKAN ABAYOMI DRIVE IKOYI LAGOS	RESIDENTIAL		ILLEGAL STRUCTURAL			TOTAL DEMOLITION
22	PROPERTY BESIDE ALHAJI DAVIES STR, ORILE AGUDA	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
23	PROPERTY BESIDE ALHAJI DAVIES STR, ORILE AGUDA SURULERE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
24	PROPERTY AT NO 1224 KWARA LODGE, ALONG AHMADU BELLO WAY	COMM		ILLEGAL STRUCTURAL			TOTAL DEMOLITION

25	PROPERTY AT NO 40 ALABA INTERNATIONAL MARKET ROAD LAGOS	RESIDENTIAL	9-2-2026	DISTRESS BUILDING		TOTAL DEMOLITION
26	PROPERTY AT NO 1 SHONDE STREET IJESHATEDO ITIRE- IKATE LAGOS	RESIDENTIAL	30-3-20206	DISTRESS BUILDING		TOTAL DEMOLITION
27	PROPERTY AT NO 72 OLD YABA ROAD SABO YABA	RESIDENTIAL		DISTRESS BUILDING		TOTAL DEMOLITION
28	PROPERTY AT NO 8 MOSHALASHI STREET ALABA ORO AMUKOKO	RESIDENTIAL		DISTRESS BUILDING		TOTAL DEMOLITION


29	PROPERTY AT NO 39 GAFARU STREET, OFF IJEGUN IKOTUN RD, IKOTUN	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
30	PROPERTY AT NO 13 OYABIYI STREET YABA LAGOS	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
31	PROPERTY AT NO 10 KEKERE – EKUN STR ORILE IGANMU SURULERE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
32	PROPERTY AT NO 13 KEKERE – EKUN STR ORILE IGANMU SURULERE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION

33	PROPERTY AT NO 44 OSHO DRIVE, AJEGUNLE OLODI APAPA	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
34	PROPERTY AT NO 8, CHURCH STREET LAGOS ISLAND	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
35	PROPERTY AT NO 47 OWOSENI STREET, ITIRE IKATE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
36	PROPERTY AT NO 2 OYABIYI STREET, BEHIND MAJESTIC HOTEL	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION

37	PROPERTY AT NO 14 AROWONSERE STRE ITIRE IKATE	RESIDENTIAL		DISTRESS BUILDING	 14 Arowosere STREET ITIRE IKATE	 14 Arowosere street itire ikate	TOTAL DEMOLITION
38	PROPERTY AT NO 13 TOWN HALL STR APAPA	RESIDENTIAL		DISTRESS BUILDING	 13 town hall Street APAPA LAGOS	 13 town hall Street APAPA	TOTAL DEMOLITION
39	PROPERTY AT NO 48 TOWN HALL STR APAPA	RESIDENTIAL		DISTRESS BUILDING	 48 town hall Street APAPA LAGOS	 48 town hall Street APAPA LAGOS	TOTAL DEMOLITION
40	PROPERTY AT NO 787A SHOMIDE ODUJINRIN AVENUE BERGER	RESIDENTIAL		DISTRESS BUILDING	 787A shomide odujinrin Avenue Berger	 787A shomide odujinrin Avenue Berger	TOTAL DEMOLITION

41	PROPERTY AT NO 113 IGBOSERE ROAD LAGOS ISLAND	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
42	PROPERTY AT NO 2C TEMIDIRE STR, ITIRE IKATE	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
43	PROPERTY AT NO 6, GOLOBA STR, ISOLO	RESIDENTIAL		DISTRESS BUILDING			TOTAL DEMOLITION
44	PROPERTY AT NO 4 DELO DOSUMU STREET, IKEJA	RESIDENTIAL		DISTRESSED BUILDING			TOTAL DEMOLITION

45	PROPERTY AT NO 11 OLUSOJI STR OFF ORIMOLADE IFAKO IJAIYE	RESIDENTIAL		DISTRESSED BUILDING			TOTAL DEMOLITION
46	COLLAPSED AT NO 44 BALOGUN STREET, LAGOS ISLAND	SHOPS	26-6-2026	COLLAPSED			TOTAL DEMOLITION
47	PROPERTY AT NO 59, GBEMISHOLA ADENUBI STREET AGO PALACE	RESIDENTIAL		DISTRESSED BUILDING			TOTAL DEMOLITION
48	PROPERTY AT NO 9 ROSANWO STR COKER AGUDA SURULERE	RESIDENTIAL	3/7/2026	PARTIAL DISTRESSED			

49	PROPERTY AT NO 54 HARBERT MACAULAY STR, OYINGBO EBUTE METTA	RESIDENTIAL	2-8-2026	DISTRESSED BUILDING			TOTAL DEMOLITION
50	PROPERTY AT NO 6 KARIMU STR OFF BAALE STREET, AGBOJU, ORIADE	RESIDENTIAL	2-8-2026	DISTRESSED BUILDING			TOTAL DEMOLITION

**LAGOS STATE BUILDING CONTROL AGENCY
ENFORCEMENT DEPARTMENT**

COMPENDIUM OF DISTRESS BUILDING BEFORE AND AFTER IN LAGOS STATE GOVERNMENT SCHOOLS

S/N	LOCATION	TYPE OF D EVT.	DATE OF ENFORCEMENT	DETAIL OF CONTRAVENTION	PIC. CONTR BEFORE ENFORCEMENT	PIC, AFTER ENFORCEMENT
1	LAGOS STATE MODEL COLLEGE AGBOWA- IKOSI (BUNGALOW BUILDING AND TOILET FACILITY)	SCHOOL	26-03-2026	DISTRESS BUILDING		
2	COMMUNITY GRAMMER SCHOOL AGBOWA	SCHOOL	26-03-2026	DISTRESS BUILDING		
3	FESTAC JUNIOR GRAMMAR SCHOOL	SCHOOL	11-3-2026	DISTRESS BUILDING		

4	AWORI JUNIOR COLLEGE, OJO	SCHOOL	17-3-2026	DISTRESS BUILDING		
5	MAINLAND HIGH SCHOOL (BLK A) FADEYI	SCHOOL	18-3-2026	DISTRESS BUILDING		
6	ELETU SENIOR HIGH SCHOOL, ABULE OJA AKOKA YABA LAGOS	SCHOOL	20-3-2026	DISTRESS BUILDING		
7	MAINLAND SENIOR HIGH SCHOOL FADEYI	SCHOOL	25-3-2026	DISTRESS BUILDING		

LAGOS STATE BUILDING CONTROL AGENCY

ENFORCEMENT DEPARTMENT

IKORODU IMOTA

S/N	LOCATION	TYPE OF D EVT.	DATE OF ENFORCEMENT	DETAIL OF CONTRAVENTION	PIC. CONTR BEFORE ENFORCEMENT	PIC, AFTER ENFORCEMENT
1	PROPERTY ALONG HTCL GREEN GATE ISIU IKORODU	RESIDENTIAL	25-06-2026	PETITION/ILLEGAL STRUCTURE		
						

LAGOS STATE BUILDING CONTROL AGENCY

ENFORCEMENT DEPARTMENT

COMPENDIUM OF DISTRESS BUILDING BEFORE AND AFTER IN LAGOS STATE GOVERNMENT SCHOOLS

S/N	LOCATION	TYPE OF D EVT.	DATE OF ENFORCEMENT	DETAIL OF CONTRAVENTION	PIC. CONTR BEFORE ENFORCEMENT	PIC, AFTER ENFORCEMENT
1	AKESAN HIGH SCHOOL IGANDO- IKOTUN	SCHOOL	13-07-2026	DISTRESS BUILDING		
2	TOMIA COMMUNITY JUNIOR SECONDARY SCHOOL ALAGBADO	SCHOOL	13-07-2026	DISTRESS BUILDING		
3	AJE COMPREHENSIVE SENIOR HIGH SCHOOL SABO YABA	SCHOOL	11-7-2026	DISTRESS BUILDING		

4	AWODI ORA JUNIOR SECONDARY SCHOOL CARDODO AJEGUNLE	SCHOOL	4-7-2026	DISTRESS BUILDING		
5	AWODI ORA SENIOR SECONDARY SCHOOL CARDODO AJEGUNLE	SCHOOL	4-7-2026	DISTRESS BUILDING		
6	ISOLO SENIOR SECONDARY SCHOOL OKOTA	SCHOOL	9-7-2026	DISTRESS BUILDING	 	 

7	LAGOS STATE EXAMINATIONS BOARD, AGEGE	SCHOOL	11-7-2026	DISTRESS BUILDING		
8	STATE SENIOR GRAMMER SCHOOL ERIC MOORE SURULERE	SCHOOL	11-7-2026	DISTRESS BUILDING		